QUALIFICATIONS VALIDATED
EVERY 3 YEARS

QPL-6106-59
15-Nov-01
SUPERSEDING
QPL-6106-58
18-Sep-01

QUALIFIED PRODUCTS LIST
OF
PRODUCTS QUALIFIED UNDER PERFORMANCE SPECIFICATION
MIL-PRF-6106
RELAYS, ELECTROMAGNETIC,
GENERAL SPECIFICATION FOR

This list has been prepared for use by or for the Government in the acquisition of products covered by Specification MIL-PRF-6106. Listing of a product is not intended to and does not connote endorsement of the product by the Department of Defense. All products listed herein have been qualified under the requirements for the product as specified in the latest effective issue of the applicable specification. This list is subject to change without notice; revision or amendment of this list will be issued as necessary. The listing of a product does not release the supplier from compliance with the specification requirements.

The activity responsible for this QPL is the Defense Supply Center Columbus (DSCC-VQ), Columbus, OH 43216-5000.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| *** AN3303 Inactive for New Design After 17 Nov 54 (No Superseding Standard)** | | | |
| AN3303-1 | 814C2 | 6106-98-0192 | Leach International North America |
| *** AN3303 Inactive for New Design After 17 Nov 54 (No Superseding Standard)** | | | |
| AN3303-2 | 5724-0015HPM | 6106-98-0186 | CII Technologies (Fairview, NC) |
| AN3303-2 | 64-703 | 6106-98-0192 | Leach International North America |
| *** AN3304 Inactive for New Design After 19 May 59 (Use MS25267)** | | | |
| AN3304-2 | 64-704 | 6106-98-0193 | Leach International North America |
| *** AN3306 Inactive for New Design After 17 Nov 54 (no Superseding Standard)** | | | |
| AN3306-2 | 637-3444 | 6106-98-0194 | Leach International North America |
| *** AN3307 Inactive for New Design After 24 Feb 60 (No Superseding Standard)** | | | |
| AN3307-2 | 637-3583 | 6106-98-0195 | Leach International North America |
| *** AN3308 Inactive for New Design After 17 Nov 54 (No Superseding Standard)** | | | |
| AN3308-2 | 5715-0018HPM | 6106-98-0187 | CII Technologies (Fairview, NC) |
| AN3308-2 | 9031-3431 | 6106-98-0196 | Leach International North America |
| *** AN3310 Inactive for New Design After 17 Nov 54 (No Superseding Standard)** | | | |
| AN3310-2 | 9039-3419 | 6106-98-0197 | Leach International North America |
| *** AN3311 Inactive for New Design After 30 Nov 59 (Use MS24149)** | | | |
| AN3311-2 | 9057-3619 | 6106-98-0198 | Leach International North America |
| *** AN3312 Inactive for New Design After 14 Mar 55 (Use MS24568)** | | | |
| AN3312-2 | 9048-3466 | 6106-98-0199 | Leach International North America |
| *** AN3320 Inactive For New Design After 15 Jun 55 (No Superseding Standard)** | | | |
| AN3320-1 | 5002-B | 6106-98-0188 | CII Technologies (Fairview, NC) |
| *** AN3324 Inactive for New Design After 22 Jun 55 (No Superseding Standard)** | | | |
| AN3324-1 | 5004-B | 6106-98-0189 | CII Technologies (Fairview, NC) |
| *** AN3362 Inactive for New Design After 30 Aug 57 (No Supeseding Standard)** | | | |
| AN3362 | 6041H209 | 6106-98-0054 | Eaton Corporation of Florida |
| *** AN3372 Inactive for New Design After 25 Nov 57 (No Superseding Standard)** | | | |
| AN3372-1 | 6041H204 | 6106-98-0055 | Eaton Corporation of Florida |
| *** AN3381 Canceled 30 Jun 94 (Use MS24179)** | | | |
| AN3381 | N/A | | |
| M6106/9-001 | SM15CWD1 | 6106-95-0241 | Eaton Corporation of Florida |


**DISTRIBUTION STATEMENT A.** Approved for public release; distribution is unlimited.

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| M6106/9-002 | SM15CXD1 | 6106-95-0241 | Eaton Corporation of Florida |
| M6106/9-003 | SM15CWA4 | 6106-97-0024 | Eaton Corporation of Florida |
| M6106/9-004 | SM15CXA10 | 6106-97-0024 | Eaton Corporation of Florida |
| M6106/10-001 | SM15AWD1 | 6106-95-0242 | Eaton Corporation of Florida |
| M6106/10-002 | SM15AXD1 | 6106-95-0242 | Eaton Corporation of Florida |
| M6106/10-005 | SM15AWD3 | 6106-95-0242 | Eaton Corporation of Florida |
| M6106/11-001 | SM15BWD1 | 6106-95-0243 | Eaton Corporation of Florida |
| M6106/11-002 | SM15BXD1 | 6106-95-0243 | Eaton Corporation of Florida |
| M6106/12-001 | KDL-D2A-002 | 6106-98-0190 | Leach International North America |
| M6106/12-002 | KDL-D4A-002 | 6106-98-0190 | Leach International North America |
| M6106/13-001 | KD-D2A-002 | 6106-98-0132 | Leach International North America |
| M6106/13-002 | KD-D4A-002 | KDA-D2F-002 | Leach International North America |
| M6106/13-003 | KDA-D2F-002 | 6106-98-0132 | Leach International North America |
| M6106/13-004 | KD-E4F-002 | 6106-98-0132 | Leach International North America |
| M6106/13-005 | KD-D1A-102 | 6106-98-0132 | Leach International North America |
| M6106/13-006 | KD-J1A-102 | 6106-98-0132 | Leach International North America |
| M6106/13-007 | KD-D2N-103 | 6106-98-0132 | Leach International North America |
| M6106/13-008 | KD-D4N-103 | 6106-98-0132 | Leach International North America |
| M6106/13-009 | KD-J2A-002 | 6106-98-0132 | Leach International North America |
| M6106/13-010 | KD-A1A-002 | 6106-98-0132 | Leach International North America |
| M6106/13-011 | KD-A4A-002 | 6106-98-0132 | Leach International North America |
| M6106/13-012 | KDA-A1F-002 | 6106-98-0132 | Leach International North America |
| M6106/13-013 | KDA-A4F-002 | 6106-98-0132 | Leach International North America |
| M6106/13-014 | KD-A1N-103 | 6106-98-0132 | Leach International North America |
| M6106/13-015 | KD-A4N-103 | 6106-98-0132 | Leach International North America |
| M6106/13-016 | KD-D1N-103 | 6106-98-0132 | Leach International North America |
| M6106/13-017 | KD-D1N-104 | 6106-98-0132 | Leach International North America |
| M6106/13-018 | KD-J2N-103 | 6106-98-0132 | Leach International North America |
| M6106/15-001 | D50-1005 | 6106-96-0016(1) | Deutsch Relays, Inc. |
| M6106/15-002 | DS50-1006 | 6106-96-0017(2) | Deutsch Relays, Inc. |
| M6106/15-004 | SDH110B | 6106-030-01 | CII Technologies (Mansfield, OH) |
| M6106/19-003 | BR250-320B2-28V-003 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-003 | JS-D2A-002 | 6106-97-0127 | Leach International North America |
| M6106/19-004 | BR250-320A2-28V-004 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-004 | JS-D4A-002 | 6106-97-0127 | Leach International North America |
| M6106/19-005 | FCA-125-5 | 6106-98-0222 | MSD, Inc. |
| M6106/19-005 | BR250-320C2-28V-005 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-005 | JC-D1A-102 | 6106-97-0127 | Leach International North America |
| M6106/19-005 | E1250402CTER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-006 | FCA-125-6 | 6106-98-0222 | MSD, Inc. |
| M6106/19-006 | BR250-320B2-28V-006 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-006 | JC-D2A-102 | 6106-97-0127 | Leach International North America |
| M6106/19-006 | E1250402ATER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-007 | FCA-125-7 | 6106-98-0222 | MSD, Inc. |
| M6106/19-007 | BR250-320A2-28V-007 | 6106-97-0205 | Babcock, Inc. |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| M6106/19-007 | JC-D4A-102 | 6106-97-0127 | Leach International North America |
| M6106/19-007 | E1250402BGER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-008 | FCA-125-8 | 6106-98-0222 | MSD, Inc. |
| M6106/19-008 | BR250-320C3-28V-008 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-008 | JC-J1A-102 | 6106-97-0127 | Leach International North America |
| M6106/19-008 | E1250403CTER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-009 | FCA-125-9 | 6106-98-0222 | MSD, Inc. |
| M6106/19-009 | BR250-320C3-28V-009 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-009 | JC-J2A-102 | 6106-97-0127 | Leach International North America |
| M6106/19-009 | E1250403ATER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-010 | FCA-125-10 | 6106-98-0222 | MSD, Inc. |
| M6106/19-010 | BR250-320C2-28V-010 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-010 | JC-D1A-003 | 6106-97-0127 | Leach International North America |
| M6106/19-010 | E1250402CT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-011 | FCA-125-11 | 6106-98-0222 | MSD, Inc. |
| M6106/19-011 | BR250-320B2-28V-011 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-011 | JC-D2A-003 | 6106-97-0127 | Leach International North America |
| M6106/19-011 | E1250402AT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-012 | FCA-125-12 | 6106-98-0222 | MSD, Inc. |
| M6106/19-012 | BR250-320A2-28V-012 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-012 | JC-D4A-003 | 6106-97-0127 | Leach International North America |
| M6106/19-012 | E1250402BG | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-013 | FCA-125-13 | 6106-98-0222 | MSD, Inc. |
| M6106/19-013 | BR250-320C3-28V-013 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-013 | JC-J1A-003 | 6106-97-0127 | Leach International North America |
| M6106/19-013 | E1250402CT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-014 | FCA-125-14 | 6106-98-0222 | MSD, Inc. |
| M6106/19-014 | BR250-320B3-28V-014 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-014 | JC-J2A-003 | 6106-97-0127 | Leach International North America |
| M6106/19-014 | E1250402AT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-015 | FCA-125-15 | 6106-98-0222 | MSD, Inc. |
| M6106/19-015 | BR250-320C2-28V-015 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-015 | JC-D1N-103 | 6106-97-0127 | Leach International North America |
| M6106/19-015 | E1250402CT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-016 | FCA-125-16 | 6106-98-0222 | MSD, Inc. |
| M6106/19-016 | BR250D-320B2-28V-016 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-016 | JC-D2N-103 | 6106-97-0127 | Leach International North America |
| M6106/19-016 | E1250402AT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-017 | FCA-125-17 | 6106-98-0222 | MSD, Inc. |
| M6106/19-017 | BR250D-320A2-28V-017 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-017 | JC-D4N-103 | 6106-97-0127 | Leach International North America |
| M6106/19-017 | E1250402BG | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-018 | FCA-125-18 | 6106-98-0222 | MSD, Inc. |
| M6106/19-018 | BR250D-320C3-28V-018 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-018 | JC-J1N-103 | 6106-97-0127 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| M6106/19-018 | E1250402CT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-019 | FCA-125-19 | 6106-98-0222 | MSD, Inc. |
| M6106/19-019 | BR250D-320B3-28V-019 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-019 | JC-J2N-103 | 6106-97-0127 | Leach International North America |
| M6106/19-019 | E1250402AT | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-020 | FCA-125-20 | 6106-98-0222 | MSD, Inc. |
| M6106/19-020 | BR250D-320C2-28V-020 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-020 | JC-D1N-104 | 6106-97-0127 | Leach International North America |
| M6106/19-020 | E1250402CTER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-021 | FCA-125-21 | 6106-98-0222 | MSD, Inc. |
| M6106/19-021 | BR250D-320B2-28V-021 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-021 | JC-D2N-104 | 6106-97-0127 | Leach International North America |
| M6106/19-021 | E1250402ATER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-022 | FCA-125-22 | 6106-98-0222 | MSD, Inc. |
| M6106/19-022 | BR250D-320A2-28V-022 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-022 | JC-D4N-104 | 6106-97-0127 | Leach International North America |
| M6106/19-022 | E1250402BGER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-023 | FCA-125-23 | 6106-98-0222 | MSD, Inc. |
| M6106/19-023 | BR250D-320C3-28V-023 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-023 | JC-J1N-104 | 6106-97-0127 | Leach International North America |
| M6106/19-023 | E1250402CTER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-024 | FCA-125-24 | 6106-98-0222 | MSD, Inc. |
| M6106/19-024 | BR250D-320B3-28V-024 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-024 | JC-J2N-104 | 6106-97-0127 | Leach International North America |
| M6106/19-024 | E1250402ATER | 6106-98-0221 | Deutsch Relays, Inc. (France) |
| M6106/19-025 | BR250-320B3-28V-025 | 6106-97-0205 | Babcock, Inc. |
| M6106/19-025 | JC-J2A-102 | 6106-97-0127 | Leach International North America |
| M6106/20-001 | BR251-600B2-28V-001 | 6106-97-0206 | Babcock, Inc. |
| M6106/20-001 | JCL-D2A-002 | 6106-97-0191 | Leach International North America |
| M6106/20-002 | BR251-600A2-28V-002 | 6106-97-0206 | Babcock, Inc. |
| M6106/20-002 | JCL-D4A-002 | 6106-97-0191 | Leach International North America |
| M6106/20-003 | BR251-600B3-28V-003 | 6106-97-0206 | Babcock, Inc. |
| M6106/20-003 | JCL-J2A-002 | 6106-97-0191 | Leach International North America |
| M6106/26-001 | H-A9A-042 | 6106-96-0119 | Leach International North America |
| M6106/26-001 | M6106/26-001 | 6106-047-00 | CII Technologies (Mansfield, OH) |
| M6106/31-001 | CNA040301 | 6106-98-0108 | Precision Connenctor Designs |
| M6106/32-001 | CNA081501 | 6106-98-0109 | Precision Connenctor Designs |
| M6106/33-040 | AJ-A4A-153 | 6106-96-0123 | Leach International North America |
| M6106/33-041 | AJ-A4NA-154 | 6106-96-0123 | Leach International North America |
| M6106/33-042 | AJ-A4NA-155 | 6106/96-0123 | Leach International North America |
| M6106/33-043 | AJ-A4A-156 | 6106-96-0123 | Leach International North America |
| M6106/33-044 | AJ-B8NA-157 | 9106-96-0123 | Leach International North America |
| M6106/33-045 | AJ-B8A-158 | 6106-96-0123 | Leach International North America |
| M6106/33-046 | AJ-A2NA-159 | 6106-96-0123 | Leach International North America |
| M6106/33-047 | AJ-A3NA-160 | 6106-96-0123 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| M6106/33-048 | AJ-A2A-161 | 6106-96-0123 | Leach International North America |
| M6106/33-049 | AJ-A3A-162 | 6106-96-0123 | Leach International North America |
| M6106/33-050 | AJ-A8NA-163 | 6106-96-0123 | Leach International North America |
| M6106/33-051 | AJ-A8A-164 | 6106-96-0123 | Leach International North America |
| M6106/33-052 | AJ-B9NA-165 | 6106-96-0123 | Leach International North America |
| M6106/33-053 | AJ-B9A-166 | 6106-96-0123 | Leach International North America |
| M6106/33-054 | AJ-A9NA-167 | 6106-96-0123 | Leach International North America |
| M6106/33-055 | AJ-A9A-168 | 6106-96-0123 | Leach International North America |
| M6106/33-056 | AJ-B7NA-169 | 6106-96-0123 | Leach International North America |
| M6106/33-057 | AJ-B7A-170 | 6106-96-0123 | Leach International North America |
| M6106/33-058 | AJ-A7NA-171 | 6106-96-0123 | Leach International North America |
| M6106/33-059 | AJ-A7A-172 | 6106-96-0123 | Leach International North America |
| M6106/33-060 | AJ-B8N-173 | 6106-96-0123 | Leach International North America |
| M6106/33-061 | AJ-B9N-174 | 6106-96-0123 | Leach International North America |
| M6106/33-062 | AJ-B7N-175 | 6106-96-0123 | Leach International North America |
| M6106/33-063 | AJ-A4N-176 | 6106-96-0123 | Leach International North America |
| M6106/33-064 | AJ-A4N-177 | 6106-96-0123 | Leach International North America |
| M6106/33-065 | AJ-B4A-178 | 6106-96-0123 | Leach International North America |
| M6106/33-066 | AJ-B4NA-179 | 6106-96-0123 | Leach International North America |
| M6106/33-067 | AJ-B4N-180 | 6106-96-0123 | Leach International North America |
| M6106/33-068 | AJ-A8N-181 | 6106-96-0123 | Leach International North America |
| M6106/33-069 | AJ-A2N-182 | 6106-96-0123 | Leach International North America |
| M6106/33-070 | AJ-B2A-183 | 6106-96-0123 | Leach International North America |
| M6106/33-071 | AJ-B2NA-184 | 6106-96-0123 | Leach International North America |
| M6106/33-072 | AJ-B2N-185 | 6106-96-0123 | Leach International North America |
| M6106/33-073 | AJ-A3N-186 | 6106-96-0123 | Leach International North America |
| M6106/33-074 | AJ-B3A-187 | 6106-96-0123 | Leach International North America |
| M6106/33-075 | AJ-B3NA-188 | 6106-96-0123 | Leach International North America |
| M6106/33-076 | AJ-B3N-189 | 6106-96-0123 | Leach International North America |
| M6106/33-077 | AJ-A9N-190 | 6106-96-0123 | Leach International North America |
| M6106/33-078 | AJ-A7N-191 | 6106-96-0123 | Leach International North America |
| M6106/35-001 | 2215-2 | 6106-98-0183 | Deutsch Relays, Inc. |
| M6106/38-001 | XL-D2A-003 | 6106-96-0116 | Leach International North America |
| M6106/38-002 | XL-D4A-003 | 6106-96-0116 | Leach International North America |
| M6106/38-003 | XL-D1A-003 | 6106-96-0116 | Leach International North America |
| M6106/38-004 | XL-J2A-003 | 6106-96-0116 | Leach International North America |
| M6106/38-005 | XL-A1A-003 | 6106-96-0116 | Leach International North America |
| M6106/38-006 | XL-J1A-003 | 6106-96-0116 | Leach International North America |
| M6106/39-001 | YL-D2A-003 | 6106-96-0102 | Leach International North America |
| M6106/39-002 | YL-D4A-003 | 6106-96-0102 | Leach International North America |
| M6106/39-003 | YL-D1A-003 | 6106-96-0102 | Leach International North America |
| M6106/39-004 | YL-J2A-003 | 6106-96-0102 | Leach International North America |
| M6106/39-005 | YL-A1A-003 | 6106-96-0102 | Leach International North America |
| M6106/39-006 | YL-J1A-003 | 6106-96-0102 | Leach International North America |
| M6106/40-001 | YCL-D2A-003 | 6106-97-0199 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| M6106/40-002 | YCL-D4A-003 | 6106-97-0199 | Leach International North America |
| M6106/40-003 | YCL-D1A-003 | 6106-97-0199 | Leach International North America |
| M6106/40-004 | YCL-J2A-003 | 6106-97-0199 | Leach International North America |
| M6106/40-005 | YCL-A1A-003 | 6106-97-0199 | Leach International North America |
| M6106/40-006 | YCL-J1A-003 | 6106-97-0199 | Leach International North America |
| M6106/41-001 | 9339-10223 | 6106-96-0007 | Leach International North America |
| M6106/41-002 | H-A9A-060 | 6106-96-0120 | Leach International North America |
| M6106/41-002 | 9339-10224 | 6106-96-0007 | Leach International North America |
| M6106/43-001 | H-A9A-063 | 6106-96-0120 | Leach International North America |
| M6106/48-001 | SM100H1 | 6106-98-0208 | Eaton Corporation of Florida |
| M6106/48-002 | SM100H15 | 6106-022-01 | Eaton Corporation of Florida |
| MS24140-D1 | 6042H155 | 6106-97-0043 | Eaton Corporation of Florida |
| MS24140-D2 | 6042H156 | 6106-97-0043 | Eaton Corporation of Florida |
| MS24141-D2 | 6042H159 | 6106-97-0044 | Eaton Corporation of Florida |
| MS24141-D2 | 6042H160 | 6106-97-0044 | Eaton Corporation of Florida |
| MS24142-D1 | 6042H151 | 6106-96-0175 | Eaton Corporation of Florida |
| MS24142-D2 | 6042H152 | 6106-96-0175 | Eaton Corporation of Florida |
| MS24143-A3 | 6042H290 | 6106-97-0046 | Eaton Corporation of Florida |
| MS24143-A4 | 6042H291 | 6106-97-0046 | Eaton Corporation of Florida |
| MS24143-D1 | 6042H141 | 6106-97-0046 | Eaton Corporation of Florida |
| MS24143-D2 | 6042H142 | 6106-97-0046 | Eaton Corporation of Florida |
| MS24143-D3 | 6042H110 | 6106-97-0046 | Eaton Corporation of Florida |
| *** MS24149-A1 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS24149-A1 | 9330-4027 | 6106-97-0064 | Leach International North America |
| MS24149-D1 | 9330-4026 | 6106-97-0064 | Leach International North America |
| *** MS24152-D1 Inactive For New Design After 27 May 1994 (No Superseding Standard)** | | | |
| MS24152-D1 | 9565H29 | 6106-98-0049 | Eaton Corporation of Florida |
| MS24166-D1 | 7064-4653 | 6106-034-00 | Leach International North America |
| MS24166-D1 | 6041H200 | 6106-98-0017 | Eaton Corporation of Florida |
| MS24166-D1 | 7064-4653 | 6106-034-00 | Leach International Europe |
| MS24166-D2 | 7064-4653 | 6106-034-00 | Leach International North America |
| MS24166-D2 | 6041H201 | 6106-98-0017 | Eaton Corporation of Florida |
| MS24166-D2 | 7064-238 | 6106-034-00 | Leach International Europe |
| MS24168-A3 | 6042H289 | 6106-96-0244 | Eaton Corporation of Florida |
| MS24168-A4 | 6042H286 | 6106-96-0244 | Eaton Corporation of Florida |
| MS24168-D1 | 6042H161 | 6106-96-0244 | Eaton Corporation of Florida |
| MS24168-D2 | 6042H162 | 6106-96-0244 | Eaton Corporation of Florida |
| MS24171-D1 | 6041H215 | 6106-98-0018 | Eaton Corporation of Florida |
| MS24171-D1 | 7264-4654 | 6106-035-00 | Leach International Europe |
| MS24171-D2 | 6041H202 | 6106-98-0018 | Eaton Corporation of Florida |
| MS24171-D2 | 7264-283 | 6106-035-00 | Leach International Europe |
| MS24172-D1 | 6041H216 | 6106-98-0019 | Eaton Corporation of Florida |
| MS24172-D1 | 7264-4655 | 6106-035-00 | Leach International Europe |
| MS24172-D2 | 6041H203 | 6106-98-0019 | Eaton Corporation of Florida |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| MS24178-D1 | 7064-4656 | 6106-033-00 | Leach International Europe |
| MS24178-D1 | 6041H219 | 6106-97-0020 | Eaton Corporation of Florida |
| MS24179-D1 | 7401-9444 | 6106-033-00 | Leach International North America |
| MS24179-D1 | 6041H218 | 6106-98-0168 | Eaton Corporation of Florida |
| MS24179-D2 | 6041H206 | 6106-98-0168 | Eaton Corporation of Florida |
| MS24182-D1 | 6042H166 | 6106-96-0176 | Eaton Corporation of Florida |
| MS24183-D1 | 6042H167 | 6106-96-0243 | Eaton Corporation of Florida |
| MS24184-D1 | 6042H153 | 6106-96-0242 | Eaton Corporation of Florida |
| MS24184-D2 | 6042H154 | 6106-96-0242 | Eaton Corporation of Florida |
| MS24185-D1 | 6041H205 | 6106-105-00 | CII Technologies (Mansfield, OH) |
| MS24185-D1 | 6041H217 | 6106-98-0044 | Eaton Corporation of Florida |
| MS24185-D1 | 7401-4658 | 6106-033-00 | Leach International Europe |
| MS24185-D2 | M24185-D2 | 6106-105-00 | CII Technologies (Mansfield, OH) |
| MS24185-D2 | 6041H205 | 6106-98-0044 | Eaton Corporation of Florida |
| MS24185-D2 | 7401-C05 | 6106-033-00 | Leach International Europe |
| MS24187-D1 | 6041H220 | 6106-98-0045 | Eaton Corporation of Florida |
| MS24187-D2 | 6041H230 | 6106-98-0045 | Eaton Corporation of Florida |
| MS24192-D1 | 9565H2 | 6106-95-0186 | Eaton Corporation of Florida |
| MS24193-D1 | 9565H94 | 6106-95-0187 | Eaton Corporation of Florida |
| MS24376-A1 | 6042-H147 | 6106-97-0098 | Eaton Corporation of Florida |
| MS24376-A2 | 6042H148 | 6106-97-0098 | Eaton Corporation of Florida |
| MS24376-A3 | 6042H288 | 6106-97-0098 | Eaton Corporation of Florida |
| MS24376-A4 | 6042H285 | 6106-97-0098 | Eaton Corporation of Florida |
| MS24376-D1 | 6042H145 | 6106-97-0098 | Eaton Corporation of Florida |
| MS24376-D1 | 6042H145 | 6106-97-0098 | Eaton Corporation of Florida |
| MS24376-D2 | 6042H146 | 6106-97-0098 | Eaton Corporation of Florida |
| *** MS24568-A1 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS24568-A1 | 9274-6667 | 6106-97-0110 | Leach International North America |
| *** MS24568-A2 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS24568-A2 | 9274-10291 | 6106-97-0110 | Leach International North America |
| MS24568-D1 | 9274-6205 | 6106-97-0110 | Leach International North America |
| *** MS25024 Inactive for New Design After 11 Dec 64 (Use MS24568-D1)** | | | |
| MS25024-2 | A410-157763-00 | 6106-97-0128 | Guardian Electric Manufacturing Company |
| *** MS25030 Inactive for New Design After 28 Apr 95 (No Superseding Standard)** | | | |
| MS25030-D1B | 6046H51 | 6106-98-0050 | Eaton Corporation of Florida |
| *** MS25031 Inactive for New Design After 29 Sep 90 (No Superseding Standard)** | | | |
| MS25031-D1B | 6046H53 | 6106-98-0051 | Eaton Corporation of Florida |
| *** MS25032 Inactive for New Design After 29 Sep 90 (No Superseding Standard)** | | | |
| MS25032-D1 | 6046H46 | 6106-98-0052 | Eaton Corporation of Florida |
| *** MS25033 Inactive for New Design After 18 Jan 57 (No Superseding Standard)** | | | |
| MS25033-1 | A419-054978-01 | 6106-97-0129 | Guardian Electric Manufacturing Company |
| *** MS25035 Inactive for New Design After 14 Nov 79 (No Superseding Standard)** | | | |
| MS25035-1 | A410-154555-00 | 6106-97-0130 | Guardian Electric Manufacturing Company |
| MS25267-A1 | 9220-4186 | 6106-96-0092 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| MS25267-D1 | 9220-4185 | 6106-96-0092 | Leach International North America |
| *** MS25268 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25268-A1 | 9220-4192 | 6106-98-0032 | Leach International North America |
| *** MS25268 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25268-D1 | 9220-4191 | 6106-98-0032 | Leach International North America |
| *** MS25269 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25269-A1 | 9226-4188 | 6106-98-0086 | Leach International North America |
| *** MS25269 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25269-D1 | 9226-4187 | 6106-98-0086 | Leach International North America |
| *** MS25270 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25270-A1 | 9226-4190 | 6106-98-0087 | Leach International North America |
| *** MS25270 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25270-D1 | 9226-4189 | 6106-98-0087 | Leach International North America |
| MS25271-A1 | 9224-4076 | 6106-96-0050 | Leach International North America |
| MS25271-D1 | 9224-4091 | 6106-96-0050 | Leach International North America |
| *** MS25272 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25272-A1 | 9224-4194 | 6106-98-0036 | Leach International North America |
| *** MS25272 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25272-D1 | 9224-4193 | 6106-98-0036 | Leach International North America |
| MS25273-A1 | 9227-4085 | 6106-96-0004 | Leach International North America |
| MS25273-A2 | 9227-10410 | 6106-96-0004 | Leach International North America |
| MS25273-D1 | 9227-4084 | 6106-96-0004 | Leach International North America |
| *** MS25321 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/27)** | | | |
| MS25321-A2 | 9229-4463 | 6106-98-0021 | Leach International North America |
| *** MS25321 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/27)** | | | |
| MS25321-A3 | 9229-8986 | 6106-98-0021 | Leach International North America |
| *** MS25321 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/27)** | | | |
| MS25321-D2 | 9229-4459 | 6106-98-0021 | Leach International North America |
| *** MS25323 Inactive for New Design After 5 Jun 87 (Use MS27401)** | | | |
| MS25323-A2 | 9227-4449 | 6106-98-0026 | Leach International North America |
| *** MS25323 Inactive for New Design After 5 Jun 87 (Use MS27401)** | | | |
| MS25323-D2 | 9227-4444 | 6106-98-0026 | Leach International North America |
| *** MS25325 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/28)** | | | |
| MS25325-A1 | 9220-4406 | 6106-98-0033 | Leach International North America |
| *** MS25325 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/28)** | | | |
| MS25325-A2 | 9220-8985 | 6106-98-0033 | Leach International North America |
| *** MS25325 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/28)** | | | |
| MS25325-D1 | 9220-4402 | 6106-98-0033 | Leach International North America |
| *** MS25327 Inactive for New Design After 5 Jun 87 (Use MS27400)** | | | |
| MS25327-A1 | 9224-4488 | 6106-98-0037 | Leach International North America |
| *** MS25327 Inactive for New Design After 5 Jun 87 (Use MS27400)** | | | |
| MS25327-D1 | 9224-4487 | 6106-98-0037 | Leach International North America |
| *** MS25329 Inactive for New Design After 30 Sep 87 (No Superseding Standard)** | | | |
| MS25329-A1 | 9226-4433 | 6106-98-0088 | Leach International North America |
| *** MS25329 Inactive for New Design After 30 Sep 87 (No Superseding Standard)** | | | |
| MS25329-D1 | 9226-4429 | 6106-98-0088 | Leach International North America |
| MS25395-A1 | 9229-4461 | 6106-96-0006 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| *** MS25395-A2 Inactive for New Design After 5 Jun 87** | | | |
| MS25395-A2 | 9229-4512 | 6106-96-0006 | Leach International North America |
| MS25395-A3 | 9229-10007 | 6106-96-0006 | Leach International North America |
| *** MS25395-A4 Inactive for New Design After 5 Jun 87** | | | |
| MS25395-A4 | 9229-10008 | 6106-96-0006 | Leach International North America |
| MS25395-D1 | 9229-4457 | 6106-96-0006 | Leach International North America |
| *** MS25395-D2 Inactive for New Design After 5 Jun 87** | | | |
| MS25395-D2 | 9229-4511 | 6106-96-0006 | Leach International North America |
| *** MS25455 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25455-A1 | 9235-4843 | 6106-98-0082 | Leach International North America |
| *** MS25455 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25455-D1 | 9235-4842 | 6106-98-0082 | Leach International North America |
| *** MS25457 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25457-A1 | 9237-4846 | 6106-98-0023 | Leach International North America |
| *** MS25457 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25457-D1 | 9237-4845 | 6106-98-0023 | Leach International North America |
| *** MS25459 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25459-A1 | 9228-4622 | 6106-98-0089 | Leach International North America |
| *** MS25459 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25459-D1 | 9228-4424 | 6106-98-0089 | Leach International North America |
| *** MS25461 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25461-A1 | 9225-4616 | 6106-98-0157 | Leach International North America |
| *** MS25461 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25461-D1 | 9225-4416 | 6106-98-0157 | Leach International North America |
| *** MS25463 Inactive for New Design After 30 Jun 87 (No Superseding Standard)** | | | |
| MS25463-A1 | 9223-4834 | 6106-97-0197 | Leach International North America |
| *** MS25463 Inactive for New Design After 30 Jun 87 (No Superseding Standard)** | | | |
| MS25463-D1 | 9223-4833 | 6106-97-0197 | Leach International North America |
| *** MS25465 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25465-A1 | 9235-4718 | 6106-98-0083 | Leach International North America |
| *** MS25465 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25465-D1 | 9235-4717 | 6106-98-0083 | Leach International North America |
| *** MS25466 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25466-A1 | 9237-5125 | 6106-98-0024 | Leach International North America |
| *** MS25466 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS25466-D1 | 9237-5124 | 6106-98-0024 | Leach International North America |
| MS25467-A1 | 9228-4531 | 6106-98-0090 | Leach International North America |
| MS25467-D1 | 9228-4530 | 6106-98-0090 | Leach International North America |
| MS25468-A1 | 9225-4494 | 6106-96-0137 | Leach International North America |
| *** MS25468-AD1 Inactive for New Design After 29 Sep 87 (No Superseding Standard)** | | | |
| MS25468-AD1 | 9225-8756 | 6106-96-0137 | Leach International North America |
| MS25468-D1 | 9225-4241 | 6106-96-0137 | Leach International North America |
| *** MS25469-A1 Inactive for New Design After 30 Sep 87 (No Superseding Standard)** | | | |
| MS25469-A1 | 9223-5129 | 6106-97-0198 | Leach International North America |
| MS25469-D1 | 9223-4692 | 6106-97-0198 | Leach International North America |
| *** MS25917 Inactive for New Design After 2 Mar 87 (No Superseding Standard)** | | | |
| MS25917-1 | 9220-3474 | 6106-98-0034 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| *** MS25917 Inactive for New Design After 2 Mar 87 (No Superseding Standard)** | | | |
| MS25917-2 | 9220-3475 | 6106-98-0034 | Leach International North America |
| *** MS25918 Inactive for New Design After 14 Aug 81 (No Superseding Standard)** | | | |
| MS25918-D1 | 9226-3478 | 6106-98-0091 | Leach International North America |
| *** MS25918 Inactive for New Design After 14 Aug 81 (No Superseding Standard)** | | | |
| MS25918-D2 | 9226-3476 | 6106-98-0091 | Leach International North America |
| MS27222-1 | 9124-C7C4-002 | 6106-98-0133 | Leach International North America |
| MS27222-2 | 9124-1Z-C7C4-002 | 6106-98-0133 | Leach International North America |
| MS27222-3 | 9124-C7D3-002 | 6106-98-0133 | Leach International North America |
| MS27222-4 | 9124-1Z-C7D3-002 | 6106-98-0133 | Leach International North America |
| MS27222-5 | 9124-10278 | 6106-98-0133 | Leach International North America |
| MS27222-6 | 9124-10279 | 6106-98-0133 | Leach International North America |
| MS27222-7 | 9124-10280 | 6106-98-0133 | Leach International North America |
| MS27242-1 | 6042H181 | 6106-98-0047 | Eaton Corporation of Florida |
| MS27242-2 | 6042H182 | 6106-98-0047 | Eaton Corporation of Florida |
| MS27243-1 | 49-2661 | 6106-98-0053 | Eaton Corporation of Florida |
| MS27243-2 | 49-2665 | 6106-98-0053 | Eaton Corporation of Florida |
| MS27243-3 | 49-2667 | 6106-98-0053 | Eaton Corporation of Florida |
| MS27243-4 | 49-2670 | 6106-98-0053 | Eaton Corporation of Florida |
| MS27243-5 | 49-2672 | 6106-98-0053 | Eaton Corporation of Florida |
| MS27243-6 | 49-3179 | 6106-98-0053 | Eaton Corporation of Florida |
| *** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27245-1 | B07D112BC4-0007 | 6106-98-0184 | CII Technologies (Fairview, NC) |
| *** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27245-2 | B07D919BC4-0054 | 6106-98-0184 | CII Technologies (Fairview, NC) |
| *** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27245-3 | B07D112BC4-0203 | 6106-98-0184 | CII Technologies (Fairview, NC) |
| *** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27245-4 | B07D919BC4-0204 | 6106-98-0184 | CII Technologies (Fairview, NC) |
| *** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27245-5 | B07E932BC4-0262 | 6106-98-0184 | CII Technologies (Fairview, NC) |
| *** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27245-6 | B07D932BC4-0263 | 6106-98-0184 | CII Technologies (Fairview, NC) |
| *** MS27247 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27247-1 | B07D111BC4-0006 | 6106-98-0185 | CII Technologies (Fairview, NC) |
| *** MS27247 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27247-2 | B07D11BC4-0202 | 6106-98-0185 | CII Technologies (Fairview, NC) |
| *** MS27247 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27247-4 | B07D915BC4-0264 | 6106-98-0185 | CII Technologies (Fairview, NC) |
| *** MS27247 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27247-5 | B07E915BC4-0265 | 6106-98-0185 | CII Technologies (Fairview, NC) |
| *** MS27254 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27254-1 | A410-161171-01 | 6106-97-0131 | Guardian Electric Manufacturing Company |
| *** MS27254 Inactive for New Design After 5 Jun 87 (No Superseding Standards)** | | | |
| MS27254-2 | A410-161171-02 | 6106-97-0131 | Guardian Electric Manufacturing Company |
| *** MS27255 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27255-1 | A410-161916-00 | 6106-97-0132 | Guardian Electric Manufacturing Company |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| *** MS27255 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27255-2 | A410-161059-03 | 6106-97-0132 | Guardian Electric Manufacturing Company |
| *** MS27255 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27255-3 | A410-161916-03 | 6106-97-0132 | Guardian Electric Manufacturing Company |
| *** MS27255 Inactive for New Design After 5 Jun 87 (No Superseding Standard)** | | | |
| MS27255-4 | A410-161059-04 | 6106-97-0132 | Guardian Electric Manufacturing Company |
| MS27418-1A | 9324-8215 | 6106-96-0008 | Leach International North America |
| MS27418-1B | 9324-8214 | 6106-96-0008 | Leach International North America |
| MS27418-1C | 9324-10126 | 6106-96-0008 | Leach International North America |
| MS27418-1D | 9324-10314 | 6106-96-0008 | Leach International North America |
| MS27418-2A | 9324-8213 | 6106-96-0008 | Leach International North America |
| MS27418-2B | 9324-7424 | 6106-96-0008 | Leach International North America |
| MS27418-2C | 9324-10128 | 6106-96-0008 | Leach International North America |
| MS27418-2D | 9324-10315 | 6106-96-0008 | Leach International North America |
| *** MS27706 Inactive for New Design After 8 Sep 95 (No Superseding Standard)** | | | |
| MS27706-1B | 9325-8398 | 6106-98-0027 | Leach International North America |
| *** MS27706 Inactive for New Design After 8 Sep 95 (No Superseding Standard)** | | | |
| MS27706-2B | 9325-8390 | 6106-98-0027 | Leach International North America |
| *** MS27709 Inactive for New Design After 5 Jun 87 (For New Design Use MIL-R-83536/15 or/16)** | | | |
| MS27709-3 | BR230-S0187 | 6106-98-0200 | Babcock, Inc. |
| MS27709-3 | K-X2A-061 | 6106-98-0191 | Leach International North America |
| MS27709-3 | E410-1740 | 6106-98-0135 | Deutsch Relays, Inc. |
| *** MS27709 Inactive for New Design After 5 Jun 87 (For New Design Use MIL-R-83536/15 or/16)** | | | |
| MS27709-4 | BR230-S0188 | 6106-98-0200 | Babcock, Inc. |
| MS27709-4 | K-X2A-062 | 6106-98-0191 | Leach International North America |
| MS27709-4 | E410-1741 | 6106-98-0135 | Deutsch Relays, Inc. |
| *** MS27709 Inactive for New Design After 5 Jun 87 (For New Design Use MIL-R-83536/15 or/16)** | | | |
| MS27709-5 | BR230-S0189 | 6106-98-0200 | Babcock, Inc. |
| MS27709-5 | K-X9A-013 | 6106-98-0191 | Leach International North America |
| MS27709-5 | E410-1742 | 6106-98-0135 | Deutsch Relays, Inc. |
| *** MS27714 Inactive for New Design After 27 Mar 95 (No Superseding Standard)** | | | |
| MS27714-1 | A419-062426-00 | 6106-97-0133 | Guardian Electric Manufacturing Company |
| *** MS27714 Inactive for New Design After 27 Mar 95 (No Superseding Standard)** | | | |
| MS27714-2 | A419-062426-03 | 6106-97-0133 | Guardian Electric Manufacturing Company |
| *** MS27715 Inactive for New Design After 27 Mar 95 (No Superseding Standard)** | | | |
| MS27715-1 | A419-062470-00 | 6106-97-0134 | Guardian Electric Manufacturing Company |
| *** MS27715 Inactive for New Design After 27 Mar 95 (No Superseding Standard)** | | | |
| MS27715-2 | A419-063394-03 | 6106-97-0134 | Guardian Electric Manufacturing Company |
| MS27742-1 | BR236-450B2-28V-1 | 6106-98-0096 | Babcock, Inc. |
| MS27742-1 | KCL-S2A-002 | 6106-97-0037 | Leach International North America |
| MS27742-1 | EL3250402AT | 6106-149-00 | Deutsch Relays, Inc. (France) |
| MS27742-2 | BR236-450A2-28V-1 | 6106-98-0096 | Babcock, Inc. |
| MS27742-2 | KCL-D4A-002 | 6106-97-0037 | Leach International North America |
| MS27742-2 | EL3250402BG | 6106-149-00 | Deutsch Relays, Inc. (France) |
| MS27749-1 | HL-A1A-002 | 6106-96-0110 | Leach International North America |
| MS27749-2 | HLT-A1A-002 | 6106-96-0110 | Leach International North America |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|
| MS27750-1 | HC-A1A-002 | 6106-96-0111 | Leach International North America |
| MS27750-1 | M27750-1 | 6106-037-00 | CII Technologies (Mansfield, OH) |
| MS27750-2 | HC-A1A-017 | 6106-96-0111 | Leach International North America |
| MS27750-2 | M27750-2 | 6106-037-00 | CII Technologies (Mansfield, OH) |
| MS27751-1 | H-A1A-002 | 6106-96-0121 | Leach International North America |
| MS27751-2 | H-A1F-002 | 6106-96-0121 | Leach International North America |
| MS27751-3 | H-A2A-002 | 6106-96-0121 | Leach International North America |
| MS27751-4 | H-A2F-002 | 6106-96-0121 | Leach International North America |
| MS27751-5 | H-A3A-002 | 6106-96-0121 | Leach International North America |
| MS27751-6 | H-A3F-002 | 6106-96-0121 | Leach International North America |
| MS27751-7 | H-A4A-002 | 6106-96-0121 | Leach International North America |
| MS27751-8 | H-A4F-002 | 6106-96-0121 | Leach International North America |
| MS27751-9 | H-A5A-002 | 6106-96-0121 | Leach International North America |
| MS27751-10 | H-A5F-002 | 6106-96-0121 | Leach International North America |
| MS27751-11 | HT-A1A-002 | 6106-96-0121 | Leach International North America |
| MS27751-12 | HT-A1F-002 | 6106-96-0121 | Leach International North America |
| MS27751-13 | HT-A2A-002 | 6106-96-0121 | Leach International North America |
| MS27751-14 | HT-A2F-002 | 6106-96-0121 | Leach International North America |
| MS27751-15 | HT-A3A-002 | 6106-96-0121 | Leach International North America |
| MS27751-16 | HT-A3F-002 | 6106-96-0121 | Leach International North America |
| MS27751-17 | HT-A4A-002 | 6106-96-0121 | Leach International North America |
| MS27751-18 | HT-A4F-002 | 6106-96-0121 | Leach International North America |
| MS27751-19 | HT-A5A-002 | 6106-96-0121 | Leach International North America |
| MS27751-20 | HT-A5F-002 | 6106-96-0121 | Leach International North America |
| MS27751-21 | H-1AN-059 | 6106-96-0121 | Leach International North America |
| MS27997-A1 | 9123-C7D3-002 | 6106-98-0134 | Leach International North America |
| MS27997-A2 | 9123-1Z-C7D3-002 | 6106-98-0134 | Leach International North America |
| MS27997-D1 | 9123-C7C4-002 | 6106-98-0134 | Leach International North America |
| MS27997-D1 | 6042H91 | 6106-98-0048 | Eaton Corporation of Florida |
| MS27997-D2 | 9123-1Z-C7C4-002 | 6106-98-0134 | Leach International North America |
| MS27997-D2 | 6042H92 | 6106-98-0048 | Eaton Corporation of Florida |

**Manufacturer: Babcock, Inc. (CAGE Code: 56623)**
Location: 14930 East Alondra Blvd., La Mirada, CA 90638-5752, US

Plant Location: Same Address as Manufacturer

**Manufacturer: CII Technologies (Fairview, NC) (CAGE Code: 58614)**
Location: Communications Instruments Division, P. O. Box 520, Highway 74 East, Fairview, NC 28730, US

Plant Location: Same Address as Manufacturer

Distributor Locations:
1. Airtechnics, P.O. Box 3466, 230 Ida, Wichita, KS 67201, US
2. Airtechnics, 4250 Veterans Highway, Suite 220, Holbrook, NY 11741, US
3. Airtechnics, 5787 South Hampton, Suite 380, Dallas, TX 75232, US
4. Airtechnics, 15215 Alton Parkway, Irvine, CA 92718, US
5. Avnet, 1301 West Geneva Drive, Tempe, AZ 85282, US
6. Flame Enterprises, Inc., 20945 Osborne Street, Canoga Park, CA `91304, US
7. Gemcap, Inc., 600-D North Bicycle Path, Port Jefferson Station, NY 11776, US
8. Gemcap, Inc., 13 Virginia Avenue, Enfield, CT 06082, US
9. Master Distributors, 1026 6th Avenue, Oakland, CA 94606, US
10. Master Distributors, 1220 Olympic Boulevard, Oakland, CA 94604, US
11. Master Distributors, 1301 Olympic Boulevard, Santa Monica, CA 90404, US
12. Master Distributors, 842 South 7th Street, Louisville, KY 40203, US
13. Master Distributors, 9701 Dessau Road, Suite 204, Austin, TX 78753, US
14. Master Distributors, 12506 130th Lane, NE, Kirkland, WA 98034, US
15. Master Distributors, 2425 South 21st Street, Phoenix, AZ 85034, US
16. Monteva Aviation Group, 1134 Ste. Catherine Street, W, Suite 410, Montreal H3B 1H4, Quebec, Canada
17. Norstan Electronics, 1911 East Carnegie Avenue, Santa Ana, CA 92705, US

**Manufacturer: CII Technologies (Mansfield, OH) (CAGE Code: 74063)**
Location: Hartman Division, 175 North Diamond Street, Mansfield, OH 44902, US

Plant Location: Same Address as Manufacturer

**Manufacturer: Deutsch Relays, Inc. (CAGE Code: 99699)**
Location: 65 Daly Road, East Northport, NY 11731-6395, US

Plant Locations:
1. Same Address as Manufacturer
2. Deutsch Relays, Inc. (France), 22 Rue Des Chaises, F45140 St. Jean De La Rule, France

**Manufacturer: Eaton Corporation of Florida (CAGE Code: 81640)**
Location: Aerospace Controls Division, 2250 Whitfield Ave., Sarasota, FL 34243-9703, US

Plant Location: Same Address as Manufacturer

**Manufacturer: Guardian Electric Manufacturing Company (CAGE Code: 73949)**
Location: 1425 Lake Avenue, Woodstock, IL 60098, US

Plant Location: Same Address as Manufacturer

**Manufacturer: Leach International Europe (CAGE Code: F0219)**
Location: 2 Rue Goethe, F-57430 Sarralbe, France

Plant Location: Same Address as Manufacturer

**Manufacturer: Leach International North America (CAGE Code: 58657)**
Location: North America, P. O. Box 5032, 6900 Orangethorpe Avenue, Buena Park, CA 90620-1351, US

Plant Locations:
1. Same Address as Manufacturer

Distributor Locations:

1. Avnet Electronics Marketing, 3350 NW 53rd Street, #105-107, Ft. Lauderdale, FL 33309, US
2. Avnet Electronics Marketing, 9401 James Avenue S, #140, Bloomington, MN 55431, US
3. Avnet Electronics Marketing, 44191 Plymouth Oaks Boulevard, Plymouth, MI 48170, US
4. Avnet Electronics Marketing, 10-D Centennial Drive, Peabody, MA 01960, US
5. Avnet Electronics Marketing, 7134 Columbia Gateway Drive, Columbia, MD 21046, US
6. Avnet Electronics Marketing, 9200 Indian Creek Parkway, Overland, KS 66210, US
7. Avnet Electronics Marketing, 655 W. Carmel Drive, #160, Carmel, IN 46032, US
8. Avnet Electronics Marketing, 3030 Salt Creek Lane, #300, Chicago, IL 60005, US
9. Avnet Electronics Marketing, (Category A), 500 Lake Ridge Drive, SE, Smyrna, GA 30082, US
10. Avnet Electronics Marketing, 4975 Bradford Drive, Huntsville, AL 35805, US
11. Avnet Electronics Marketing, 7079 University Boulevard, Winter Park, FL 32792, US
12. Avnet Electronics Marketing, 7000 Atrium Way, #6, Mt. Laurel, NJ 08054, US
13. Avnet Electronics Marketing, 5516 Rio Vista Drive, Clearwater, FL 34620, US
14. Avnet Electronics Marketing, 1157 Highland Avenue, #207, Cheshire, CT 06410, US
15. Avnet Electronics Marketing, 12503 E. Euclid Drive, #20, Denver, CO 80111, US
16. Avnet Electronics Marketing, 21150 Califa Street, Woodland Hills, CA 91327, US
17. Avnet Electronics Marketing, 2105 Lundy Avenue, San Jose, CA 95131, US
18. Avnet Electronics Marketing, 4545 Viewridge Avenue, San Diego, CA 92123, US
19. Avnet Electronics Marketing, 580 Menlo Drive, #2, Rocklin, CA 95765, US
20. Avnet Electronics Marketing, 140 Technology Drive, Suite 400, Irvine, CA 92718, US
21. Avnet Electronics Marketing, 2617 South 46th, Phoenix, AZ 85034, US
22. Avnet Electronics Marketing, 3425 Corporate Way, G & A, Duluth, GA 31036, US
23. Avnet Electronics Marketing, 9750 SW Nimbus Avenue, Beaverton, OR 97005, US
24. Avnet Electronics Marketing, 6705 Millcreek Drive, #1, Mississauga L5N 5R9, Ontario (Toronto District), Canada
25. Avnet Electronics Marketing, 190 Colonnade Road, Nepean K2E 7J5, Ontario (Ottawa District), Canada
26. Avnet Electronics Marketing, 7575 Transcanada Highway, St. Laurent H4T 1V6, Quebec, Canada
27. Avnet Electronics Marketing, 8610 Commerce Court, Burnaby V5A 4N6, British Columbia, Canada
28. Avnet Electronics Marketing, W232 N2960 Roundy Circle West, Pewaukee, WI 53072, US
29. Avnet Electronics Marketing, 8214 154th Avenue, NE, Redmond, WA 98052, US
30. Avnet Electronics Marketing, 1100 East 6600 South, #120, Salt Lake City, UT 84121, US
31. Avnet Electronics Marketing, 10500 Richmond Avenue, #112, Houston, TX 77042, US
32. Avnet Electronics Marketing, 11-A Founders Boulevard, El Paso, TX 79906, US
33. Avnet Electronics Marketing, 3783 Rider Trail South, Earth City, MO 63045, US
34. Avnet Electronics Marketing, 12211 Technology Boulevard, Austin, TX 78727, US
35. Avnet Electronics Marketing, 5234 Green's Dairy Road, Raleigh, NC 27604, US
36. Avnet Electronics Marketing, 12206 E. 51st Street, Tulsa, OK 74146, US
37. Avnet Electronics Marketing, 777-L Dearborn Park Lane, Worthington, OH 43085, US
38. Avnet Electronics Marketing, 30775 Bainbridge Road, Solon, OH 44139, US
39. Avnet Electronics Marketing, 5792 Widewaters Parkway, Syracuse, NY 13214, US
40. Avnet Electronics Marketing, 1057 E. Henrietta Road, Rochester, NY 14623, US
41. Avnet Electronics Marketing, 390 Rabro Drive, Hauppauge, NY 11788, US
42. Avnet Electronics Marketing, 2601 Wyoming Boulevard NE, Albuquerque, NM 87109, US
43. Avnet Electronics Marketing, 10 Lanidex Plaza West, Parsippany, NJ 07054, US
44. Avnet Electronics Marketing, 11333 Page Mill Road, Dallas, TX 75243, US
45. Flame Enterprises, (Category A), 20945 Osborne Street, Canoga Park, CA 91304, US

**Manufacturer: MSD, Inc. (CAGE Code: 00213)**
Location: 700 Orange Street, Darlington, SC 29532, US

Plant Location: Same Address as Manufacturer

**Manufacturer: Precision Connenctor Designs (CAGE Code: 58982)**
Location: 2 Technology Drive, Centennial Park, Peabody, MA 01960-7977, US

Plant Location: Same Address as Manufacturer