Specification Details: **Date: 11/13/2019**

Specification: W-F-1814
Title: Fuse, Cartridge, High Interrupting Capacity
Federal Supply Class (FSC): 5920
Conventional: Yes
Specification contains quality assurance program: No
MIL-STD-790 Established Reliability & High Reliability: No
MIL-STD-690 Failure Rate Sampling Plans & Procedures: No
Weibull Graded: No
Specification contains space level reliability requirements: No
Specification allows test optimization: No

Contact Information:

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH
Primary Qualifying Activity Contact: 614-692-0594, e-mail: vqh.kr@dla.mil
Secondary Qualifying Activity Contact: 614-692-9821, e-mail: vqh.jg@dla.mil

Notes:

N/A

Part Configuration:

WF1814/01-001

Military Specification Sheet Number	Dash Number
WF1814/01	-001

PART LISTINGS

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/01-001	SC 1	Certification dtd 29 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/01-002	SC 3	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/01-003	SC 6	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/01-004	SC 10	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/01-005	SC 15	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/02-001	SC 20	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/03-001	SC 25	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/03-002	SC 30	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/04-001	SC 35	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/04-002	SC 40	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/04-003	SC 45	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/04-004	SC 50	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/04-005	SC 60	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-001	JKS 1	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-002	JKS 3	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-003	JKS 6	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-004	JKS 10	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-005	JKS 15	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-006	JKS 20	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-007	JKS 25	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-008	JKS 30	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/05-001	A4J1	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/05-002	A4J3	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/05-003	A4J6	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/05-004	A4J10	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/05-005	A4J15	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

PART LISTINGS				
GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/05-006	A4J20	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/05-007	A4J25	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/05-008	A4J30	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/06-001	JKS 35	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/06-002	JKS 40	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/06-003	JKS 45	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/06-004	JKS 50	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/06-005	JKS 60	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/06-001	A4J35	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/06-002	A4J40	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/06-003	A4J45	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/06-004	A4J50	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/06-005	A4J60	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/07-001	JKS 70	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/07-002	JKS 80	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/07-003	JKS 90	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/07-004	JKS 100	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/07-001	A4J70	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/07-002	A4J80	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/07-003	A4J90	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/07-004	A4J100	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/08-001	JKS 110	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/08-002	JKS 125	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/08-003	JKS 150	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/08-004	JKS 175	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/08-005	JKS 200	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/08-001	A4J110	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/08-002	A4J125	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/08-003	A4J150	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/08-004	A4J175	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/08-005	A4J200	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/09-001	JKS 225	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/09-002	JKS 250	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/09-003	JKS 300	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/09-004	JKS 350	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/09-005	JKS 400	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/09-001	A4J225	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/09-002	A4J250	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/09-003	A4J300	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/09-004	A4J350	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/09-005	A4J400	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/10-001	JKS 450	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/10-002	JKS 500	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/10-003	JKS 600	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/10-001	A4J450	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/10-002	A4J500	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/10-003	A4J600	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/47-001	KTU 700	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/47-002	KTU 800	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/47-001	A4BY700	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/47-002	A4BY800	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/47-003	A4BY700	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

PART LISTINGS

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/47-004	A4BY800	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/48-001	KTU 1000	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/48-002	KTU 1200	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/48-001	A4BY1000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/48-002	A4BY1200	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/48-003	A4BY1000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/48-004	A4BY1200	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/49-001	KTU 1600	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/49-001	A4BY1600	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/49-002	A4BY1600	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/50-001	KTU 2000	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/50-001	A4BY2000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/50-002	A4BY2000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/51-001	KTU 2500	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/51-001	A4BY2500	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/51-002	A4BY2500	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/52-001	KTU 3000	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/52-001	A4BY3000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/52-002	A4BY3000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/53-001	KTU 4000	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/53-001	A4BY4000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/53-002	A4BY4000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/54-001	KTU 5000	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/54-001	A4BY5000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/54-002	A4BY5000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/55-001	KTU 6000	Certification dtd 28 May 1974	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/55-001	A4BY6000	Certification dtd 6 May 1982	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D101	LPN-RK 1	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F101	KTN-R 1	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D102	LPN-RK 2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D103	LPN-RK 3	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F103	KTN-R 3	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D104	LPN-RK 4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D105	LPN-RK 5	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D106	LPN-RK 6	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F106	KTN-R 6	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D107	LPN-RK 7	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D108	LPN-RK 8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D109	LPN-RK 9	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D110	LPN-RK 10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F110	KTN-R 10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D112	LPN-RK 12	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D115	LPN-RK 15	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F115	KTN-R 15	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D120	LPN-RK 20	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F120	KTN-R 20	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D125	LPN-RK 25	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F125	KTN-R 25	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D130	LPN-RK 30	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F130	KTN-R 30	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)

PART LISTINGS

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/56-D501	FRN-R 1	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D502	FRN-R 2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D503	FRN-R 3	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D504	FRN-R 4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D505	FRN-R 5	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D506	FRN-R 6	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D507	FRN-R 7	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D508	FRN-R 8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D509	FRN-R 9	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D510	FRN-R 10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D512	FRN-R 12	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D515	FRN-R 15	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D520	FRN-R 20	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D525	FRN-R 25	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D530	FRN-R 30	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1001	LPN-RK 1/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1002	LPN-RK 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1003	LPN-RK 3/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1004	LPN-RK 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1005	LPN-RK 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1006	LPN-RK 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1008	LPN-RK 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1014	LPN-RK 1 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1016	LPN-RK 1 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1018	LPN-RK 1 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1025	LPN-RK 2 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1028	LPN-RK 2 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1032	LPN-RK 3 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1035	LPN-RK 3 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1045	LPN-RK 4 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1056	LPN-RK 5 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D1175	LPN-RK 17 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5001	FRN-R 1/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5002	FRN-R 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5003	FRN-R 3/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5004	FRN-R 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5005	FRN-R 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5006	FRN-R 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5008	FRN-R 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5014	FRN-R 1 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5016	FRN-R 1 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5018	FRN-R 1 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5025	FRN-R 2 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5032	FRN-R 3 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5035	FRN-R 3 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5045	FRN-R 4 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5056	FRN-R 5 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D5175	FRN-R 17 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D10015	LPN-RK 15/100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D10112	LPN-RK 1 1/8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D10225	LPN-RK 2 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D10625	LPN-RK 6 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D50015	FRN-R 15/100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D50112	FRN-R 1 1/8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D50125	FRN-R 1 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-D50225	FRN-R 2 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/56-D50625	FRN-R 6 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/56-F101	A2K1R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D101	A2D 1R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D102	A2D 2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F103	A2K3R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D103	A2D 3R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D104	A2D 4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D105	A2D 5R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F106	A2K6R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D106	A2D 6R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D107	A2D 7R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D108	A2D 8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F110	A2K10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D110	A2D 10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D112	A2D 12R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F115	A2K15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D115	A2D 15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F120	A2K20R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D120	A2D 20R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F125	A2K25R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D125	A2D 25R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-F130	A2K30R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D130	A2D 30R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D501	TR 1R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D502	TR 2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D503	TR 3R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D504	TR 4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D505	TR 5R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D506	TR 6R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D507	TR 7R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D508	TR 8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D509	TR 9R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D510	TR 10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D512	TR 12R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D515	TR 15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D520	TR 20R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D525	TR 25R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D530	TR 30R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1001	A2D 1/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1002	A2D 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1003	A2D 3/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1004	A2D 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1005	A2D 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1006	A2D 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1008	A2D 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1014	A2D 1 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1016	A2D 1 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1018	A2D 1 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1025	A2D 2 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1028	A2D 2 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1032	A2D 3 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1035	A2D 3 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1045	A2D 4 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1056	A2D 5 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D1175	A2D 17 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5001	TR 1/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/56-D5002	TR 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5003	TR 3/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5004	TR 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5005	TR 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5006	TR 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5008	TR 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5014	TR 1 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5016	TR 1 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5018	TR 1 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5025	TR 2 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5028	TR 2 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5032	TR 3 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5035	TR 3 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5045	TR 4 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5056	TR 5 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D5175	TR 17 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D10015	A2D 1 5/100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D10112	A2D 1 1/8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D10125	A2D 1 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D10225	A2D 2 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D10625	A2D 6 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D50015	TR 1 5/100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D50112	TR 1 1/8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D50125	TR 1 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D50225	TR 2 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D50625	TR 6 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/56-D109	A2D 9R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico) Ferraz Shawmut (Mexico)
WF1814/57-D135	LPN-RK 35	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-F135	KTN-R 35	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D140	LPN-RK 40	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-F140	KTN-R 40	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D145	LPN-RK 45	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-F145	KTN-R 45	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D150	LPN-RK 50	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-F150	KTN-R 50	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D155	LPN-RK 55	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-F155	KTN-R 55	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D160	LPN-RK 60	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-F160	KTN-R 60	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D535	FRN-R 35	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D540	FRN-R 40	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D545	FRN-R 45	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D550	FRN-R 50	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D555	FRN-R 55	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D560	FRN-R 60	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/57-D135	A2D35R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-F135	A2K35R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D140	A2D40R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-F140	A2K40R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D145	A2D45R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-F145	A2K45R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D150	A2D50R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-F150	A2K50R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D155	A2D55R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-F155	A2K55R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/57-D160	A2D60R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-F160	A2K60R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D535	TR35R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D540	TR40R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D545	TR45R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D550	TR50R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D555	TR55R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/57-D560	TR60R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D1070	LPN-RK 70	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-F1070	KTN-R 70	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D1080	LPN-RK 80	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-F1080	KTN-R 80	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D1090	LPN-RK 90	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-F1090	KTN-R 90	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D1100	LPN-RK 100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-F1100	KTN-R 100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D5070	FRN-R 70	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D5080	FRN-R 80	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D5090	FRN-R 90	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D5100	FRN-R 100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/58-D1070	A2D70R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-F1070	A2K70R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D1080	A2D80R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-F1080	A2K80R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D1090	A2D90R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-F1090	A2K90R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D1100	A2D100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-F1100	A2K100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D5070	TR70R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D5080	TR80R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D5090	TR90R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/58-D5100	TR100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D1110	LPN-RK 110	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-F1110	KTN-R 110	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D1125	LPN-RK 125	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-F1125	KTN-R 125	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D1150	LPN-RK 150	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-F1150	KTN-R 150	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D1175	LPN-RK 175	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-F1175	KTN-R 175	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D1200	LPN-RK 200	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-F1200	KTN-R 200	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D5110	FRN-R 110	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D5125	FRN-R 125	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D5150	FRN-R 150	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D5175	FRN-R 175	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-D5200	FRN-R 200	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/59-F1110	A2K120R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D1110	A2D110R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-F1125	A2K125R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D1125	A2D125R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-F1150	A2K150R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D1150	A2D150R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-F1175	A2K175R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D1175	A2D175R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/59-D1200	TR200R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-F1200	A2K200R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D1200	A2D200R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D5110	TR110R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D5125	TR125R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D5150	TR150R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/59-D5175	TR175R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D1225	LPN-RK 225	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-F1225	KTN-R 225	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D1250	LPN-RK 250	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-F1250	KTN-R 250	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D1300	LPN-RK 300	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-F1300	KTN-R 300	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D1350	LPN-RK 350	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-F1350	KTN-R 350	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D1400	LPN-RK 400	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-F1400	KTN-R 400	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D5225	FRN-R 225	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D5250	FRN-R 250	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D5300	FRN-R 300	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D5350	FRN-R 350	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D5400	FRN-R 400	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/60-D1225	A2D225R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-F1225	A2K225R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D1250	A2D250R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-F1250	A2K250R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D1300	A2D300R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-F1300	A2K300R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D1350	A2D350R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-F1350	A2K350R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D1400	A2D400R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-F1400	A2K400R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D5225	TR225R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D5250	TR250R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D5300	TR300R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D5350	TR350R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/60-D5400	TR400R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-D1450	LPN-RK 450	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-F1450	KTN-R 450	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-D1500	LPN-RK 500	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-F1500	KTN-R 500	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-D1600	LPN-RK 600	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-F1600	KTN-R 600	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-D5450	FRN-R 450	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-D5500	FRN-R 500	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-D5600	FRN-R 600	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/61-D1450	A2D450R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-F1450	A2K450R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-D1500	A2D500R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-F1500	A2K500R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-D1600	A2D600R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-F1600	A2K600R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-D5450	TR450R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-D5500	TR500R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/61-D5600	TR600R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/62-D0015	LPS-RK 15/100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F101	KTS-R 1	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D101	LPS-RK 1	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D102	LPS-RK 2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D103	LPS-RK 3	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F103	KTS-R 3	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D104	LPS-RK 4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D105	LPS-RK 5	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D106	LPS-RK 6	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F106	KTS-R 6	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D107	LPS-RK 7	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D108	LPS-RK 8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D109	LPS-RK 9	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D110	LPS-RK 10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F110	KTS-R 10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D112	LPS-RK 12	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D115	LPS-RK 15	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F115	KTS-R 15	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D120	LPS-RK 20	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F120	KTS-R 20	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D125	LPS-RK 25	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F125	KTS-R 25	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D130	LPS-RK 30	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F130	KTS-R 30	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D501	FRS-R 1	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D502	FRS-R 2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D503	FRS-R 3	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D504	FRS-R 4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D505	FRS-R 5	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D507	FRS-R 7	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D508	FRS-R 8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D509	FRS-R 9	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D510	FRS-R 10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D512	FRS-R 12	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D515	FRS-R 15	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D520	FRS-R 20	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D525	FRS-R 25	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1001	LPS-RK 1/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1002	LPS-RK 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1003	LPS-RK 3/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1004	LPS-RK 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1005	LPS-RK 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1006	LPS-RK 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1008	LPS-RK 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1014	LPS-RK 1 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1016	LPS-RK 1 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1018	LPS-RK 1 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1025	LPS-RK 2 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1028	LPS-RK 2 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1032	LPS-RK 3 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1035	LPS-RK 3 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1045	LPS-RK 4 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1056	LPS-RK 5 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D1175	LPS-RK 17 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5001	FRS-R 1/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5002	FRS-R 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/62-D5003	FRS-R 3/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5004	FRS-R 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5005	FRS-R 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5006	FRS-R 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5008	FRS-R 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5014	FRS-R 1 4/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5016	FRS-R 1 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5018	FRS-R 1 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5025	FRS-R 2 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5028	FRS-R 2 8/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5032	FRS-R 3 2/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5035	FRS-R 3 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5045	FRS-R 4 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5056	FRS-R 5 6/10	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D5175	FRS-R 17 1/2	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D10112	LPS-RK 1 1/8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D10125	LPS-RK 1 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D10225	LPS-RK 2 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D10625	LPS-RK 6 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D50015	FRS-R 15/100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D50112	FRS-R 1 1/8	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D50125	FRS-R 1 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D50225	FRS-R 2 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-D50625	FRS-R 6 1/4	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/62-F101	A6K1R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D101	A6D 1R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D102	A6D 2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F103	A6K3R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D103	A6D 3R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D104	A6D 4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D105	A6D 5R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F106	A6K6R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D106	A6D 6R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D107	A6D 7R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D108	A6D 8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D109	A6D 9R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F110	A6K10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D110	A6D 10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D112	A6D 12R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F115	A6K15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D115	A6D 15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F120	A6K20R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D120	A6D 20R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F125	A6K25R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D125	A6D 25R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-F130	A6K30R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D130	A6D 30 R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D501	TRS 1R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D502	TRS 2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D503	TRS 3R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D504	TRS 4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D505	TRS 5R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D506	TRS 6R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D507	TRS 7R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D508	TRS 8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D509	TRS 9R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/62-D510	TRS 10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D512	TRS 12R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D515	TRS 15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D520	TRS 20R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D525	TRS 15R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D530	TRS 30R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1001	A6D 1/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1002	A6D 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1003	A6D 3/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1004	A6D 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1005	A6D 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1006	A6D 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1008	A6D 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1014	A6D 1 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1016	A6D 1 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1018	A6D 1 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1025	A6D 2 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1028	A6D 2 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1032	A6D 3 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1035	A6D 3 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1045	A6D 4 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1056	A6D 5 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D1175	A6D 17 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5001	TRS 1/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5002	TRS 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5003	TRS 3/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5004	TRS 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5005	TRS 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5006	TRS 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5008	TRS 5/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5014	TRS 1 4/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5016	TRS 1 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5018	TRS 1 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5025	TRS 2 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5028	TRS 2 8/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5032	TRS 3 2/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5035	TRS 3 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5045	TRS 4 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5056	TRS 5 6/10R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D5175	TRS 17 1/2R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D10015	A6D 1 5/100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D10112	A6D 1 1/8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D10125	A6D 1 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D10225	A6D 2 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D10625	A6D 6 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D50015	TRS 1 5/100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D50112	TRS 1 1/8R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D50125	TRS 1 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D50225	TRS 2 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/62-D50625	TRS 6 1/4R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D135	LPS-RK 35	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-F135	KTS-R 35	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D140	LPS-RK 40	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-F140	KTS-R 40	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D145	LPS-RK 45	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-F145	KTS-R 45	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/63-D150	LPS-RK 50	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-F150	KTS-R 50	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D160	LPS-RK 60	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-F160	KTS-R 60	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D535	FRS-R 35	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D540	FRS-R 40	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D545	FRS-R 45	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D550	FRS-R 50	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D560	FRS-R 60	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/63-D135	A6D35R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-F135	A6K35R	Certification 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D140	A6D40R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-F140	A6K40R	Certification 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D145	A6D45R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-F145	A6K45R	Certification 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D150	A6D50R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-F150	A6K50R	Certification 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D160	A6D60R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-F160	A6K60R	Certification 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D535	TRS35R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D540	TRS40R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D545	TRS45R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D550	TRS50R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/63-D560	TRS60R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D1070	LPS-RK 70	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-F1070	KTS-R 70	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D1080	LPS-RK 80	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-F1080	KTS-R 80	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D1090	LPS-RK 90	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-F1090	KTS-R 90	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D1100	LPS-RK 100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-F1100	KTS-R 100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D5070	FRS-R 70	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D5080	FRS-R 80	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D5090	FRS-R 90	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D5100	FRS-R 100	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/64-D1070	A6D70R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-F1070	A6K70R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D1080	A6D80R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-F1080	A6K80R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D1090	A6D90R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-F1090	A6K90R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D1100	A6D100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-F1100	A6K100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D5070	TRS70R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D5080	TRS80R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D5090	TRS90R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/64-D5100	TRS100R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D1110	LPS-RK 110	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-F1110	KTS-R 110	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D1125	LPS-RK 125	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-F1125	KTS-R 125	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D1150	LPS-RK 150	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-F1150	KTS-R 150	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D1175	LPS-RK 175	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/65-F1175	KTS-R 175	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D1200	LPS-RK 200	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-F1200	KTS-R 200	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D5110	FRS-R 110	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D5125	FRS-R 125	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D5150	FRS-R 150	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D5175	FRS-R 175	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D5200	FRS-R 200	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/65-D1110	A6D110R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-F1110	A6K110R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D1125	A6D125R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-F1125	A6K125R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D1150	AD6D150R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-F1150	A6K150R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D1175	AD6D175R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-F1175	A6K175R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D1200	AD6D200R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-F1200	A6K200R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D5110	TRS110R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D5125	TRS125R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D5150	TRS150R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D5175	TRS175R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/65-D5200	TRS200R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D1225	LPS-RK 225	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-F1225	KTS-R 225	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D1250	LPS-RK 250	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-F1250	KTS-R 250	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D1300	LPS-RK 300	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-F1300	KTS-R 300	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D1350	LPS-RK 350	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-F1350	KTS-R 350	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D1400	LPS-RK 400	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-F1400	KTS-R 400	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D5225	FRS-R 225	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D5300	FRS-R 250	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D5350	FRS-R 300	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D5350	FRS-R 350	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D5400	FRS-R 400	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/66-D1225	A6K225R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-F1225	A6K225R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D1250	A6K250R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-F1250	A6K250R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D1300	A6D300R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-F1300	A6K300R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D1350	A6D350R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-F1350	A6K350R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D1400	A6D400R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-F1400	A6K400R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D5225	TRS225R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D5250	TRS250R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D5300	TRS300R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D5350	TRS350R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/66-D5400	TRS400R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-D1450	LPS-RK 450	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-F1450	KTS-R 450	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)

PART LISTINGS				
GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	UNDERWRITERS' LABORATORIES FILE NUMBER	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
WF1814/67-D1500	LPS-RK 500	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-F1500	KTS-R 500	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-D1600	LPS-RK 600	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-F1600	KTS-R 600	Certification dtd 4 Feb 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-D5450	FRS-R 450	Certification dtd 8 Mar 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-D5500	FRS-R 500	Certification dtd 8 Mar 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-D5600	FRS-R 600	Certification dtd 8 Mar 1983	Guide No. JDDZ File E4273	Eaton Bussmann, LLC (Juarez, Mexico)
WF1814/67-D1450	A6D450R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-F1450	A6K450F	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-D1500	A6D500R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-F1500	A6K500F	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-D1600	A6D600R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-F1600	A6K600R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-D5450	TRS450R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-D5500	TRS500R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)
WF1814/67-D5600	TRS600R	Certification dtd 10 Feb 1983	Guide No. JDDZ File E2137 (M)	Ferraz Shawmut (Mexico)

Manufacturer and Supplier Location Information

Manufacturer: Eaton Bussmann, LLC. (CAGE Code: 71400)

Location: P.O. Box 14460, St. Louis, MO 63178, US, 114 Old State Road, Ellsville, MO 63021-5915, US

Plants:

1. Eaton Bussmann, LLC (Juarez, Mexico), Planta Juarez-Prolongacion Hermanos Escobar, No. 7750, Parque Industrial Omega, Col. Partido Doblado,, Ciudad Juarez, 32320 Ciudad Juarez, Chihuahua, MX, Mexico

Manufacturer: Ferraz Shawmut, Inc. (CAGE Code: 71424)

Location: 374 Merrimac Street, Newburyport, MA 01950-1930, US

Plants:

1. Ferraz Shawmut (Mexico), Parque Industrial Rio Bravo, Nuevu Zaragoza D.B. Chih., Juarez, MX