**Specification Details:** **Date: 9/28/2021**

Specification: W-F-1814
Title: Fuse, Cartridge, High Interrupting Capacity
Federal Supply Class (FSC): 5920
Conventional: Yes
Specification contains quality assurance program: No
MIL-STD-790 Established Reliability & High Reliability: No
MIL-STD-690 Failure Rate Sampling Plans & Procedures: No
Weibull Graded: No
Specification contains space level reliability requirements: No
Specification allows test optimization: No

**Contact Information:**

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH
Primary Qualifying Activity Contact: 614-692-0504, e-mail: vqh.bb@dla.mil
Secondary Qualifying Activity Contact: 614-692-9821, e-mail: vqh.jg@dla.mil

**Notes:**

N/A

**Part Configuration:**

WF1814/01-001

| Military Specification Sheet Number | Dash Number |
|---|---|
| WF1814/01 | -001 |

**PART LISTINGS**

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/01-001 | SC 1 | Certification dtd 29 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/01-002 | SC 3 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/01-003 | SC 6 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/01-004 | SC 10 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/01-005 | SC 15 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/02-001 | SC 20 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/03-001 | SC 25 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/03-002 | SC 30 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/04-001 | SC 35 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/04-002 | SC 40 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/04-003 | SC 45 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/04-004 | SC 50 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/04-005 | SC 60 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-001 | JKS 1 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-002 | JKS 3 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-003 | JKS 6 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-004 | JKS 10 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-005 | JKS 15 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-006 | JKS 20 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-007 | JKS 25 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-008 | JKS 30 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/05-001 | A4J1 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/05-002 | A4J3 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/05-003 | A4J6 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/05-004 | A4J10 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/05-005 | A4J15 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

| PART LISTINGS | | | | |
|---|---|---|---|---|
| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
| WF1814/05-006 | A4J20 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/05-007 | A4J25 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/05-008 | A4J30 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/06-001 | JKS 35 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/06-002 | JKS 40 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/06-003 | JKS 45 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/06-004 | JKS 50 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/06-005 | JKS 60 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/06-001 | A4J35 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/06-002 | A4J40 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/06-003 | A4J45 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/06-004 | A4J50 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/06-005 | A4J60 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/07-001 | JKS 70 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/07-002 | JKS 80 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/07-003 | JKS 90 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/07-004 | JKS 100 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/07-001 | A4J70 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/07-002 | A4J80 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/07-003 | A4J90 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/07-004 | A4J100 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/08-001 | JKS 110 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/08-002 | JKS 125 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/08-003 | JKS 150 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/08-004 | JKS 175 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/08-005 | JKS 200 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/08-001 | A4J110 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/08-002 | A4J125 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/08-003 | A4J150 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/08-004 | A4J175 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/08-005 | A4J200 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/09-001 | JKS 225 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/09-002 | JKS 250 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/09-003 | JKS 300 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/09-004 | JKS 350 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/09-005 | JKS 400 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/09-001 | A4J225 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/09-002 | A4J250 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/09-003 | A4J300 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/09-004 | A4J350 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/09-005 | A4J400 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/10-001 | JKS 450 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/10-002 | JKS 500 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/10-003 | JKS 600 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/10-001 | A4J450 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/10-002 | A4J500 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/10-003 | A4J600 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/47-001 | KTU 700 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/47-002 | KTU 800 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/47-001 | A4BY700 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/47-002 | A4BY800 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/47-003 | A4BY700 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/47-004 | A4BY800 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/48-001 | KTU 1000 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/48-002 | KTU 1200 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/48-001 | A4BY1000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/48-002 | A4BY1200 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/48-003 | A4BY1000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/48-004 | A4BY1200 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/49-001 | KTU 1600 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/49-001 | A4BY1600 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/49-002 | A4BY1600 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/50-001 | KTU 2000 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/50-001 | A4BY2000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/50-002 | A4BY2000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/51-001 | KTU 2500 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/51-001 | A4BY2500 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/51-002 | A4BY2500 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/52-001 | KTU 3000 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/52-001 | A4BY3000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/52-002 | A4BY3000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/53-001 | KTU 4000 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/53-001 | A4BY4000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/53-002 | A4BY4000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/54-001 | KTU 5000 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/54-001 | A4BY5000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/54-002 | A4BY5000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/55-001 | KTU 6000 | Certification dtd 28 May 1974 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/55-001 | A4BY6000 | Certification dtd 6 May 1982 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D101 | LPN-RK 1 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F101 | KTN-R 1 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D102 | LPN-RK 2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D103 | LPN-RK 3 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F103 | KTN-R 3 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D104 | LPN-RK 4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D105 | LPN-RK 5 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D106 | LPN-RK 6 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F106 | KTN-R 6 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D107 | LPN-RK 7 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D108 | LPN-RK 8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D109 | LPN-RK 9 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D110 | LPN-RK 10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F110 | KTN-R 10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D112 | LPN-RK 12 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D115 | LPN-RK 15 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F115 | KTN-R 15 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D120 | LPN-RK 20 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F120 | KTN-R 20 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D125 | LPN-RK 25 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F125 | KTN-R 25 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D130 | LPN-RK 30 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F130 | KTN-R 30 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/56-D501 | FRN-R 1 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D502 | FRN-R 2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D503 | FRN-R 3 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D504 | FRN-R 4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D505 | FRN-R 5 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D506 | FRN-R 6 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D507 | FRN-R 7 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D508 | FRN-R 8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D509 | FRN-R 9 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D510 | FRN-R 10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D512 | FRN-R 12 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D515 | FRN-R 15 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D520 | FRN-R 20 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D525 | FRN-R 25 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D530 | FRN-R 30 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1001 | LPN-RK 1/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1002 | LPN-RK 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1003 | LPN-RK 3/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1004 | LPN-RK 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1005 | LPN-RK 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1006 | LPN-RK 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1008 | LPN-RK 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1014 | LPN-RK 1 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1016 | LPN-RK 1 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1018 | LPN-RK 1 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1025 | LPN-RK 2 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1028 | LPN-RK 2 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1032 | LPN-RK 3 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1035 | LPN-RK 3 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1045 | LPN-RK 4 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1056 | LPN-RK 5 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D1175 | LPN-RK 17 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5001 | FRN-R 1/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5002 | FRN-R 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5003 | FRN-R 3/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5004 | FRN-R 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5005 | FRN-R 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5006 | FRN-R 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5008 | FRN-R 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5014 | FRN-R 1 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5016 | FRN-R 1 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5018 | FRN-R 1 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5025 | FRN-R 2 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5032 | FRN-R 3 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5035 | FRN-R 3 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5045 | FRN-R 4 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5056 | FRN-R 5 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D5175 | FRN-R 17 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D10015 | LPN-RK 15/100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D10112 | LPN-RK 1 1/8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D10225 | LPN-RK 2 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D10625 | LPN-RK 6 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D50015 | FRN-R 15/100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D50112 | FRN-R 1 1/8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D50125 | FRN-R 1 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-D50225 | FRN-R 2 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/56-D50625 | FRN-R 6 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/56-F101 | A2K1R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D101 | A2D 1R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D102 | A2D 2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F103 | A2K3R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D103 | A2D 3R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D104 | A2D 4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D105 | A2D 5R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F106 | A2K6R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D106 | A2D 6R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D107 | A2D 7R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D108 | A2D 8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F110 | A2K10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D110 | A2D 10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D112 | A2D 12R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F115 | A2K15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D115 | A2D 15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F120 | A2K20R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D120 | A2D 20R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F125 | A2K25R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D125 | A2D 25R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-F130 | A2K30R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D130 | A2D 30R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D501 | TR 1R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D502 | TR 2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D503 | TR 3R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D504 | TR 4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D505 | TR 5R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D506 | TR 6R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D507 | TR 7R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D508 | TR 8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D509 | TR 9R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D510 | TR 10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D512 | TR 12R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D515 | TR 15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D520 | TR 20R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D525 | TR 25R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D530 | TR 30R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1001 | A2D 1/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1002 | A2D 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1003 | A2D 3/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1004 | A2D 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1005 | A2D 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1006 | A2D 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1008 | A2D 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1014 | A2D 1 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1016 | A2D 1 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1018 | A2D 1 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1025 | A2D 2 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1028 | A2D 2 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1032 | A2D 3 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1035 | A2D 3 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1045 | A2D 4 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1056 | A2D 5 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D1175 | A2D 17 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5001 | TR 1/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/56-D5002 | TR 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5003 | TR 3/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5004 | TR 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5005 | TR 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5006 | TR 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5008 | TR 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5014 | TR 1 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5016 | TR 1 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5018 | TR 1 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5025 | TR 2 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5028 | TR 2 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5032 | TR 3 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5035 | TR 3 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5045 | TR 4 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5056 | TR 5 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D5175 | TR 17 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D10015 | A2D 1 5/100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D10112 | A2D 1 1/8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D10125 | A2D 1 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D10225 | A2D 2 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D10625 | A2D 6 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D50015 | TR 1 5/100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D50112 | TR 1 1/8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D50125 | TR 1 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D50225 | TR 2 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D50625 | TR 6 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/56-D109 | A2D 9R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico)<br>Ferraz Shawmut (Mexico) |
| WF1814/57-D135 | LPN-RK 35 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-F135 | KTN-R 35 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D140 | LPN-RK 40 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-F140 | KTN-R 40 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D145 | LPN-RK 45 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-F145 | KTN-R 45 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D150 | LPN-RK 50 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-F150 | KTN-R 50 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D155 | LPN-RK 55 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-F155 | KTN-R 55 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D160 | LPN-RK 60 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-F160 | KTN-R 60 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D535 | FRN-R 35 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D540 | FRN-R 40 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D545 | FRN-R 45 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D550 | FRN-R 50 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D555 | FRN-R 55 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D560 | FRN-R 60 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/57-D135 | A2D35R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-F135 | A2K35R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D140 | A2D40R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-F140 | A2K40R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D145 | A2D45R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-F145 | A2K45R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D150 | A2D50R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-F150 | A2K50R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D155 | A2D55R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-F155 | A2K55R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/57-D160 | A2D60R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-F160 | A2K60R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D535 | TR35R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D540 | TR40R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D545 | TR45R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D550 | TR50R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D555 | TR55R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/57-D560 | TR60R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D1070 | LPN-RK 70 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-F1070 | KTN-R 70 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D1080 | LPN-RK 80 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-F1080 | KTN-R 80 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D1090 | LPN-RK 90 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-F1090 | KTN-R 90 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D1100 | LPN-RK 100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-F1100 | KTN-R 100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D5070 | FRN-R 70 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D5080 | FRN-R 80 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D5090 | FRN-R 90 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D5100 | FRN-R 100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/58-D1070 | A2D70R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-F1070 | A2K70R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D1080 | A2D80R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-F1080 | A2K80R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D1090 | A2D90R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-F1090 | A2K90R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D1100 | A2D100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-F1100 | A2K100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D5070 | TR70R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D5080 | TR80R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D5090 | TR90R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/58-D5100 | TR100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D1110 | LPN-RK 110 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-F1110 | KTN-R 110 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D1125 | LPN-RK 125 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-F1125 | KTN-R 125 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D1150 | LPN-RK 150 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-F1150 | KTN-R 150 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D1175 | LPN-RK 175 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-F1175 | KTN-R 175 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D1200 | LPN-RK 200 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-F1200 | KTN-R 200 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D5110 | FRN-R 110 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D5125 | FRN-R 125 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D5150 | FRN-R 150 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D5175 | FRN-R 175 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-D5200 | FRN-R 200 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/59-F1110 | A2K120R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D1110 | A2D110R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-F1125 | A2K125R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D1125 | A2D125R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-F1150 | A2K150R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D1150 | A2D150R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-F1175 | A2K175R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D1175 | A2D175R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/59-D1200 | TR200R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-F1200 | A2K200R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D1200 | A2D200R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D5110 | TR110R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D5125 | TR125R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D5150 | TR150R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/59-D5175 | TR175R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D1225 | LPN-RK 225 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-F1225 | KTN-R 225 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D1250 | LPN-RK 250 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-F1250 | KTN-R 250 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D1300 | LPN-RK 300 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-F1300 | KTN-R 300 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D1350 | LPN-RK 350 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-F1350 | KTN-R 350 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D1400 | LPN-RK 400 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-F1400 | KTN-R 400 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D5225 | FRN-R 225 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D5250 | FRN-R 250 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D5300 | FRN-R 300 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D5350 | FRN-R 350 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D5400 | FRN-R 400 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/60-D1225 | A2D225R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-F1225 | A2K225R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D1250 | A2D250R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-F1250 | A2K250R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D1300 | A2D300R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-F1300 | A2K300R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D1350 | A2D350R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-F1350 | A2K350R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D1400 | A2D400R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-F1400 | A2K400R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D5225 | TR225R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D5250 | TR250R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D5300 | TR300R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D5350 | TR350R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/60-D5400 | TR400R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-D1450 | LPN-RK 450 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-F1450 | KTN-R 450 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-D1500 | LPN-RK 500 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-F1500 | KTN-R 500 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-D1600 | LPN-RK 600 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-F1600 | KTN-R 600 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-D5450 | FRN-R 450 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-D5500 | FRN-R 500 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-D5600 | FRN-R 600 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/61-D1450 | A2D450R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-F1450 | A2K450R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-D1500 | A2D500R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-F1500 | A2K500R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-D1600 | A2D600R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-F1600 | A2K600R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-D5450 | TR450R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-D5500 | TR500R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/61-D5600 | TR600R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/62-D0015 | LPS-RK 15/100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F101 | KTS-R 1 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D101 | LPS-RK 1 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D102 | LPS-RK 2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D103 | LPS-RK 3 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F103 | KTS-R 3 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D104 | LPS-RK 4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D105 | LPS-RK 5 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D106 | LPS-RK 6 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F106 | KTS-R 6 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D107 | LPS-RK 7 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D108 | LPS-RK 8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D109 | LPS-RK 9 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D110 | LPS-RK 10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F110 | KTS-R 10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D112 | LPS-RK 12 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D115 | LPS-RK 15 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F115 | KTS-R 15 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D120 | LPS-RK 20 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F120 | KTS-R 20 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D125 | LPS-RK 25 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F125 | KTS-R 25 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D130 | LPS-RK 30 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F130 | KTS-R 30 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D501 | FRS-R 1 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D502 | FRS-R 2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D503 | FRS-R 3 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D504 | FRS-R 4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D505 | FRS-R 5 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D507 | FRS-R 7 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D508 | FRS-R 8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D509 | FRS-R 9 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D510 | FRS-R 10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D512 | FRS-R 12 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D515 | FRS-R 15 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D520 | FRS-R 20 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D525 | FRS-R 25 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1001 | LPS-RK 1/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1002 | LPS-RK 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1003 | LPS-RK 3/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1004 | LPS-RK 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1005 | LPS-RK 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1006 | LPS-RK 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1008 | LPS-RK 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1014 | LPS-RK 1 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1016 | LPS-RK 1 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1018 | LPS-RK 1 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1025 | LPS-RK 2 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1028 | LPS-RK 2 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1032 | LPS-RK 3 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1035 | LPS-RK 3 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1045 | LPS-RK 4 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1056 | LPS-RK 5 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D1175 | LPS-RK 17 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5001 | FRS-R 1/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5002 | FRS-R 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/62-D5003 | FRS-R 3/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5004 | FRS-R 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5005 | FRS-R 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5006 | FRS-R 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5008 | FRS-R 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5014 | FRS-R 1 4/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5016 | FRS-R 1 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5018 | FRS-R 1 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5025 | FRS-R 2 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5028 | FRS-R 2 8/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5032 | FRS-R 3 2/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5035 | FRS-R 3 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5045 | FRS-R 4 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5056 | FRS-R 5 6/10 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D5175 | FRS-R 17 1/2 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D10112 | LPS-RK 1 1/8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D10125 | LPS-RK 1 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D10225 | LPS-RK 2 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D10625 | LPS-RK 6 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D50015 | FRS-R 15/100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D50112 | FRS-R 1 1/8 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D50125 | FRS-R 1 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D50225 | FRS-R 2 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-D50625 | FRS-R 6 1/4 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/62-F101 | A6K1R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D101 | A6D 1R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D102 | A6D 2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F103 | A6K3R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D103 | A6D 3R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D104 | A6D 4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D105 | A6D 5R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F106 | A6K6R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D106 | A6D 6R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D107 | A6D 7R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D108 | A6D 8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D109 | A6D 9R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F110 | A6K10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D110 | A6D 10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D112 | A6D 12R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F115 | A6K15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D115 | A6D 15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F120 | A6K20R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D120 | A6D 20R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F125 | A6K25R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D125 | A6D 25R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-F130 | A6K30R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D130 | A6D 30 R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D501 | TRS 1R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D502 | TRS 2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D503 | TRS 3R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D504 | TRS 4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D505 | TRS 5R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D506 | TRS 6R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D507 | TRS 7R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D508 | TRS 8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D509 | TRS 9R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/62-D510 | TRS 10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D512 | TRS 12R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D515 | TRS 15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D520 | TRS 20R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D525 | TRS 15R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D530 | TRS 30R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1001 | A6D 1/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1002 | A6D 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1003 | A6D 3/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1004 | A6D 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1005 | A6D 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1006 | A6D 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1008 | A6D 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1014 | A6D 1 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1016 | A6D 1 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1018 | A6D 1 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1025 | A6D 2 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1028 | A6D 2 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1032 | A6D 3 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1035 | A6D 3 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1045 | A6D 4 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1056 | A6D 5 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D1175 | A6D 17 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5001 | TRS 1/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5002 | TRS 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5003 | TRS 3/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5004 | TRS 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5005 | TRS 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5006 | TRS 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5008 | TRS 5/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5014 | TRS 1 4/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5016 | TRS 1 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5018 | TRS 1 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5025 | TRS 2 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5028 | TRS 2 8/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5032 | TRS 3 2/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5035 | TRS 3 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5045 | TRS 4 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5056 | TRS 5 6/10R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D5175 | TRS 17 1/2R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D10015 | A6D 1 5/100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D10112 | A6D 1 1/8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D10125 | A6D 1 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D10225 | A6D 2 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D10625 | A6D 6 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D50015 | TRS 1 5/100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D50112 | TRS 1 1/8R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D50125 | TRS 1 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D50225 | TRS 2 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/62-D50625 | TRS 6 1/4R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D135 | LPS-RK 35 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-F135 | KTS-R 35 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D140 | LPS-RK 40 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-F140 | KTS-R 40 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D145 | LPS-RK 45 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-F145 | KTS-R 45 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/63-D150 | LPS-RK 50 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-F150 | KTS-R 50 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D160 | LPS-RK 60 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-F160 | KTS-R 60 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D535 | FRS-R 35 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D540 | FRS-R 40 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D545 | FRS-R 45 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D550 | FRS-R 50 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D560 | FRS-R 60 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/63-D135 | A6D35R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-F135 | A6K35R | Certification 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D140 | A6D40R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-F140 | A6K40R | Certification 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D145 | A6D45R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-F145 | A6K45R | Certification 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D150 | A6D50R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-F150 | A6K50R | Certification 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D160 | A6D60R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-F160 | A6K60R | Certification 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D535 | TRS35R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D540 | TRS40R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D545 | TRS45R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D550 | TRS50R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/63-D560 | TRS60R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D1070 | LPS-RK 70 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-F1070 | KTS-R 70 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D1080 | LPS-RK 80 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-F1080 | KTS-R 80 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D1090 | LPS-RK 90 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-F1090 | KTS-R 90 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D1100 | LPS-RK 100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-F1100 | KTS-R 100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D5070 | FRS-R 70 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D5080 | FRS-R 80 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D5090 | FRS-R 90 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D5100 | FRS-R 100 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/64-D1070 | A6D70R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-F1070 | A6K70R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D1080 | A6D80R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-F1080 | A6K80R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D1090 | A6D90R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-F1090 | A6K90R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D1100 | A6D100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-F1100 | A6K100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D5070 | TRS70R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D5080 | TRS80R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D5090 | TRS90R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/64-D5100 | TRS100R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D1110 | LPS-RK 110 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-F1110 | KTS-R 110 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D1125 | LPS-RK 125 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-F1125 | KTS-R 125 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D1150 | LPS-RK 150 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-F1150 | KTS-R 150 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D1175 | LPS-RK 175 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| WF1814/65-F1175 | KTS-R 175 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D1200 | LPS-RK 200 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-F1200 | KTS-R 200 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D5110 | FRS-R 110 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D5125 | FRS-R 125 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D5150 | FRS-R 150 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D5175 | FRS-R 175 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D5200 | FRS-R 200 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/65-D1110 | A6D110R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-F1110 | A6K110R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D1125 | A6D125R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-F1125 | A6K125R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D1150 | AD6D150R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-F1150 | A6K150R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D1175 | AD6D175R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-F1175 | A6K175R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D1200 | AD6D200R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-F1200 | A6K200R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D5110 | TRS110R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D5125 | TRS125R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D5150 | TRS150R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D5175 | TRS175R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/65-D5200 | TRS200R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D1225 | LPS-RK 225 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-F1225 | KTS-R 225 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D1250 | LPS-RK 250 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-F1250 | KTS-R 250 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D1300 | LPS-RK 300 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-F1300 | KTS-R 300 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D1350 | LPS-RK 350 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-F1350 | KTS-R 350 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D1400 | LPS-RK 400 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-F1400 | KTS-R 400 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D5225 | FRS-R 225 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D5300 | FRS-R 250 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D5350 | FRS-R 300 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D5350 | FRS-R 350 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D5400 | FRS-R 400 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/66-D1225 | A6K225R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-F1225 | A6K225R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D1250 | A6K250R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-F1250 | A6K250R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D1300 | A6D300R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-F1300 | A6K300R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D1350 | A6D350R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-F1350 | A6K350R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D1400 | A6D400R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-F1400 | A6K400R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D5225 | TRS225R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D5250 | TRS250R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D5300 | TRS300R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D5350 | TRS350R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/66-D5400 | TRS400R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-D1450 | LPS-RK 450 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-F1450 | KTS-R 450 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |

| PART LISTINGS | | | | |
|---|---|---|---|---|
| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | UNDERWRITERS' LABORATORIES FILE NUMBER | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
| WF1814/67-D1500 | LPS-RK 500 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-F1500 | KTS-R 500 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-D1600 | LPS-RK 600 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-F1600 | KTS-R 600 | Certification dtd 4 Feb 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-D5450 | FRS-R 450 | Certification dtd 8 Mar 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-D5500 | FRS-R 500 | Certification dtd 8 Mar 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-D5600 | FRS-R 600 | Certification dtd 8 Mar 1983 | Guide No. JDDZ File E4273 | Eaton Bussmann, LLC (Juarez, Mexico) |
| WF1814/67-D1450 | A6D450R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-F1450 | A6K450F | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-D1500 | A6D500R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-F1500 | A6K500F | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-D1600 | A6D600R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-F1600 | A6K600R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-D5450 | TRS450R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-D5500 | TRS500R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |
| WF1814/67-D5600 | TRS600R | Certification dtd 10 Feb 1983 | Guide No. JDDZ File E2137 (M) | Ferraz Shawmut (Mexico) |

## Manufacturer and Supplier Location Information

**Manufacturer: Eaton Bussmann, LLC. (CAGE Code: 71400)**

Location: P.O. Box 14460, 114 Old State Road, Ellsville, MO 63021-5915, US

Plants:

1. Eaton Bussmann, LLC (Juarez, Mexico), Planta Juarez-Prolongacion Hermanos Escobar, No. 7750, Parque Industrial Omega, Col. Partido Doblado,, Ciudad Juarez, 32320 Ciudad Juarez, Chihuahua, MX, Mexico

**Manufacturer: Ferraz Shawmut, Inc. (CAGE Code: 71424)**

Location: 374 Merrimac Street, Newburyport, MA 01950-1930, US

Plants:

1. Ferraz Shawmut (Mexico), Parque Industrial Rio Bravo, Nuevu Zaragoza D.B. Chih., Juarez, MX