Specification Details: **Date: 8/25/2016**

Specification: MIL-PRF-6106
Title: Relays, Electromagnetic (including Established Reliability (ER) Types)
Federal Supply Class (FSC): 5945
Conventional: No
Specification contains quality assurance program: No
MIL-STD-790 Established Reliability & High Reliability: Yes
MIL-STD-690 Failure Rate Sampling Plans & Procedures: No
Weibull Graded: No
Specification contains space level reliability requirements: No
Specification allows test optimization: No

Contact Information:

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH
Primary Qualifying Activity Contact: 614-692-0594, e-mail: vqh.kr@dla.mil
Secondary Qualifying Activity Contact: 614-692-0586, e-mail: vqh.bt@dla.mil

Notes:

Contact the manufacturer or refer to the manufacturers website for a list of Authorized Distributors.

Part Configuration:

M6106/20-001

Specification Designator	Specification Sheet Number	Dash Number
M6106	/20	-001

PART LISTINGS

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
*** AN3303 Inactive for New Design After 17 Nov 54 (No Superseding Standard)**			
AN3303-2	5724-0015HPM	6106-98-0186	Tyco - CII Technologies
*** AN3306 Inactive for New Design After 17 Nov 54 (No Superseding Standard)**			
AN3306-2	AE108-021-99	6106-1676-06	DARE Electronics, Inc.
*** AN3308 Inactive for New Design After 17 Nov 54 (No Superseding Standard)**			
AN3308-2	5715-0018HPM	6106-98-0187	Tyco - CII Technologies
*** AN3320 Inactive For New Design After 15 Jun 55 (No Superseding Standard)**			
AN3320-1	5002-B	6106-98-0188	Tyco - CII Technologies
*** AN3324 Inactive for New Design After 22 Jun 55 (No Superseding Standard)**			
AN3324-1	5004-B	6106-98-0189	Tyco - CII Technologies
*** AN3362 Inactive for New Design After 30 Aug 57 (No Supeseding Standard)**			
AN3362-1	6041H209	6106-98-0054	Labinal, LLC
*** AN3372 Inactive for New Design After 25 Nov 57 (No Superseding Standard)**			
AN3372-1	6041H204	6106-98-0055	Labinal, LLC
*** AN3381 Canceled 20 Jun 94 (Use MS24179 - For Spares Only)**			
AN3381			
*** MIL-R-6106/1 Canceled 2 Oct 95 (Use MIL-R-83536/10 or /11)**			
MIL-R-6106/1			
*** MIL-R-6106/2 Canceled 2 Oct 95 (Use MIL-R-85356/16 or /17)**			
MIL-R-6106/2			
*** MIL-R-6106/3 Canceled 31 May 95 (Use MIL-PRF-12883/49)**			
MIL-R-6106/3			
*** MIL-R-6106/4 Canceled 28 Nov 94 (Use MIL-PRF-12883/50)**			
MIL-R-6106/4			

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
*** MIL-R-6106/5 Canceled 28 Nov 94 (Use MIL-PRF-12883/51)**			
MIL-R-6106/5			
*** MIL-R-6106/6 Canceled 30 Jun 89 (Use MIL-R-83536/15, /16, or /17)**			
MIL-R-6106/6			
*** MIL-R-6106/7 Canceled 30 Jun 89 (Use MIL-R-83536/9, /10 or /11)**			
MIL-R-6106/7			
*** MIL-R-6106/8 Canceled 11 Aug 97 (Use MIL-R-83536/25 and /26)**			
MIL-R-6106/8			
M6106/9-001	SM15CWD1	6106-95-0241	Labinal, LLC
M6106/9-002	SM15CXD1	6106-95-0241	Labinal, LLC
M6106/9-003	SM15CWA4	6106-97-0024	Labinal, LLC
M6106/9-004	SM15CXA10	6106-97-0024	Labinal, LLC
M6106/10-001	SM15AWD1	6106-95-0242	Labinal, LLC
M6106/10-002	SM15AXD1	6106-95-0242	Labinal, LLC
M6106/10-005	SM15AWD3	6106-95-0242	Labinal, LLC
M6106/11-001	SM15BWD1	6106-95-0243	Labinal, LLC
M6106/11-002	SM15BXD1	6106-95-0243	Labinal, LLC
*** M6106/12 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
M6106/12-001	KDL-D2A-002	6106-98-0190	Leach International North America
M6106/12-002	KDL-D4A-002	6106-98-0190	Leach International North America
M6106/13-001	KD-D2A-002	6106-98-0132	Leach International North America
M6106/13-002	KD-D4A-002	KDA-D2F-002	Leach International North America
M6106/13-003	KDA-D2F-002	6106-98-0132	Leach International North America
M6106/13-004	KDA-E4F-002	6106-98-0132	Leach International North America
M6106/13-005	KD-D1A-102	6106-98-0132	Leach International North America
M6106/13-006	KD-J1A-102	6106-98-0132	Leach International North America
M6106/13-007	KD-D2N-103	6106-98-0132	Leach International North America
M6106/13-008	KD-D4N-103	6106-98-0132	Leach International North America
M6106/13-009	KD-J2A-002	6106-98-0132	Leach International North America
M6106/13-010	KD-A1A-002	6106-98-0132	Leach International North America
M6106/13-011	KD-A4A-002	6106-98-0132	Leach International North America
M6106/13-012	KDA-A1F-002	6106-98-0132	Leach International North America
M6106/13-013	KDA-A4F-002	6106-98-0132	Leach International North America
M6106/13-014	KD-A1N-103	6106-98-0132	Leach International North America
M6106/13-015	KD-A4N-103	6106-98-0132	Leach International North America
M6106/13-016	KD-D1N-103	6106-98-0132	Leach International North America
M6106/13-017	KD-D1N-104	6106-98-0132	Leach International North America
M6106/13-018	KD-J2N-103	6106-98-0132	Leach International North America
M6106/15-001	D50-1005	6106-96-0016(1)	DRI Relays, Inc.
M6106/15-002	DS50-1006	6106-96-0017(2)	DRI Relays, Inc.
*** MIL-R-6106/16 Canceled 27 Aug 82 (No Superseding Standard)**			
MIL-R-6106/16			
*** MIL-R-6106/17 Canceled 27 Aug 82 (No Superseding Standard)**			
MIL-R-6106/17			
*** MIL-R-6106/18 Canceled 27 Aug 82 (No Superseding Standard)**			
MIL-R-6106/18			
M6106/19-005	E1250402CTER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-006	E1250402ATER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-007	E1250402BGER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-008	E1250403CTER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-009	E1250403ATER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-010	E1250402CT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-011	E1250402AT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M6106/19-012	E1250402BG	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-013	E1250403CT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-014	E1250402AT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-015	ES1250402CT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-016	ES1250402AT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-017	ES1250402BG	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-018	ES1250403CT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-019	ES1250403AT	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-020	ES1250402CTER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-021	ES1250402ATER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-022	ES1250402BGER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-023	ES1250402CTER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-024	ES1250402ATER	6106-2219-08; 6106-98-0221	DRI Relays, Inc.
M6106/19-003	JS-D2A-002	6106-97-0127	Leach International North America
M6106/19-004	JS-D4A-002	6106-97-0127	Leach International North America
M6106/19-005	JC-D1A-102	6106-97-0127	Leach International North America
M6106/19-006	JC-D2A-102	6106-97-0127	Leach International North America
M6106/19-007	JC-D4A-102	6106-97-0127	Leach International North America
M6106/19-008	JC-J1A-102	6106-97-0127	Leach International North America
M6106/19-009	JC-J2A-102	6106-97-0127	Leach International North America
M6106/19-010	JC-D1A-003	6106-97-0127	Leach International North America
M6106/19-011	JC-D2A-003	6106-97-0127	Leach International North America
M6106/19-012	JC-D4A-003	6106-97-0127	Leach International North America
M6106/19-013	JC-J1A-003	6106-97-0127	Leach International North America
M6106/19-014	JC-J2A-003	6106-97-0127	Leach International North America
M6106/19-015	JC-D1N-103	6106-97-0127	Leach International North America
M6106/19-016	JC-D2N-103	6106-97-0127	Leach International North America
M6106/19-017	JC-D4N-103	6106-97-0127	Leach International North America
M6106/19-018	JC-J1N-103	6106-97-0127	Leach International North America
M6106/19-019	JC-J2N-103	6106-97-0127	Leach International North America
M6106/19-020	JC-D1N-104	6106-97-0127	Leach International North America
M6106/19-021	JC-D2N-104	6106-97-0127	Leach International North America
M6106/19-022	JC-D4N-104	6106-97-0127	Leach International North America
M6106/19-023	JC-J1N-104	6106-97-0127	Leach International North America
M6106/19-024	JC-J2N-104	6106-97-0127	Leach International North America
M6106/19-025	JS-J2A-102	6106-97-0127	Leach International North America
M6106/19-003	BR250-320B2-28V-003	6106-97-0205	Microsemi Corp.
M6106/19-004	BR250-320A2-28V-004	6106-97-0205	Microsemi Corp.
M6106/19-005	BR250-320C2-28V-005	6106-97-0205	Microsemi Corp.
M6106/19-006	BR250-320B2-28V-006	6106-97-0205	Microsemi Corp.
M6106/19-007	BR250-320A2-28V-007	6106-97-0205	Microsemi Corp.
M6106/19-008	BR250-320C3-28V-008	6106-97-0205	Microsemi Corp.
M6106/19-009	BR250-320B3-28V-009	6106-97-0205	Microsemi Corp.
M6106/19-010	BR250-320C2-28V-010	6106-97-0205	Microsemi Corp.
M6106/19-011	BR250-320B2-28V-011	6106-97-0205	Microsemi Corp.
M6106/19-012	BR250-320A2-28V-012	6106-97-0205	Microsemi Corp.
M6106/19-013	BR250-320C3-28V-013	6106-97-0205	Microsemi Corp.
M6106/19-014	BR250-320B3-28V-014	6106-97-0205	Microsemi Corp.
M6106/19-015	BR250D-320C2-28V-015	6106-97-0205	Microsemi Corp.
M6106/19-016	BR250D-320B2-28V-016	6106-97-0205	Microsemi Corp.
M6106/19-017	BR250D-320A2-28V-017	6106-97-0205	Microsemi Corp.
M6106/19-018	BR250D-320C3-28V-018	6106-97-0205	Microsemi Corp.
M6106/19-019	BR250D-320B3-28V-019	6106-97-0205	Microsemi Corp.
M6106/19-020	BR250D-320C2-28V-020	6106-97-0205	Microsemi Corp.
M6106/19-021	BR250D-320B2-28V-021	6106-97-0205	Microsemi Corp.
M6106/19-022	BR250D-320A2-28V-022	6106-97-0205	Microsemi Corp.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M6106/19-023	BR250D-320C3-28V-023	6106-97-0205	Microsemi Corp.
M6106/19-024	BR250D-320B3-28V-024	6106-97-0205	Microsemi Corp.
M6106/19-025	BR250-320B3-28V-025	6106-97-0205	Microsemi Corp.
M6106/19-005	E1250402CTER	6106-2219-08; 6106-98-0221	REL
M6106/19-006	E1250402ATER	6106-2219-08; 6106-98-0221	REL
M6106/19-007	E1250402BGER	6106-2219-08; 6106-98-0221	REL
M6106/19-008	E1250403CTER	6106-2219-08; 6106-98-0221	REL
M6106/19-009	E1250403ATER	6106-2219-08; 6106-98-0221	REL
M6106/19-010	E1250402CT	6106-2219-08; 6106-98-0221	REL
M6106/19-011	E1250402AT	6106-2219-08; 6106-98-0221	REL
M6106/19-012	E1250402BG	6106-2219-08; 6106-98-0221	REL
M6106/19-013	E1250403CT	6106-2219-08; 6106-98-0221	REL
M6106/19-014	E1250402AT	6106-2219-08; 6106-98-0221	REL
M6106/19-015	ES1250402CT	6106-2219-08; 6106-98-0221	REL
M6106/19-016	ES1250402AT	6106-2219-08; 6106-98-0221	REL
M6106/19-017	ES1250402BG	6106-2219-08; 6106-98-0221	REL
M6106/19-018	ES1250403CT	6106-2219-08; 6106-98-0221	REL
M6106/19-019	ES1250403AT	6106-2219-08; 6106-98-0221	REL
M6106/19-020	ES1250402CTER	6106-2219-08; 6106-98-0221	REL
M6106/19-021	ES1250402ATER	6106-2219-08; 6106-98-0221	REL
M6106/19-022	ES1250402BGER	6106-2219-08; 6106-98-0221	REL
M6106/19-023	ES1250402CTER	6106-2219-08; 6106-98-0221	REL
M6106/19-024	ES1250402ATER	6106-2219-08; 6106-98-0221	REL
M6106/19-003	FCA-125-3	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-004	FCA-125-4	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-005	FCA-125-5	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-006	FCA-125-6	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-007	FCA-125-7	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-008	FCA-125-8	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-009	FCA-125-9	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-010	FCA-125-10	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-011	FCA-125-11	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-012	FCA-125-12	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-013	FCA-125-13	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-014	FCA-125-14	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-015	FCA-125-15	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-016	FCA-125-16	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-017	FCA-125-17	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-018	FCA-125-18	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-019	FCA-125-19	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-020	FCA-125-20	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-021	FCA-125-21	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-022	FCA-125-22	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-023	FCA-125-23	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-024	FCA-125-24	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)
M6106/19-025	FCA-125-25	6106-1565-06; 83536-986-04	Tyco - HPG (Fairview, NC)

*** M6106/20 Inactive For New Design After 15 Nov 02 (No Superseding Standard)**

M6106/20-001	JCL-D2A-002	6106-97-0191	Leach International North America
M6106/20-002	JCL-D4A-002	6106-97-0191	Leach International North America
M6106/20-003	JCL-J2A-002	6106-97-0191	Leach International North America

*** MIL-R-6106/21 Canceled 2 Oct 95 (Use MIL-R-83536/2)**

MIL-R-6106/21

*** MIL-R-6106/22 Canceled 2 Oct 95 (Use MIL-R-83536/6)**

MIL-R-6106/22

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
*** MIL-R-6106/23 Canceled 28 Nov 94 (Use MIL-PRF-12883/52)**			
MIL-R-6106/23			
*** MIL-R-6106/24 Canceled 2 Oct 95 (Use MIL-R-12883/22)**			
MIL-R-6106/24			
*** MIL-R-6106/25 Canceled 28 Nov 94 (Use MIL-PRF-12883/53)**			
MIL-R-6106/25			
M6106/26-001	H-A9A-042	6106-96-0119	Leach International North America
*** MIL-R-6106/27 Canceled 2 Oct 95 (Use MIL-R-83536/1 or /2)**			
MIL-R-6106/27			
*** MIL-R-6106/28 Canceled 2 Oct 95 (Use MIL-R-83536/5 or /6)**			
MIL-R-6106/28			
*** MIL-R-6106/29 Canceled 2 Oct 95 (Use MIL-R-83536/21 or /22)**			
MIL-R-6106/29			
M6106/31-001	CNA040301	6106-98-0108	Precision Connenctor Designs
M6106/32-001	CNA081501	6106-98-0109	Precision Connenctor Designs
M6106/33-040	AJ-A4A-153	6106-96-0123	Leach International North America
M6106/33-041	AJ-A4NA-154	6106-96-0123	Leach International North America
M6106/33-042	AJ-A4NA-155	6106/96-0123	Leach International North America
M6106/33-043	AJ-A4A-156	6106-96-0123	Leach International North America
M6106/33-044	AJ-B8NA-157	9106-96-0123	Leach International North America
M6106/33-045	AJ-B8A-158	6106-96-0123	Leach International North America
M6106/33-046	AJ-A2NA-159	6106-96-0123	Leach International North America
M6106/33-047	AJ-A3NA-160	6106-96-0123	Leach International North America
M6106/33-048	AJ-A2A-161	6106-96-0123	Leach International North America
M6106/33-049	AJ-A3A-162	6106-96-0123	Leach International North America
M6106/33-050	AJ-A8NA-163	6106-96-0123	Leach International North America
M6106/33-051	AJ-A8A-164	6106-96-0123	Leach International North America
M6106/33-052	AJ-B9NA-165	6106-96-0123	Leach International North America
M6106/33-053	AJ-B9A-166	6106-96-0123	Leach International North America
M6106/33-054	AJ-A9NA-167	6106-96-0123	Leach International North America
M6106/33-055	AJ-A9A-168	6106-96-0123	Leach International North America
M6106/33-056	AJ-B7NA-169	6106-96-0123	Leach International North America
M6106/33-057	AJ-B7A-170	6106-96-0123	Leach International North America
M6106/33-058	AJ-A7NA-171	6106-96-0123	Leach International North America
M6106/33-059	AJ-A7A-172	6106-96-0123	Leach International North America
M6106/33-060	AJ-B8N-173	6106-96-0123	Leach International North America
M6106/33-061	AJ-B9N-174	6106-96-0123	Leach International North America
M6106/33-062	AJ-B7N-175	6106-96-0123	Leach International North America
M6106/33-063	AJ-A4N-176	6106-96-0123	Leach International North America
M6106/33-064	AJ-A4N-177	6106-96-0123	Leach International North America
M6106/33-065	AJ-B4A-178	6106-96-0123	Leach International North America
M6106/33-066	AJ-B4NA-179	6106-96-0123	Leach International North America
M6106/33-067	AJ-B4N-180	6106-96-0123	Leach International North America
M6106/33-068	AJ-A8N-181	6106-96-0123	Leach International North America
M6106/33-069	AJ-A2N-182	6106-96-0123	Leach International North America
M6106/33-070	AJ-B2A-183	6106-96-0123	Leach International North America
M6106/33-071	AJ-B2NA-184	6106-96-0123	Leach International North America
M6106/33-072	AJ-B2N-185	6106-96-0123	Leach International North America
M6106/33-073	AJ-A3N-186	6106-96-0123	Leach International North America
M6106/33-074	AJ-B3A-187	6106-96-0123	Leach International North America
M6106/33-075	AJ-B3NA-188	6106-96-0123	Leach International North America
M6106/33-076	AJ-B3N-189	6106-96-0123	Leach International North America
M6106/33-077	AJ-A9N-190	6106-96-0123	Leach International North America
M6106/33-078	AJ-A7N-191	6106-96-0123	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
*** MIL-R-6106/36 Canceled 2 Oct 95 (Use MIL-R-83536/13)**			
MIL-R-6106/36			
*** MIL-R-6106/37 Canceled 2 Oct 95 (Use MIL-R-83536/19)**			
MIL-R-6106/37			
M6106/38-001	XL-D2A-003	6106-96-0116	Leach International North America
M6106/38-002	XL-D4A-003	6106-96-0116	Leach International North America
M6106/38-003	XL-D1A-003	6106-96-0116	Leach International North America
M6106/38-004	XL-J2A-003	6106-96-0116	Leach International North America
M6106/38-005	XL-A1A-003	6106-96-0116	Leach International North America
M6106/38-006	XL-J1A-003	6106-96-0116	Leach International North America
M6106/39-001	YL-D2A-003	6106-96-0102	Leach International North America
M6106/39-002	YL-D4A-003	6106-96-0102	Leach International North America
M6106/39-003	YL-D1A-003	6106-96-0102	Leach International North America
M6106/39-004	YL-J2A-003	6106-96-0102	Leach International North America
M6106/39-005	YL-A1A-003	6106-96-0102	Leach International North America
M6106/39-006	YL-J1A-003	6106-96-0102	Leach International North America
*** M6106/40 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
M6106/40-001	YCL-D2A-003	6106-97-0199	Leach International North America
M6106/40-002	YCL-D4A-003	6106-97-0199	Leach International North America
M6106/40-003	YCL-D1A-003	6106-97-0199	Leach International North America
M6106/40-004	YCL-J2A-003	6106-97-0199	Leach International North America
M6106/40-005	YCL-A1A-003	6106-97-0199	Leach International North America
M6106/40-006	YCL-J1A-003	6106-97-0199	Leach International North America
*** M6106/41 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
M6106/41-001	9339-10223	6106-96-0007	Leach International North America
M6106/41-002	9339-10224	6106-96-0007	Leach International North America
M6106/43-001	H-A9N-063	6106-96-0120	Leach International North America
*** M6106/41 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
M6106/43-002	H-A9A-060	6106-96-0120	Leach International North America
M6106/48-001	SM100H1	6106-98-0208	Labinal, LLC
M6106/48-002	SM100H15	6106-022-01	Labinal, LLC
*** MIL-R-6106/50 Canceled 27 Dec 96 (Use MIL-R-83536/12, /13 and /14)**			
MIL-R-6106/50			
*** MIL-R-6106/51 Canceled 27 Dec 96 (Use MIL-R-83536/18, /19 and /20)**			
MIL-R-6106/51			
MS24140-D1	6042H155, 6042H155-2	6106-3096-11; 6106-97-0043	Labinal, LLC
MS24140-D2	6042H156, 6042H156-2	6106-3096-11; 6106-97-0043	Labinal, LLC
MS24141-D1	6042H159, 6042H159-2	6106-3096-11; 6106-97-0044	Labinal, LLC
MS24141-D2	6042H160, 6042H160-2	6106-3096-11; 6106-97-0044	Labinal, LLC
MS24142-D1	6042H151, 6042H151-2	6106-3096-11; 6106-96-0175	Labinal, LLC
MS24142-D2	6042H152, 6042H151-2	6106-3096-11; 6106-96-0175	Labinal, LLC
MS24143-A3	6042H290, 6042H290-2	6106-3096-11; 6106-97-0046	Labinal, LLC
MS24143-A4	6042H291, 6042H291-2	6106-3096-11; 6106-97-0046	Labinal, LLC
MS24143-D1	6042H141, 6042H141-2	6106-3096-11; 6106-97-0046	Labinal, LLC
MS24143-D2	6042H142, 6042H142-2	6106-3096-11; 6106-97-0046	Labinal, LLC
MS24143-D3	6042H110, 6042H110-2	6106-3096-11; 6106-97-0046	Labinal, LLC
*** MS24149-A1 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS24149-A1	9330-4027	6106-97-0064	Leach International North America
*** MS24149-D1 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS24149-D1	9330-4026	6106-97-0064	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
*** MS24152-D1 Inactive For New Design After 27 May 1994 (No Superseding Standard)**			
MS24152-D1	9565H29	6106-98-0049	Labinal, LLC
MS24166-D1	6041H200	6106-98-0017	Labinal, LLC
MS24166-D2	6041H201	6106-98-0017	Labinal, LLC
MS24166-D2	7064-238	6106-034-00, 6106-185-02	Leach International Europe
MS24166-D1	7064-4653	6106-034-00; 6106-185-02	Leach International Europe S.A.
MS24166-D1	7064-4653	6106-3176-11	Leach International North America
MS24166-D2	7064-238	6106-3176-11	Leach International North America
MS24168-A3	6042H289, 6042H289-2	6106-3096-11; 6106-96-0244	Labinal, LLC
MS24168-A4	6042H286, 6042H286-2	6106-3096-11; 6106-96-0244	Labinal, LLC
MS24168-D1	6042H161, 6042H161-2	6106-3096-11; 6106-96-0244	Labinal, LLC
MS24168-D2	6042H162, 6042H162-2	6106-3096-11; 6106-96-0244	Labinal, LLC
MS24171-D1	6041H215	6106-98-0018	Labinal, LLC
MS24171-D2	6041H202	6106-98-0018	Labinal, LLC
MS24171-D1	7246-4654	6106-214-02	Leach International Europe
MS24171-D2	7246-283	6106-214-02	Leach International Europe
MS24171-D1	7246-4654	6106-3838-13	Leach International North America
MS24171-D2	7246-238	6106-3838-13	Leach International North America
MS24172-D1	6041H216	6106-98-0019	Labinal, LLC
MS24172-D2	6041H203	6106-98-0019	Labinal, LLC
MS24172-D1	7264-4655	6106-214-02	Leach International Europe
MS24178-D1	6041H219	6106-97-0020	Labinal, LLC
MS24178-D1	7064-4656	6106-185-02	Leach International Europe
MS24179-D1	6041H218	6106-98-0168	Labinal, LLC
MS24179-D2	6041H206	6106-98-0168	Labinal, LLC
MS24179-D1	7401-9444	6106-215-02	Leach International Europe
MS24182-D1	6042H166, 6042H166-2	6106-3096-11; 6106-96-0176	Labinal, LLC
MS24183-D1	6042H167, 6042H167-2	6106-3096-11; 6106-96-0243	Labinal, LLC
MS24184-D1	6042H153, 6042H153-2	6106-3096-11; 6106-96-0242	Labinal, LLC
MS24184-D2	6042H154, 6042H154-2	6106-3096-11; 6106-96-0242	Labinal, LLC
MS24185-D1	C400-4	6106-2267-08	313 Aerospace
MS24185-D1	6041H217	6106-98-0044	Labinal, LLC
MS24185-D2	6041H205	6106-98-0044	Labinal, LLC
MS24185-D1	7401-4658	6106-215-02	Leach International Europe
MS24185-D2	7401-C	6106-215-02	Leach International Europe
MS24187-D1	6041H220	6106-98-0045	Labinal, LLC
MS24187-D2	6041H230	6106-98-0045	Labinal, LLC
MS24187-D1	7064-423	6106-391-03	Leach International Europe
MS24187-D2	7064-424	6106-391-03	Leach International Europe
MS24192-D1	9565H2	6106-95-0186	Labinal, LLC
MS24193-D1	9565H94	6106-95-0187	Labinal, LLC
MS24376-A1	6042-H147, 6042H147-2	6106-3096-11; 6106-97-0098	Labinal, LLC
MS24376-A2	6042H148, 6042H148-2	6106-3096-11; 6106-97-0098	Labinal, LLC
MS24376-A3	6042H288, 6042H288-2	6106-3096-11; 6106-97-0098	Labinal, LLC
MS24376-A4	6042H285, 6042H285-2	6106-3096-11; 6106-97-0098	Labinal, LLC
MS24376-D1	6042H145, 6042H145-2	6106-3096-11; 6106-97-0098	Labinal, LLC

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
MS24376-D2	6042H146, 6042H146-2	6106-3096-11; 6106-97-0098	Labinal, LLC
MS24568-D1	9274-6205	6106-97-0110	Leach International North America
*** MS24568-A1 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS24568-A1	9274-6667	6106-97-0110	Leach International North America
*** MS24568-A2 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS24568-A2	9274-10291	6106-97-0110	Leach International North America
*** MS25024 Inactive for New Design After 11 Dec 64 (Use MS24568-D1)**			
MS25024-2	A410-157763-00	6106-97-0128	Guardian Electric Manufacturing Company
*** MS25030 Inactive for New Design After 28 Apr 95 (No Superseding Standard)**			
MS25030-D1B	6046H51	6106-98-0050	Labinal, LLC
*** MS25031 Inactive for New Design After 29 Sep 90 (No Superseding Standard)**			
MS25031-D1B	6046H53	6106-98-0051	Labinal, LLC
*** MS25032 Inactive for New Design After 29 Sep 90 (No Superseding Standard)**			
MS25032-D1	6046H46	6106-98-0052	Labinal, LLC
*** MS25033 Inactive for New Design After 18 Jan 57 (No Superseding Standard)**			
MS25033-1	A419-054978-01	6106-97-0129	Guardian Electric Manufacturing Company
*** MS25035 Inactive for New Design After 14 Nov 79 (No Superseding Standard)**			
MS25035-1	A410-154555-00	6106-97-0130	Guardian Electric Manufacturing Company
MS25267-D1	9220-4185	6106-96-0092	Leach International North America
*** MS25267 Inactive for New Design After 29 Feb 02 (No Superseding Standard)**			
MS25267-A1	9220-4186	6106-96-0092	Leach International North America
MS25268-D1	9220-4191	6106-98-0032	Leach International North America
*** MS25268 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25268-A1	9220-4192	6106-98-0032	Leach International North America
MS25269-D1	9226-4187	6106-98-0086	Leach International North America
*** MS25269 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25269-A1	9226-4188	6106-98-0086	Leach International North America
*** MS25270 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25270-A1	9226-4190	6106-98-0087	Leach International North America
MS25270-D1	9226-4189	6106-98-0087	Leach International North America
*** MS25271-A1 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS25271-A1	9224-4076	6106-96-0050	Leach International North America
*** MS25271-D1 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS25271-D1	9224-4091	6106-96-0050	Leach International North America
*** MS25272 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25272-A1	9224-4194	6106-98-0036	Leach International North America
MS25272-D1	9224-4193	6106-98-0036	Leach International North America
*** MS25273 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25273-A1	9227-4085	6106-96-0004	Leach International North America
MS25273-A2	9227-10410	6106-96-0004	Leach International North America
MS25273-D1	9227-4084	6106-96-0004	Leach International North America
*** MS25321 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/27)**			
MS25321-A2	9229-4463	6106-98-0021	Leach International North America
MS25321-A3	9229-8986	6106-98-0021	Leach International North America
MS25321-D2	9229-4459	6106-98-0021	Leach International North America
MS25323-D2	9227-4444	6106-98-0026	Leach International North America
*** MS25323 Inactive for New Design After 5 Jun 87 (Use MS27401)**			
MS25323-A2	9227-4449	6106-98-0026	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
MS25325-A2	9220-8985	6106-98-0033	Leach International North America
MS25325-D1	9220-4402	6106-98-0033	Leach International North America
*** MS25325 Inactive for New Design After 5 Jun 87 (Use MIL-R-6106/28)**			
MS25325-A1	9220-4406	6106-98-0033	Leach International North America
*** MS25327 Inactive for New Design After 5 Jun 87 (Use MS27400)**			
MS25327-A1	9224-4488	6106-98-0037	Leach International North America
MS25327-D1	9224-4487	6106-98-0037	Leach International North America
*** MS25329 Inactive for New Design After 30 Sep 87 (No Superseding Standard)**			
MS25329-A1	9226-4433	6106-98-0088	Leach International North America
MS25329-D1	9226-4429	6106-98-0088	Leach International North America
MS25395-A1	9229-4461	6106-96-0006	Leach International North America
MS25395-A3	9229-10007	6106-96-0006	Leach International North America
*** MS25395-A2 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25395-A2	9229-4512	6106-96-0006	Leach International North America
*** MS25395-A4 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25395-A4	9229-10008	6106-96-0006	Leach International North America
*** MS25395-D1 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS25395-D1	9229-4457	6106-96-0006	Leach International North America
*** MS25395-D2 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25395-D2	9229-4511	6106-96-0006	Leach International North America
MS25455-D1	9235-4842	6106-98-0082	Leach International North America
*** MS25455 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25455-A1	9235-4843	6106-98-0082	Leach International North America
*** MS25457 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25457-A1	9237-4846	6106-98-0023	Leach International North America
MS25457-D1	9237-4845	6106-98-0023	Leach International North America
*** MS25459 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25459-A1	9228-4622	6106-98-0089	Leach International North America
MS25459-D1	9228-4424	6106-98-0089	Leach International North America
*** MS25461 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25461-A1	9225-4616	6106-98-0157	Leach International North America
MS25461-D1	9225-4416	6106-98-0157	Leach International North America
*** MS25463 Inactive for New Design After 30 Jun 87 (No Superseding Standard)**			
MS25463-A1	9223-4834	6106-97-0197	Leach International North America
MS25463-D1	9223-4833	6106-97-0197	Leach International North America
*** MS25465 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25465-A1	9235-4718	6106-98-0083	Leach International North America
MS25465-D1	9235-4717	6106-98-0083	Leach International North America
*** MS25466 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS25466-A1	9237-5125	6106-98-0024	Leach International North America
MS25466-D1	9237-5124	6106-98-0024	Leach International North America
*** MS25467 Inactive for New Design After 15 Oct 99 (No Superseding Standard)**			
MS25467-A1	9228-4531	6106-98-0090	Leach International North America
MS25467-D1	9228-4530	6106-98-0090	Leach International North America
*** MS25468-A1 Inactive for New Design After 29 Feb 00 (No Superseding Standard)**			
MS25468-A1	9225-4494	6106-96-0137	Leach International North America
*** MS25468-AD1 Inactive for New Design After 29 Sep 87 (No Superseding Standard)**			
MS25468-AD1	9225-8756	6106-96-0137	Leach International North America
*** MS25468-D1 Inactive for New Design After 29 Feb 00 (No Superseding Standard)**			
MS25468-D1	9225-4241	6106-96-0137	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
*** MS25469-A1 Inactive for New Design After 30 Sep 87 (No Superseding Standard)**			
MS25469-A1	9223-5129	6106-97-0198	Leach International North America
*** MS25469-D1 Inactive for New Design After 14 Feb 01 (No Superseding Standard)**			
MS25469-D1	9223-4692	6106-97-0198	Leach International North America
*** MS25917 Inactive for New Design After 2 Mar 87 (No Superseding Standard)**			
MS25917-1	AE108-020-99	6106-2154-08	DARE Electronics, Inc.
MS25917-1	9220-3474	6106-98-0034	Leach International North America
MS25917-2	9220-3475	6106-98-0034	Leach International North America
*** MS25918 Inactive for New Design After 14 Aug 81 (No Superseding Standard)**			
MS25918-D1	9226-3478	6106-98-0091	Leach International North America
MS25918-D2	9226-3476	6106-98-0091	Leach International North America
MS27222-4	9124-1Z-C7D3-002	6106-98-0133	Leach International North America
MS27222-5	9124-10278	6106-98-0133	Leach International North America
MS27222-6	9124-10279	6106-98-0133	Leach International North America
MS27222-7	9124-10280	6106-98-0133	Leach International North America
*** MS27222 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS27222-1	9124-C7C4-002	6106-98-0133	Leach International North America
MS27222-2	9124-1Z-C7C4-002	6106-98-0133	Leach International North America
MS27222-3	9124-C7D3-002	6106-98-0133	Leach International North America
MS27242-1	6042H181	6106-98-0047	Labinal, LLC
MS27242-2	6042H182	6106-98-0047	Labinal, LLC
MS27243-1	49-2661	6106-98-0053	Labinal, LLC
MS27243-2	49-2665	6106-98-0053	Labinal, LLC
MS27243-3	49-2667	6106-98-0053	Labinal, LLC
MS27243-4	49-2670	6106-98-0053	Labinal, LLC
MS27243-5	49-2672	6106-98-0053	Labinal, LLC
MS27243-6	49-3179	6106-98-0053	Labinal, LLC
MS27245-2	B07D919BC4-0054	6106-98-0184	Tyco - CII Technologies
MS27245-3	B07D112BC4-0203	6106-98-0184	Tyco - CII Technologies
MS27245-4	B07D919BC4-0204	6106-98-0184	Tyco - CII Technologies
MS27245-5	B07E932BC4-0262	6106-98-0184	Tyco - CII Technologies
MS27245-6	B07D932BC4-0263	6106-98-0184	Tyco - CII Technologies
*** MS27245 Inactive for New Design After 5 Jun 87 (No Superseding Standards)**			
MS27245-1	B07D112BC4-0007	6106-98-0184	Tyco - CII Technologies
MS27247-2	B07D11BC4-0202	6106-98-0185	Tyco - CII Technologies
MS27247-4	B07D915BC4-0264	6106-98-0185	Tyco - CII Technologies
MS27247-5	B07E915BC4-0265	6106-98-0185	Tyco - CII Technologies
*** MS27247 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS27247-1	B07D111BC4-0006	6106-98-0185	Tyco - CII Technologies
MS27254-2	A410-161171-02	6106-97-0131	Guardian Electric Manufacturing Company
*** MS27254 Inactive for New Design After 5 Jun 87 (No Superseding Standards)**			
MS27254-1	A410-161171-01	6106-97-0131	Guardian Electric Manufacturing Company
*** MS27255 Inactive for New Design After 5 Jun 87 (No Superseding Standard)**			
MS27255-1	A410-161916-00	6106-97-0132	Guardian Electric Manufacturing Company
MS27255-2	A410-161059-03	6106-97-0132	Guardian Electric Manufacturing Company
MS27255-3	A410-161916-03	6106-97-0132	Guardian Electric Manufacturing Company
MS27255-4	A410-161059-04	6106-97-0132	Guardian Electric Manufacturing Company
*** MS27400 Canceled 2 Oct 95 (Use MIL-R-83536/15, /16 or MIL-PRF-83536/17)**			
MS27400			
*** MS27401 Canceled 2 Oct 95 (Use MIL-R-83536/9, /10 or/11)**			
MS27401			

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
MS27418-1B	9324-8214	6106-96-0008	Leach International North America
MS27418-1C	9324-10126	6106-96-0008	Leach International North America
MS27418-1D	9324-10314	6106-96-0008	Leach International North America
MS27418-2A	9324-8213	6106-96-0008	Leach International North America
MS27418-2B	9324-7424	6106-96-0008	Leach International North America
MS27418-2C	9324-10128	6106-96-0008	Leach International North America
MS27418-2D	9324-10315	6106-96-0008	Leach International North America
*** MS27418 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS27418-1A	9324-8215	6106-96-0008	Leach International North America
MS27418-1A	FC-325-1	6106-4619-16	Tyco - CII Technologies
MS27418-1B	FC-325-2	6106-4619-16	Tyco - CII Technologies
MS27418-1C	FC-325-3	6106-4619-16	Tyco - CII Technologies
MS27418-1D	FC-325-7	6106-4619-16	Tyco - CII Technologies
MS27418-2A	FC-325-4	6106-4619-16	Tyco - CII Technologies
MS27418-2B	FC-325-5	6106-4619-16	Tyco - CII Technologies
MS27418-2C	FC-325-6	6106-4619-16	Tyco - CII Technologies
MS27418-2D	FC-325-8	6106-4619-16	Tyco - CII Technologies
MS27706-2B	9325-8390	6106-98-0027	Leach International North America
*** MS27706 Inactive for New Design After 8 Sep 95 (No Superseding Standard)**			
MS27706-1B	9325-8398	6106-98-0027	Leach International North America
MS27709-4	K-X2A-062	6106-98-0191	Leach International North America
MS27714-2	A419-062426-03	6106-97-0133	Guardian Electric Manufacturing Company
*** MS27714 Inactive for New Design After 27 Mar 95 (No Superseding Standard)**			
MS27714-1	A419-062426-00	6106-97-0133	Guardian Electric Manufacturing Company
MS27715-2	A419-063394-03	6106-97-0134	Guardian Electric Manufacturing Company
*** MS27715 Inactive for New Design After 27 Mar 95 (No Superseding Standard)**			
MS27715-1	A419-062470-00	6106-97-0134	Guardian Electric Manufacturing Company
MS27742-1	KCL-D2A-002	6106-97-0037	Leach International North America
MS27742-2	KCL-D4A-002	6106-97-0037	Leach International North America
MS27742-1	EL3250402AT	6106-149-00	REL
MS27742-2	EL3250402BG	6106-149-00	REL
*** MS27744 Canceled 30 Nov 89 (Use MIL-R-83536/12, /13 and /14)**			
MS27744			
*** MS27745 Canceled 30 Nov 89 (Use MIL-R-83536/18, /19 and /20)**			
MS27745			
MS27749-2	HLT-A1A-002	6106-96-0110	Leach International North America
*** MS27749 Inactive for New Design After 15 Nov 02 (No Superseding Standard)**			
MS27749-1	HL-A1A-002	6106-96-0110	Leach International North America
MS27750-1	HC-A1A-002	6106-96-0111	Leach International North America
MS27750-2	HC-A1A-017	6106-96-0111	Leach International North America
MS27751-1	H-A1A-002	6106-96-0121	Leach International North America
MS27751-2	H-A1F-002	6106-96-0121	Leach International North America
MS27751-3	H-A2A-002	6106-96-0121	Leach International North America
MS27751-4	H-A2F-002	6106-96-0121	Leach International North America
MS27751-5	H-A3A-002	6106-96-0121	Leach International North America
MS27751-6	H-A3F-002	6106-96-0121	Leach International North America
MS27751-7	H-A4A-002	6106-96-0121	Leach International North America
MS27751-8	H-A4F-002	6106-96-0121	Leach International North America
MS27751-9	H-A5A-002	6106-96-0121	Leach International North America
MS27751-10	H-A5F-002	6106-96-0121	Leach International North America
MS27751-11	HT-A1A-002	6106-96-0121	Leach International North America

PART LISTINGS			
GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
MS27751-12	HT-A1F-002	6106-96-0121	Leach International North America
MS27751-13	HT-A2A-002	6106-96-0121	Leach International North America
MS27751-14	HT-A2F-002	6106-96-0121	Leach International North America
MS27751-15	HT-A3A-002	6106-96-0121	Leach International North America
MS27751-16	HT-A3F-002	6106-96-0121	Leach International North America
MS27751-17	HT-A4A-002	6106-96-0121	Leach International North America
MS27751-18	HT-A4F-002	6106-96-0121	Leach International North America
MS27751-19	HT-A5A-002	6106-96-0121	Leach International North America
MS27751-20	HT-A5F-002	6106-96-0121	Leach International North America
MS27751-21	H-1AN-059	6106-96-0121	Leach International North America
MS27997-D1	6042H91	6106-98-0048	Labinal, LLC
MS27997-D2	6042H92	6106-98-0048	Labinal, LLC
MS27997-A2	9123-1Z-C7D3-002	6106-98-0134	Leach International North America
MS27997-D1	9123-C7C4-002	6106-98-0134	Leach International North America
MS27997-D2	9123-1Z-C7C4-002	6106-98-0134	Leach International North America
*** MS27997 Inactive for New Design After 14 Feb 01 (No Superseding Standard)**			
MS27997-A1	9123-C7D3-002	6106-98-0134	Leach International North America

Manufacturer: 313 Aerospace (CAGE Code: 3VEK3)
Location: 5305 Bimini Drive, Bradenton, FL 34210-2024, US

Plants:
1. Plant: Same Address as Manufacturer

Manufacturer: Amphenol PSD (CAGE Code: 58982)
Location: 2 Technology Drive, Centennial Park, Peabody, MA 01960-7977, US

Plants:
1. Plant: Same Address as Manufacturer

Manufacturer: DARE Electronics, Inc. (CAGE Code: 55901)
Location: P.O. Box 419, 3245 S. County Road 25A, Troy, OH 45373-9384, US

Plants:
1. Plant: Same Address as Manufacturer

Manufacturer: DRI Relays, Inc. (CAGE Code: 99699)
Location: 60 Commerce Drive, Hauppauge, NY 11788, US

Plants:
1. Plant: Same Address as Manufacturer
2. REL, CAGE Code: FAUB3, 22 Rue Des Chaises, 45142, St. Jean De La Rulle, France

Manufacturer: Guardian Electric Manufacturing Company (CAGE Code: 73949)
Location: 1425 Lake Avenue, Woodstock, IL 60098-8741, US

Plants:
1. Plant: Same Address as Manufacturer

Manufacturer: Labinal, LLC (CAGE Code: 81640)
Location: Labinal Power Systems, 2250 Whitfield Avenue, Sarasota, FL 34243, US

Plants:
1. Plant: Same Address as Manufacturer

Manufacturer: Leach International Europe S.A. (CAGE Code: F0219)
Location: 2 Rue Goethe, F-57430 Sarrable, France

Plants:
1. Leach International Europe (Niort), Zone Industrielle de St. Liguaire, 14 Rue Sainte Claire Deville, Niort F-79000, France

Manufacturer: Leach International North America (CAGE Code: 58657)
Location: North America, P.O. Box 5032, 6900 Orangethorpe Avenue, Buena Park, CA 90620-1351, US

Plants:
1. Plant: Same Address as Manufacturer
2. Plant: Same Address as Manufacturer

Manufacturer: Microsemi Corp. (CAGE Code: 56623)
Location: Space and Power Management Group, 11861 Western Avenue, Garden Grove, CA 92841, US

Plants:
1. Plant: Same Address as Manufacturer

Manufacturer: Tyco - CII Technologies (CAGE Code: 58614)
Location: Communications Instruments Division, P. O. Box 520, Highway 74 East, Fairview, NC 28730, US

Plants:
1. Plant: Same Address as Manufacturer