

**DLA Land and Maritime - VQ**  
**Supplemental Information Sheet for Electronic QPL-15160**

Date: 11/20/2019

**Specification Details:**

Specification: MIL-PRF-15160  
 Title: Fuse, Instrument, Power and Telephone  
 Federal Supply Class (FSC): 5920  
 Conventional: Yes  
 Specification contains quality assurance program: No  
 MIL-STD-790 Established Reliability & High Reliability: No  
 MIL-STD-690 Failure Rate Sampling Plans & Procedures: No  
 Weibull Graded: No  
 Specification contains space level reliability requirements: No  
 Specification allows test optimization: No

**Contact Information:**

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH  
 Primary Qualifying Activity Contact: 614-692-0594, e-mail: vqh.kr@dla.mil  
 Secondary Qualifying Activity Contact: 614-692-9821, e-mail: vqh.jg@dla.mil

**Notes:**

N/A

**Part Configuration:**

|       |                |                |                |               |
|-------|----------------|----------------|----------------|---------------|
| Style | Characteristic | Voltage Rating | Current Rating | Silver Plated |
| F02   | A              | 250 V          | 1 1/2 A        | S             |

**PART LISTINGS**

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE    | SPECIFICATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|------------------------|-------------------------------------------|------------------------------------|---------------------|----------------------------------------|
| F01A250V1/2AS          | F01A250V1/2AS                             | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V6/10AS         | F01A125V6/10AS                            | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V3/4AS          | F01A125V3/4AS                             | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V8/10AS         | F01A125V8/10AS                            | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V1AS            | F01A125V1AS                               | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V1 1/4AS        | F01A125V1-1/4AS                           | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V1 1/2AS        | F01A125V1-1/2AS                           | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V1 6/10AS       | F01A125V1-6/10A                           | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V2AS            | F01A125V2AS                               | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V2 1/2AS        | F01A125V2-1/2AS                           | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V3AS            | F01A125V3AS                               | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V3 2/10AS       | F01A125V3-2/10A                           | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V4AS            | F01A125V4AS                               | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A125V5AS            | F01A125V5AS                               | 15160-138-99; Bussmann Rpt 1276-74 | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V6A              | F01A32V6A                                 | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V6AS             | F01A32V6AS                                | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V7A              | F01A32V7A                                 | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V7AS             | F01A32V7AS                                | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V8A              | F01A32V8A                                 | 15160-706-03                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V8AS             | F01A32V8AS                                | 15160-109-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V10A             | F01A32V10A                                | 15160-706-03                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V10AS            | F01A32V10AS                               | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V15A             | F01A32V15A                                | 15160-706-03                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V15AS            | F01A32V15AS                               | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V20A             | F01A32V20A                                | 15160-706-03                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V20AS            | F01A32V20AS                               | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V25A             | F01A32V25A                                | 15160-706-03                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V25AS            | F01A32V25AS                               | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V30A             | F01A32V30A                                | 15160-706-03                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F01A32V30AS            | F01A32V30AS                               | 15160-019-01                       | /1                  | Eaton Bussmann, LLC (Juarez, Mexico)   |
| F02B250V1/16A          | F02B250V1/16A                             | 15160-706-03                       | /2                  | Eaton Bussmann, LLC (Juarez, Mexico)   |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|---------------------------------------|-----------------------------|-------------------------------------------|
| F02B250V1/10A             | F02B250V1/10A                                   | 15160-706-03                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/8A              | F02B250V1/8A                                    | 15160-706-03                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1/2A              | F02A250V1/2A                                    | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1/2AS             | F02A250V1/2AS                                   | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V6/10A             | F02A250V6/10A                                   | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V6/10AS            | F02A250V6/10AS                                  | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V3/4A              | F02A250V3/4A                                    | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V3/4AS             | F02A250V3/4AS                                   | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1A                | F02A250V1A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1AS               | F02A250V1AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1 1/4A            | F02A250V1-1/4A                                  | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1 1/4AS           | F02A250V1-1/4AS                                 | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1 1/2A            | F02A250V1-1/2A                                  | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1 1/2AS           | F02A250V1-1/2AS                                 | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1 6/10A           | F02A250V1-6/10A                                 | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V1 6/10AS          | F02A250V1-6/10AS                                | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V2A                | F02A250V2A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V2AS               | F02A250V2AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V2 1/2A            | F02A250V2-1/2A                                  | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V2 1/2AS           | F02A250V2-1/2AS                                 | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V3A                | F02A250V3A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V3AS               | F02A250V3AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V4A                | F02A250V4A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V4AS               | F02A250V4AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V5A                | F02A250V5A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V5AS               | F02A250V5AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V6A                | F02A250V6A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A250V6AS               | F02A250V6AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A125V8A                | F02A125V8A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A125V8AS               | F02A125V8AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A125V10A               | F02A125V10A                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A125V10AS              | F02A125V10AS                                    | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V15A                | F02A32V15A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V15AS               | F02A32V15AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V20A                | F02A32V20A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V20AS               | F02A32V20AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V25A                | F02A32V25A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V25AS               | F02A32V25AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V30A                | F02A32V30A                                      | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02A32V30AS               | F02A32V30AS                                     | 15160-139-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/16AS            | F02B250V1/16AS                                  | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/10AS            | F02B250V1/10AS                                  | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/8AS             | F02B250V1/8AS                                   | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V15/100A           | F02B250V15/100A                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V15/100AS          | F02B250V15/100AS                                | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2/10A             | F02B250V2/10A                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2/10AS            | F02B250V2/10AS                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/4A              | F02B250V1/4A                                    | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/4AS             | F02B250V1/4AS                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3/10A             | F02B250V3/10A                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3/10AS            | F02B250V3/10AS                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3/8A              | F02B250V3/8A                                    | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3/8AS             | F02B250V3/8AS                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/2A              | F02B250V1/2A                                    | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1/2AS             | F02B250V1/2AS                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V6/10A             | F02B250V6/10A                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|---------------------------------------|-----------------------------|-------------------------------------------|
| F02B250V6/10AS            | F02B250V6/10AS                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V7/10A             | F02B250V7/10A                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V7/10AS            | F02B250V7/10AS                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3/4A              | F02B250V3/4A                                    | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3/4AS             | F02B250V3/4AS                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V8/10A             | F02B250V8/10A                                   | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V8/10AS            | F02B250V8/10AS                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1A                | F02B250V1A                                      | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1AS               | F02B250V1AS                                     | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1 1/4A            | F02B250V1-1/4A                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1 1/4AS           | F02B250V1-1/4AS                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1 1/2A            | F02B250V1-1/2A                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1 1/2AS           | F02B250V1-1/2AS                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1 6/10A           | F02B250V1-6/10A                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V1 6/10AS          | F02B250V1-6/10AS                                | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2A                | F02B250V2A                                      | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2AS               | F02B250V2AS                                     | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2 1/2A            | F02B250V2-1/2A                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2 1/2AS           | F02B250V2-1/2AS                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2 8/10A           | F02B250V2-8/10A                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V2 8/10AS          | F02B250V2-8/10AS                                | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3A                | F02B250V3A                                      | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B250V3AS               | F02B250V3AS                                     | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V4A                | F02B125V4A                                      | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V4AS               | F02B125V4AS                                     | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V5A                | F02B125V5A                                      | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V5AS               | F02B125V5AS                                     | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V6 1/4A            | F02B125V6-1/4A                                  | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V6 1/4AS           | F02B125V6-1/4AS                                 | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V7A                | F02B125V7A                                      | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B125V7AS               | F02B125V7AS                                     | 15160-140-99; Bussmann Rpt 1276-74    | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B32V8A                 | F02B32V8A                                       | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B32V8AS                | F02B32V8AS                                      | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B32V10A                | F02B32V10A                                      | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B32V10AS               | F02B32V10AS                                     | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B32V15A                | F02B32V15A                                      | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F02B32V15AS               | F02B32V15AS                                     | 15160-019-01                          | /2                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V1A                | F03A250V1A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V1AS               | F03A250V1AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V1 1/4A            | F03A250V1-1/4A                                  | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V1 1/4AS           | F03A250V1-1/4AS                                 | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V1 1/2A            | F03A250V1-1/2A                                  | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V1 1/2AS           | F03A250V1-1/2AS                                 | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V2A                | F03A250V2A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V2AS               | F03A250V2AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V3A                | F03A250V3A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V3AS               | F03A250V3AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V4A                | F03A250V4A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V4AS               | F03A250V4AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V5A                | F03A250V5A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V5AS               | F03A250V5AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V6A                | F03A250V6A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V6AS               | F03A250V6AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V8A                | F03A250V8A                                      | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V8AS               | F03A250V8AS                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V10A               | F03A250V10A                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|---------------------------------------|-----------------------------|-------------------------------------------|
| F03A250V10AS              | F03A250V10AS                                    | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V15A               | F03A250V15A                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A250V15AS              | F03A250V15AS                                    | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A125V20A               | F03A125V20A                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A125V20AS              | F03A125V20AS                                    | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A125V25A               | F03A125V25A                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A125V25AS              | F03A125V25AS                                    | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A125V30A               | F03A125V30A                                     | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03A125V30AS              | F03A125V30AS                                    | 15160-141-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/10A             | F03B250V1/10A                                   | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/10AS            | F03B250V1/10AS                                  | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/8A              | F03B250V1/8A                                    | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/8AS             | F03B250V1/8AS                                   | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V15/100A           | F03B250V15/100A                                 | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V15/100AS          | F03B250V15/100A                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/16A             | F03B250V3/16A                                   | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/16AS            | F03B250V3/16AS                                  | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/4A              | F03B250V1/4A                                    | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/4AS             | F03B250V1/4AS                                   | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/10A             | F03B250V3/10A                                   | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/10AS            | F03B250V3/10AS                                  | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/8A              | F03B250V3/8A                                    | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/8AS             | F03B250V3/8AS                                   | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/2A              | F03B250V1/2A                                    | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1/2AS             | F03B250V1/2AS                                   | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/4A              | F03B250V3/4A                                    | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3/4AS             | F03B250V3/4AS                                   | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V8/10A             | F03B250V8/10A                                   | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V8/10AS            | F03B250V8/10AS                                  | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1A                | F03B250V1A                                      | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1AS               | F03B250V1AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1 1/4A            | F03B250V1-1/4A                                  | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1 1/4AS           | F03B250V1-1/4AS                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1 1/2A            | F03B250V1-1/2A                                  | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1 1/2AS           | F03B250V1-1/2AS                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1 6/10A           | F03B250V1-6/10A                                 | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V1 6/10AS          | F03B250V1-6/10A                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V2A                | F03B250V2A                                      | 15160-142-99                          | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V2AS               | F03B250V2AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V2 1/2A            | F03B250V2-1/2A                                  | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V2 1/2AS           | F03B250V2-1/2AS                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V2 8/10A           | F03B250V2-8/10A                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V2 8/10AS          | F03B250V2-8/10A                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3A                | F03B250V3A                                      | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3AS               | F03B250V3AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3 2/10A           | F03B250V3-2/10A                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B250V3 2/10AS          | F03B250V3-2/10A                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V4A                | F03B125V4A                                      | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V4AS               | F03B125V4AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V5A                | F03B125V5A                                      | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V5AS               | F03B125V5AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V6 1/4A            | F03B125V6-1/4A                                  | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V6 1/4AS           | F03B125V6-1/4AS                                 | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V7A                | F03B125V7A                                      | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V7AS               | F03B125V7AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V8A                | F03B125V8A                                      | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|---------------------------------------|-----------------------------|-------------------------------------------|
| F03B125V8AS               | F03B125V8AS                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V10A               | F03B125V10A                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V10AS              | F03B125V10AS                                    | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V12A               | F03B125V12A                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V12AS              | F03B125V12AS                                    | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V15A               | F03B125V15A                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V15AS              | F03B125V15AS                                    | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V20A               | F03B125V20A                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V20AS              | F03B125V20AS                                    | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V25A               | F03B125V25A                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V25AS              | F03B125V25AS                                    | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V30A               | F03B125V30A                                     | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F03B125V30AS              | F03B125V30AS                                    | 15160-142-99; Bussmann Rpt 1276-74    | /3                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V1A                | F09A250V1A                                      | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V1AS               | F09A250V1AS                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V2A                | F09A250V2A                                      | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V2AS               | F09A250V2AS                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V3A                | F09A250V3A                                      | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V3AS               | F09A250V3AS                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V3 1/2A            | F09A250V3-1/2A                                  | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V3 1/2AS           | F09A250V3-1/2AS                                 | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V4AS               | F09A250V4AS                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V5A                | F09A250V5A                                      | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V5AS               | F09A250V5AS                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V6A                | F09A250V6A                                      | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V6AS               | F09A250V6AS                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V6 1/4AS           | F09A250V6-1/4AS                                 | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V7A                | F09A250V7A                                      | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V7AS               | F09A250V7AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V8A                | F09A250V8A                                      | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V8AS               | F09A250V8AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V10A               | F09A250V10A                                     | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V10AS              | F09A250V10AS                                    | 15160-706-03                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V15A               | F09A250V15A                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V15AS              | F09A250V15AS                                    | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V20A               | F09A250V20A                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V20AS              | F09A250V20AS                                    | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V25A               | F09A250V25A                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V25AS              | F09A250V25AS                                    | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V30A               | F09A250V30A                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V30AS              | F09A250V30AS                                    | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V2/10AS            | F09B250V2/10AS                                  | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V3/10A             | F09B250V3/10A                                   | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V8/10AS            | F09B250V8/10AS                                  | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V1AS               | F09B250V1AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V1 6/10AS          | F09B250V1-6/10A                                 | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V2AS               | F09B250V2AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V2 1/2AS           | F09B250V2-1/2AS                                 | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V3 2/10AS          | F09B250V3-2/10A                                 | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V4AS               | F09B250V4AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V5AS               | F09B250V5AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V6 1/4AS           | F09B250V6-1/4AS                                 | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V8AS               | F09B250V8AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B250V10AS              | F09B250V10AS                                    | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B125V15AS              | F09B125V15AS                                    | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09B32V20AS               | F09B32V20AS                                     | Bussmann Rpt 1276-74                  | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE                                                         | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|-----------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| F09B32V25A                | F09B32V25A                                      | Bussmann Rpt 1276-74                                                                          | /9                          | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F09A250V1A                | 594001                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V1AS               | 594001S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V2A                | 594002                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V2AS               | 594002S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V3A                | 594003                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V3AS               | 594003S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V4A                | 594004                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V4AS               | 594004S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V5A                | 594005                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V5AS               | 594005S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V6A                | 594006                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V6AS               | 594006S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V7A                | 594007                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V7AS               | 594007S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V8A                | 594008                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V8AS               | 594008S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V10A               | 594010                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V10AS              | 594010S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V12A               | 594012                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V12AS              | 594012S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V15A               | 594015                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V15AS              | 594015S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V20A               | 594020                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V20AS              | 594020S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V25A               | 594025                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V25A               | 594025                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V30A               | 594030                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09A250V30AS              | 594030S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B250V1/10A             | 593.100                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B250V1/10AS            | 593.100S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B250V15/100A           | 593.150                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B250V15/100AS          | 593.150S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |

## PART LISTINGS

[illegible]

## PART LISTINGS

[illegible]

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE                                                         | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|-----------------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------|
| F09B32V25A                | 593025                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B32V25AS               | 593025S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B32V30A                | 593030                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F09B32V30AS               | 593030S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994;<br>Littelfuse Rpt TL9050; Littelfuse Rpt TL9071 | /9                          | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F10A250V1A                | F10A250V1A                                      | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V2AS               | F10A250V2AS                                     | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V3AS               | F10A250V3AS                                     | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V5AS               | F10A250V5AS                                     | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V6A                | F10A250V6A                                      | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V8A                | F10A250V8A                                      | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V10AS              | F10A250V10AS                                    | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F10A250V15AS              | F10A250V15AS                                    | 15160-706-03                                                                                  | /10                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V1A                | F15A250V1A                                      | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V1AS               | F15A250V1AS                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V2A                | F15A250V2A                                      | Bussmann Rpt 1110; Bussmann Rpt 1310                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V2AS               | F15A250V2AS                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V3A                | F15A250V3A                                      | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V3AS               | F15A250V3AS                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V5AS               | F15A250V5AS                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V5A                | F15A250V5A                                      |                                                                                               | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V6A                | F15A250V6A                                      | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V6AS               | F15A250V6AS                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V10A               | F15A250V10A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V10AS              | F15A250V10AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V15A              | F15BR250V15A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V15AS             | F15BR250V15AS                                   | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V20A               | F15A250V20A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V20AS              | F15A250V20AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V25A               | F15A250V25A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V25AS              | F15A250V25AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V30A               | F15A250V30A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15A250V30AS              | F15A250V30AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V1A               | F15BR250V1A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V1AS              | F15BR250V1AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V2A               | F15BR250V2A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V2AS              | F15BR250V2AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V4AS              | F15BR250V4AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V5A               | F15BR250V5A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V5AS              | F15BR250V5AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V6 1/4A           | F15BR250V6-1/4A                                 | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V8A               | F15BR250V8A                                     | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V8AS              | F15BR250V8AS                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V10A              | F15BR250V10A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V10AS             | F15BR250V10AS                                   | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V12A              | F15BR250V12A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V12AS             | F15BR250V12AS                                   | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V15A              | F15BR250V15A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V15AS             | F15BR250V15AS                                   | 15160-706-03                                                                                  | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V20A              | F15BR250V20A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V20AS             | F15BR250V20AS                                   | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V25A              | F15BR250V25A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V25AS             | F15BR250V25AS                                   | Bussmann Rpt 1110; Bussmann Rpt 1311                                                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|---------------------------------------|-----------------------------|-------------------------------------------|
| F15BR250V30A              | F15BR250V30A                                    | Bussmann Rpt 1110; Bussmann Rpt 1311  | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V30AS             | F15BR250V30AS                                   | Bussmann Rpt 1110; Bussmann Rpt 1311  | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F15BR250V15AS             | F15BR250V15AS                                   | 15160-706-03                          | /15                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16A250V35AS              | F16A250V35AS                                    | Bussmann Rpt 1117                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16A250V40AS              | F16A250V40AS                                    | Bussmann Rpt 1117                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16A250V45AS              | F16A250V45AS                                    | Bussmann Rpt 1117                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16A250V50AS              | F16A250V50AS                                    | Bussmann Rpt 1117                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16A250V60AS              | F16A250V60AS                                    | Bussmann Rpt 1117                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16BR250V35AS             | F16BR250V35AS                                   | Bussmann Rpt 1140                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16BR250V40AS             | F16BR250V40AS                                   | Bussmann Rpt 1140                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16BR250V45AS             | F16BR250V45AS                                   | Bussmann Rpt 1140                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16BR250V50AS             | F16BR250V50AS                                   | Bussmann Rpt 1140                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F16BR250V60AS             | F16BR250V60AS                                   | Bussmann Rpt 1140                     | /16                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F19BR250V70AS             | F19BR250V70AS                                   | Bussmann Rpt 1141                     | /19                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F19BR250V90AS             | F19BR250V90AS                                   | Bussmann Rpt 1141                     | /19                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F19BR250V100AS            | F19BR250V100AS                                  | Bussmann Rpt 1141                     | /19                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F20BR250V110AS            | F20BR250V110AS                                  | Bussmann Rpt 1142; Bussmann Rpt 1311  | /20                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F20BR250V125AS            | F20BR250V125AS                                  | Bussmann Rpt 1142; Bussmann Rpt 1311  | /20                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F20BR250V150AS            | F20BR250V150AS                                  | Bussmann Rpt 1142; Bussmann Rpt 1311  | /20                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F20BR250V175AS            | F20BR250V175AS                                  | Bussmann Rpt 1142; Bussmann Rpt 1311  | /20                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F20BR250V200AS            | F20BR250V200AS                                  | Bussmann Rpt 1142; Bussmann Rpt 1311  | /20                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/8A              | F60C500V1/8A                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/8AS             | F60C500V1/8AS                                   | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/4A              | F60C500V1/4A                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/4AS             | F60C500V1/4AS                                   | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/2A              | F60C500V1/2A                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/2AS             | F60C500V1/2AS                                   | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V7AS               | F60C500V7AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V3/4A              | F60C500V3/4A                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V3/4AS             | F60C500V3/4AS                                   | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1A                | F60C500V1A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1AS               | F60C500V1AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1 1/2AS           | F60C500V1 1/2AS                                 | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V2A                | F60C500V2A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V2AS               | F60C500V2AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V3A                | F60C500V3A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V3AS               | F60C500V3AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V4A                | F60C500V4A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V4AS               | F60C500V4AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V5A                | F60C500V5A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V5AS               | F60C500V5AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V6A                | F60C500V6A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V6AS               | F60C500V6AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V8A                | F60C500V8A                                      | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V8AS               | F60C500V8AS                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V10A               | F60C500V10A                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V10AS              | F60C500V10AS                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V12AS              | F60C500V12AS                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V15A               | F60C500V15A                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V15AS              | F60C500V15AS                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V20A               | F60C500V20A                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V20AS              | F60C500V20AS                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V25A               | F60C500V25A                                     | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V25AS              | F60C500V25AS                                    | 15160-706-03                          | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE        | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|----------------------------------------------|-----------------------------|-------------------------------------------|
| F60C500V30A               | F60C500V30A                                     | 15160-706-03                                 | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V30AS              | F60C500V30AS                                    | 15160-706-03                                 | /60                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F60C500V1/8A              | 592.125                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1/8AS             | 592.125S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V2/10A             | 592.200                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V2/10AS            | 592.200S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1/4A              | 592.250                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1/4AS             | 592.250S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3/10A             | 592.300                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3/10AS            | 592.300S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3/8A              | 592.375                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3/8AS             | 592.375S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1/2A              | 592.500                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1/2AS             | 592.500S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3/4A              | 592.750                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3/4AS             | 592.750S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1A                | 592001                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1AS               | 592001S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1 1/2A            | 59201.5                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V1 1/2AS           | 59201.5S                                        | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V2A                | 592002                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V2AS               | 592002S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3A                | 592003                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V3AS               | 592003S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V4A                | 592004                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V4AS               | 592004S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V5A                | 592005                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V5AS               | 592005S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V6A                | 592006                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V6AS               | 592006S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V8A                | 592008                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V8AS               | 592008S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V10A               | 592010                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V10AS              | 592010S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V15A               | 592015                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V15AS              | 592015S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V20A               | 592020                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V20AS              | 592020S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V25A               | 592025                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V25AS              | 592025S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V30A               | 592030                                          | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F60C500V30AS              | 592030S                                         | Littelfuse Rpt TL8985; Littelfuse Rpt TL8994 | /60                         | Littelfuse, Inc. (Piedras Negras, Mexico) |
| F61C500V1A                | F61C500V1A                                      | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V1AS               | F61C500V1AS                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V2A                | F61C500V2A                                      | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V2AS               | F61C500V2AS                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V3A                | F61C500V3A                                      | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V3AS               | F61C500V3AS                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V5A                | F61C500V5A                                      | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V5AS               | F61C500V5AS                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V6A                | F61C500V6A                                      | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V6AS               | F61C500V6AS                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V8A                | F61C500V8A                                      | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V8AS               | F61C500V8AS                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V10A               | F61C500V10A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296         | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |

**PART LISTINGS**

| GOVERNMENT<br>DESIGNATION | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SPECIFI-<br>CATION<br>SHEET | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
|---------------------------|-------------------------------------------------|---------------------------------------|-----------------------------|-------------------------------------------|
| F61C500V10AS              | F61C500V10AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V15A               | F61C500V15A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V15AS              | F61C500V15AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V20A               | F61C500V20A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V20AS              | F61C500V20AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V25A               | F61C500V25A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V25AS              | F61C500V25AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V30A               | F61C500V30A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F61C500V30AS              | F61C500V30AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /61                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V35A               | F62C500V35A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V35AS              | F62C500V35AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V40A               | F62C500V40A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V40AS              | F62C500V40AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V45A               | F62C500V45A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V45AS              | F62C500V45AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V50A               | F62C500V50A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V50AS              | F62C500V50AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V60A               | F62C500V60A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F62C500V60AS              | F62C500V60AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /62                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F63C500V70A               | F63C500V70A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /63                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F63C500V70AS              | F63C500V70AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /63                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F63C500V80A               | F63C500V80A                                     | Bussmann Rpt 1281; Bussmann Rpt 1296  | /63                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F63C500V80AS              | F63C500V80AS                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /63                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F63C500V100A              | F63C500V100A                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /63                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F63C500V100AS             | F63C500V100AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /63                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V110A              | F64C500V110A                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V110AS             | F64C500V110AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V125A              | F64C500V125A                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V125AS             | F64C500V125AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V150A              | F64C500V150A                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V150AS             | F64C500V150AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V175A              | F64C500V175A                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V175AS             | F64C500V175AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V200A              | F64C500V200A                                    | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F64C500V200AS             | F64C500V200AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /64                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F65C500V225AS             | F65C500V225AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /65                         | Eaton Bussmann, LLC (Juarez, Mexico)      |
| F65C500V400AS             | F65C500V400AS                                   | Bussmann Rpt 1281; Bussmann Rpt 1296  | /65                         | Eaton Bussmann, LLC (Juarez, Mexico)      |

---

**Manufacturer and Supplier Location Information**

---

**Manufacturer: Eaton Bussmann, LLC (CAGE Code: 71400)**

Location: 114 Old State Road, Ellisville, MO 63021-5915, US Mail: P.O. Box 14460, St. Louis, MO 63178, US

**Plants:**

1. Eaton Bussmann, LLC (Juarez, Mexico), Planta Juarez-Prolongacion Hermanos Escobar No. 7750, Parque Industrial Omega, Col. Partido Doblado, 32320 Ciudad Juarez, Chihuahua, MX

**Manufacturer: Littelfuse, Inc. (CAGE Code: 75915)**

Location: 8755 West Higgins Road Suite 500, Chicago, IL 60631, US

**Plants:**

1. Littelfuse Corp. MX, Venustiano Carranza 2501, Colonia Lomas de la villa, Piedras Negras, Coahuila 26090, MX