**Specification Details:** **Date: 5/1/2024**

Specification: MIL-PRF-23419
Title: Fuse, Cartridge, Instrument Type
Federal Supply Class (FSC): 5920
Conventional: No
Specification contains quality assurance program: No
MIL-STD-790 Established Reliability & High Reliability: Yes
MIL-STD-690 Failure Rate Sampling Plans & Procedures: No
Weibull Graded: No
Specification contains space level reliability requirements: No
Specification allows test optimization: No

**Contact Information:**

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH
Primary Qualifying Activity Contact: 614-692-2345, e-mail: vqh.cc@dla.mil
Secondary Qualifying Activity Contact: 614-692-5061, e-mail: vqh.fn@dla.mil

**Notes:**

PIN: The PIN consists of a Style, Characteristic, Voltage rating, Current rating, and Optional finish.

Style: The style is identified by the letters "FM" followed by a two-digit number denoting a fuse of a given construction and dimensions.

Characteristic: The characteristic is identified by a one-letter symbol which indicates the relative overload interrupt time.

Voltage rating: The voltage rating is the maximum dc or ac root mean square (rms) voltage for which a fuse is designed. The voltage rating is identified by a numerical value followed by the letter "V".

Current rating: The current rating is the amount of current a fuse will carry indefinitely without interruption. The current rating in amperes and fractions of an ampere is identified by a numerical value followed by the letter "A".

Optional finish: When specified, a suffix letter is added to the type designation covered by selected specification sheets to denote optional finish.

**Part Configuration:**

FM08A125V1/2A*

| Style | Characteristic | Voltage Rating | Current Rating | Optional Finish |
|---|---|---|---|---|
| FM08 | A | 125V | 1/2A | * |

**PART LISTINGS**

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| FM01A125V1/100A | FM01A125V1/16A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V1/10A | FM01A125V1/10A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V1/8A | FM01A125V1/8A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V2/10A | FM01A125V2/10A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V1/4A | FM01A125V1/4A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V3/10A | FM01A125V3/10A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V4/10A | FM01A125V4/10A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V1/2A | FM01A125V1/2A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V6/10A | FM01A125V6/10A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V3/4A | FM01A125V3/4A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V1A | FM01A125V1A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V1-1/2A | FM01A125V1-1/2A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V2.0A | FM01A125V2A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V3.0A | FM01A125V3A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V4.0A | FM01A125V4A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM01A125V5.0A | FM01A125V5A | 23419-4546-15 | /1 | Eaton's Bussmann (La Grange, NC) |
| FM02A125V1/500A | 274.002 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/200A | 274.005 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/100A | 274.010 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/64A | 274.015 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/32A | 274.031 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |

| PART LISTINGS | | | | |
|---|---|---|---|---|
| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
| FM02A125V1/16A | 274.062 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/10A | 274.100 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/8A | 274.125 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V2/10A | 274.200 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/4A | 274.250 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V3/10A | 274.300 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V4/10A | 274.400 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1/2A | 274.500 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V6/10A | 274.600 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V3/4A | 274.750 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1A | 274001 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V1-1/2A | 27401.5 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V2A | 274002 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V3A | 274003 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V4A | 274004 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM02A125V5A | 274005 | 23419-025-96; 23419-147-99 | /2 | Littelfuse Corp. MX |
| FM04A125V1/16A | 277.062 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V3/8A | 277.375 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V1/2A | 277.500 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V3/4A | 277.750 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V1A | 277001 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V1-1/2A | 27701.5 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V2A | 277002 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V3A | 277003 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V4A | 277004 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V5A | 277005 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V7A | 277007 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A125V10A | 277010 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM04A32V15A | 277015 | 23419-625-03 | /4 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/500A | 269.002 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/200A | 269.005 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/100A | 269.001 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/64A | 269.016 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/32A | 269.031 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/16A | 269.062 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/10A | 269.100 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/8A | 269.125 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V2/10A | 269.200 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/4A | 296.250 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V3/10A | 269.300 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V4/10A | 269.400 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/20A | 269.050 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1/2A | 269.500 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V6/10A | 269.600 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V7/10A | 269.700 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V3/4A | 269.750 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V8/10A | 269.800 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1A | 269.001 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V1-1/2A | 26901.5 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V2A | 269002 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V3A | 269003 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V4A | 269004 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM07A125V5A | 269005 | 23419-972-76 | /7 | Littelfuse, Inc. (Philippines) |
| FM08A125V1/8A | FM08A125V1/8A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1/4A | FM08A125V1/4A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |

## PART LISTINGS

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| FM08A125V1/4AT | FM08A125V1/4AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V3/8A | FM08A125V3/8A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V3/8AT | FM08A125V3/8AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1/2A | FM08A125V1/2A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1/2AT | FM08A125V1/2AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V3/4A | FM08A125V3/4A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V3/4AT | FM08A125V3/4AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1A | FM08A125V1A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1AT | FM08A125V1AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1 1/2A | FM08A125V1-1/2A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1-1/2T | FM08A125V1-1/2T | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V2A | FM08A125V2A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V2AT | FM08A125V2AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V2 1/2A | FM08A125V2-1/2A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V2-1/2AT | FM08A125V2-1/2AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V3A | FM08A125V3A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V3AT | FM08A125V3AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V4A | FM08A125V4A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V4AT | FM08A125V4AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V5A | FM08A125V5A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A32V15AT | FM08A32V15AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V7A | FM08A125V7A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V7AT | FM08A125V7AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V10A | FM08A125V10A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V10AT | FM08A125V10AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A32V15AT | FM08A32V15AT | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A32V15A | FM08A32V15A | 23419-4546-15 | /8 | Eaton's Bussmann (La Grange, NC) |
| FM08A125V1/8A | 267.125 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V1/4A | 267.250 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V3/8A | 267.375 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V1/2A | 267.500 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V3/4A | 267.750 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V1A | 267001 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V1 1/2A | 26701.5 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V2A | 267002 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V2 1/2A | 26702.5 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V3A | 267003 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V4A | 267004 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V5A | 267005 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V7A | 267007 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A125V10A | 267010 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM08A32V15A | 267015 | 23419-1181-79; 23419-763-79 | /8 | Littelfuse, Inc. (Philippines) |
| FM10A125V1/8A | 253.125 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V1/4A | 253.250 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V3/8A | 253.375 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V1/2A | 253.500 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V3/4A | 253.750 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V1A | 253001 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V1-1/2A | 25301.5 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V2A | 253002 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V3A | 253003 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V4A | 253004 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V5A | 253005 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V7A | 253007 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A125V10A | 253010 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A32V5A | 253005 | 23419-6912-24 | /10 | Littelfuse, Inc. (Philippines) |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| FM10A32V7A | 253007 | 23419-6912-24 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A32V10A | 253010 | 23419-6912-24 | /10 | Littelfuse, Inc. (Philippines) |
| FM10A32V15A | 253015 | 23419-625-03 | /10 | Littelfuse, Inc. (Philippines) |
| FM12A135V1/8AT | P600L-135-1/8T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/8AF | SK406-135-1/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/8A | P600L-135-1/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/4AT | P600L-135-1/4T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/4AF | SK406-135-1/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/4A | P600L-135-1/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3/8AT | P600L-135-3/8T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3/8AF | SK406-135-3/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3/8A | P600L-135-3/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/2AT | P600L-135-1/2T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/2AF | SK406-135-1/2 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1/2A | P600L-135-1/2 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3/4AT | P600L-135-3/4T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3/4AF | SK406-135-3/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3/4A | P600L-135-3/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1AT | P600L-135-1.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1AF | SK406-135-1.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1A | P600L-135-1.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1.5AT | P600L-135-1.5T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1.5AF | SK406-135-1.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V1.5A | P600L-135-1.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V2.0AT | P600L-135-2.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V2.0AF | SK406-135-2.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V2.0A | P600L-135-2.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3.0AT | P600L-135-3.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3.0AF | SK406-135-3.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V3.0A | P600L-135-3.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V4.0AT | P600L-135-4.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V4.0AF | SK406-135-4.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V4.0A | P600L-135-4.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V5.0A | P600L-135-5.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V5.0AT | P600L-135-5.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V5.0AF | SK406-135-5.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V7.5A | P600L-135-7.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V7.5AT | P600L-135-7.5T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V10A | P600L-135-10.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V10AT | P600L-135-10.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V15A | P600L-135-15.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A135V15AT | P600L-135-15.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/8AT | P600L-125-1/8T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/8A | P600L-125-1/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/8AF | SK406-125-1/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/4AT | P600L-125-1/4T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/4A | P600L-125-1/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/4AF | SK406-125-1/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3/8AT | P600L-125-3/8T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3/8A | P600L-125-3/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3/8AF | SK406-125-3/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/2AT | P600L-125-1/2T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/2A | P600L-125-1/2 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1/2AF | SK406-125-1/2 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3/4AT | P600L-125-3/4T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3/4A | P600L-125-3/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |

| PART LISTINGS | | | | |
|---|---|---|---|---|
| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
| FM12A125V3/4AF | SK406-125-3/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1AT | P600L-125-1.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1A | P600L-125-1.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1AF | SK406-125-1.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1.5AT | P600L-125-1.5T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1.5A | P600L-125-1.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V1.5AF | SK406-125-1.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V2.0AT | P600L-125-2.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V2.0A | P600L-125-2.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V2.0AF | SK406-125-2.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3.0AT | P600L-125-3.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3.0A | P600L-125-3.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V3.0AF | SK406-125-3.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V4.0AT | P600L-125-4.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V4.0A | P600L-125-4.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V4.0AF | SK406-125-4.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V5.0AT | P600L-125-5.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V5.0A | P600L-125-5.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V5.0AF | SK406-125-5.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V7.5AT | P600L-125-7.5T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V7.5A | P600L-125-7.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V10AT | P600L-125-10.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V10A | P600L-125-10.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V15AT | P600L-125-15.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A125V15A | P600L-125-15.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/8AT | P600L-72-1/8T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/8A | P600L-72-1/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/8AF | SK406-72-1/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/4AT | P600L-72-1/4T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/4A | P600L-72-1/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/4AF | SK406-72-1/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3/8AT | P600L-72-3/8T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3/8A | P600L-72-3/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3/8AF | SK406-72-3/8 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/2AT | P600L-72-1/2T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/2A | P600L-72-1/2 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1/2AF | SK406-72-1/2 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3/4AT | P600L-72-3/4T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3/4A | P600L-72-3/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3/4AF | SK406-72-3/4 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1AT | P600L-72-1.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1A | P600L-72-1.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1AF | SK406-72-1.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1.5AT | P600L-72-1.5T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1.5A | P600L-72-1.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V1.5AF | SK406-72-1.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V2.0AT | P600L-72-2.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V2.0A | P600L-72-2.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V2.0AF | SK406-72-2.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3.0AT | P600L-72-3.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3.0A | P600L-72-3.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V3.0AF | SK406-72-3.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V4.0AT | P600L-72-4.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V4.0A | P600L-72-4.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V4.0AF | SK406-72-4.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V5.0AT | P600L-72-5.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |

| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
|---|---|---|---|---|
| FM12A72V5.0A | P600L-72-5.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V5.0AF | SK406-72-5.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V6.0AT | P600L-72-6.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V6.0A | P600L-72-6.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V6.0AF | SK406-72-6.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V7.5AT | P600L-72-7.5T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V7.5A | P600L-72-7.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V7.5AF | SK406-72-7.5 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V10AT | P600L-72-10.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V10A | P600L-72-10.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V10AF | SK406-72-10.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V15AT | P600L-72-15.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V15A | P600L-72-15.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A72V15AF | SK406-72-15.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A50V20AT | P600L-50-20.0T | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A50V20A | P600L-50-20.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM12A50V20AF | SK406-50-20.0 | 23419-266-93, 23419-267-93 | /12 | AEMI HOLDINGS, LLC |
| FM13A125V1/8A | P700L-125-1/8 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V1/4A | P700L-125-1/4 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V3/8A | P700L-125-3/8 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V1/2A | P700L-125-1/2 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V3/4A | P700L-125-3/4 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V1A | P700L-125-1.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V1.5A | P700L-125-1.5 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V2.0A | P700L-125-2.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V3.0A | P700L-125-3.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V4.0A | P700L-125-4.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V5.0A | P700L-125-5.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V7.5A | P700L-125-7.5 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V10A | P700L-125-10.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A125V15A | P700L-125-15.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V1/8A | P700L-72-1/8 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V1/4A | P700L-72-1/4 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V3/8A | P700L-72-3/8 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V1/2A | P700L-72-1/2 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V3/4A | P700L-72-3/4 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V1A | P700L-72-1.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V1.5A | P700L-72-1.5 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V2.0A | P700L-72V-2.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V2.0A | P700L-72-2.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V3.0A | P700L-72-3.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V4.0A | P700L-72-4.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V5.0A | P700L-72-5.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V6.0A | P700L-72-6.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V7.5A | P700L-72-7.5 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V10A | P700L-72-10.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A72V15A | P700L-72-15.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A50V20A | P700L-50-20.0 | 23419-5068-18 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V1/8A | P700L-135-1/8 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V1/8A | P700L-135-1/8 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V1/4A | P700L-135-1/4 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V3/8A | P700L-135-3/8 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V1/2A | P700L-135-1/2 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V3/4A | P700L-135-3/4 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V1A | P700L-135-1.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V1.5A | P700L-135-1.5 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |

| PART LISTINGS | | | | |
|---|---|---|---|---|
| GOVERNMENT DESIGNATION | MANUFACTURER'S DESIGNATION OR TYPE NUMBER | TEST OR QUALIFICATION REFERENCE | SPECIFI-CATION SHEET | SUPPLIER'S NAME (ADDRESS ON LAST PAGE) |
| FM13A135V2.0A | P700L-135-2.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V3.0A | P700L-135-3.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V4.0A | P700L-135-4.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V5.0A | P700L-135-5.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V7.5A | P700L-135-7.5 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V10A | P700L-135-10.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |
| FM13A135V15A | P700L-135-15.0 | 23419-5068-18 /13 | /13 | AEMI HOLDINGS, LLC |

## Manufacturer and Supplier Location Information

**Manufacturer: AEMI HOLDINGS, LLC (CAGE Code: 1GLF1)**
Location: 6610 Cobra Way, San Diego, CA 92121, US

Plants:

1. Plant: Same Address as Manufacturer

**Manufacturer: Eaton Bussmann, LLC. (CAGE Code: 71400)**
Location: P.O. Box 14460, 114 Old State Road, Ellsville, MO 63021-5915, US

Plants:

1. Eaton Bussmann (La Grange, NC), CAGE: 1JY78, 4758 Washington Street, La Grange, NC 28551, US

**Manufacturer: Littelfuse, Inc. (CAGE Code: 75915)**
Location: 8755 West Higgins Road Suite 500, Chicago, IL 60631, US

Plants:

1. Littelfuse Corp. MX, Venustiano Carranza 2501, Colonia Lomas de la villa, Piedras Negras, Coahuila 26090, MX
2. Littelfuse, Inc. (Philippines), Littelfuse Phils., Inc., Lima Technology Center, Special Economic Zone, Lipa City Malvar, Batangas 4233, Philippines