

DLA Land and Maritime - VQ
Supplemental Information Sheet for Electronic QPL-39015

Date: 8/7/2019

Specification Details:

Specification: MIL-PRF-39015
 Title: Resistor, Variable, Wire-Wound (Lead Screw Actuated)
 Federal Supply Class (FSC): 5905
 Conventional: No
 Specification contains quality assurance program: No
 MIL-STD-790 Established Reliability & High Reliability: Yes
 MIL-STD-690 Failure Rate Sampling Plans & Procedures: Yes
 Weibull Graded: No
 Specification contains space level reliability requirements: No
 Specification allows test optimization: Yes

Contact Information:

Office of Primary Involvement: Passive Devices Branch, DLA Land and Maritime - VQP
 Primary Qualifying Activity Contact: 614-692-0597, e-mail: vqp.jz@dla.mil
 Secondary Qualifying Activity Contact: 614-692-2063, e-mail: vqp.ahc@dla.mil

Notes:

Contact the manufacturer or refer to the manufacturers website for a list of Authorized Distributors.

Part Configuration:

M39015/2-001PM

Associated Specification Number	Resistance Value Designator	Terminals	Product Level Designator
M39015/2	001	P	M

PART LISTINGS

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
---------------------------	---	---------------------------------------	-----------------------------	---

RTR22

M39015/2-003LM	M3250L	39015-069-98	/2	Bourns, Inc.
M39015/2-003PM	M3250P	39015-069-98	/2	Bourns, Inc.
M39015/2-003WM	M3250W	39015-069-98	/2	Bourns, Inc.
M39015/2-003XM	M3250X	39015-069-98	/2	Bourns, Inc.
M39015/2-004LM	M3250L	39015-069-98	/2	Bourns, Inc.
M39015/2-004PM	M3250P	39015-069-98	/2	Bourns, Inc.
M39015/2-004WM	M3250W	39015-069-98	/2	Bourns, Inc.
M39015/2-004XM	M3250X	39015-069-98	/2	Bourns, Inc.
M39015/2-005LM	M3250L	39015-069-98	/2	Bourns, Inc.
M39015/2-005PM	M3250P	39015-069-98	/2	Bourns, Inc.
M39015/2-005WM	M3250W	39015-069-98	/2	Bourns, Inc.
M39015/2-005XM	M3250X	39015-069-98	/2	Bourns, Inc.
M39015/2-006LM	M3250L	39015-069-98	/2	Bourns, Inc.
M39015/2-006PM	M3250P	39015-069-98	/2	Bourns, Inc.
M39015/2-006WM	M3250W	39015-069-98	/2	Bourns, Inc.
M39015/2-006XM	M3250X	39015-069-98	/2	Bourns, Inc.
M39015/2-007LM	M3250L	39015-069-98	/2	Bourns, Inc.
M39015/2-007PM	M3250P	39015-069-98	/2	Bourns, Inc.
M39015/2-007WM	M3250W	39015-069-98	/2	Bourns, Inc.
M39015/2-007XM	M3250X	39015-069-98	/2	Bourns, Inc.
M39015/2-008LM	M3250L	39015-069-98	/2	Bourns, Inc.
M39015/2-008PM	M3250P	39015-069-98	/2	Bourns, Inc.
M39015/2-008WM	M3250W	39015-069-98	/2	Bourns, Inc.
M39015/2-008XM	M3250X	39015-069-98	/2	Bourns, Inc.

RTR24

M39015/3-006PM	A3290P	39015-201-95	/3	Bourns, Inc.
----------------	--------	--------------	----	--------------

PART LISTINGS				
GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
RTR24				
M39015/3-006WM	A3290W	39015-201-95	/3	Bourns, Inc.
M39015/3-006XM	A3290X	39015-201-95	/3	Bourns, Inc.
M39015/3-007PM	A3290P	39015-201-95	/3	Bourns, Inc.
M39015/3-007WM	A3290W	39015-201-95	/3	Bourns, Inc.
M39015/3-007XM	A3290X	39015-201-95	/3	Bourns, Inc.
M39015/3-008PM	A3290P	39015-201-95	/3	Bourns, Inc.
M39015/3-008WM	A3290W	39015-201-95	/3	Bourns, Inc.
M39015/3-008XM	A3290X	39015-201-95	/3	Bourns, Inc.
M39015/3-009PM	A3290P	39015-201-95	/3	Bourns, Inc.
M39015/3-009WM	A3290W	39015-201-95	/3	Bourns, Inc.
M39015/3-009XM	A3290X	39015-201-95	/3	Bourns, Inc.
M39015/3-010PM	A3290P	39015-201-95	/3	Bourns, Inc.
M39015/3-010WM	A3290W	39015-201-95	/3	Bourns, Inc.
M39015/3-010XM	A3290X	39015-201-95	/3	Bourns, Inc.

Manufacturer and Supplier Location Information

Manufacturer: Bourns, Inc. (CAGE Code: 32997)

Location: Trimpot Products Division, 1200 Columbia Avenue, Riverside, CA 92507, US

Plants:

1. Bourns de Mexico, S.A., Blvd. Aqua Caliente 4600, Local 13, Centro Industrial Barranquita, Tijuana, B.C., Mexico CP 22400, MX