

Specification Details:

Date: 11/24/2008

Specification: MIL-PRF-83536

Title: Relay, Electromagnetic

Federal Supply Class (FSC): 5945

Conventional: No

Specification contains quality assurance program: No

MIL-STD-790 Established Reliability & High Reliability: Yes

MIL-STD-690 Failure Rate Sampling Plans & Procedures: Yes

Weibull Graded: No

Specification contains space level reliability requirements: No

Specification allows test optimization: No

Contact Information:

DSCC Office of Primary Involvement: Passive Devices Team, DSCC-VQP

Primary DSCC-VQ Contact: 614-692-0505, e-mail: vqp.arw@dla.mil

Secondary DSCC-VQ Contact: 614-692-0594, e-mail: vqp.kr@dla.mil

Notes:

Products listed in this QPL are available through authorized distributors authorized by the manufacturers in accordance with MIL-STD-790. Names and addresses of the distributors are listed in the back of this QPL. These lists are being furnished merely as an aid in identifying authorized sources of ER parts and the responsibility for complying with contractual provisions requiring use of such parts rests with the user of such parts. Such lists have been compiled from information furnished by the manufacturers of ER parts prior to release of this QPL for printing. Inclusion on, or omission from, the list of a particular distributor cannot be relied upon as a guarantee of their status since the information upon which the list is based may not have been complete and since authorized distributors are subject to change by the manufacturer at any time. Inclusion of a firm on the list is not, under any circumstance, to be considered an endorsement of such firm or its products by the Department of Defense.

Part Configuration:**M83536/10-001L**

Specification Designator	Specification Sheet Number	Dash Number	Failure Rate Level
M83536	/10	-001	L

Part Listings:

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFICATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/1-010L, M	E2050201CTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-011L, M	E2050201ATL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-012L, M	E2050201BGL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-013L, M	E2050202CTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-014L, M	E2050202ATL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-015L, M	E2050202BGL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-016L, M	E2050203CTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-017L, M	E2050203ATL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-018L, M	E2050203DTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-019L, M	E2050401CTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-020L, M	E2050401ATL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-021L, M	E2050401BGL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-022L, M	E2050402CTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-023L, M	E2050402ATL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-024L, M	E2050402BGL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-025L, M	E2050403CTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-026L, M	E2050403ATL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-027L, M	E2050403DTL, M	83536-98-0138	/1	DRI Relays, Inc.
M83536/1-019L, M	M210-A1A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-020L, M	M210-A2A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-021L, M	M210-A4A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-022L, M	M210-D1A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-023L, M	M210-D2A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-024L, M	M210-D4A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/1-025L, M	M210-J1A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-026L, M	M210-J2A-004L, M	83536-481-03, 83536-158-99	/1	Leach International Europe S.A.
M83536/1-001L, M	X-A1C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-002L, M	X-A2C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-003L, M	X-A4C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-004L, M	X-D1C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-005L, M	X-D2C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-006L, M	X-D4C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-007L, M	X-J1C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-008L, M	X-J2C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-009L, M	X-J7C-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-010L, M	X-A1B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-011L, M	X-A2B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-012L, M	X-A4B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-013L, M	X-D1B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-014L, M	X-D2B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-015L, M	X-D4B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-016L, M	X-J1B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-017L, M	X-J2B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-018L, M	X-J7B-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-019L, M	X-A1A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-020L, M	X-A2A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-021L, M	X-A4A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-022L, M	X-D1A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-023L, M	X-D2A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-024L, M	X-D4A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-025L, M	X-J1A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-026L, M	X-J2A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-027L, M	X-J7A-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-028L, M	X-A1M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-029L, M	X-A2M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-030L, M	X-A4M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-031L, M	X-D1M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-032L, M	X-D2M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-033L, M	X-D4M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-034L, M	X-J1M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-035L, M	X-J2M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-036L, M	X-J7M-300L, M	83536-98-0173	/1	Leach International North America
M83536/1-001L, M	FCB-205-0101L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-002L, M	FCB-205-0102L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-003L, M	FCB-205-0103L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-004L, M	FCB-205-0104L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-005L, M	FCB-205-0105L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-006L, M	FCB-205-0106L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-007L, M	FCB-205-0107L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-008L, M	FCB-205-0108L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-009L, M	FCB-205-0109L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-010L, M	FCB-205-0110L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-011L, M	FCB-205-0111L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-012L, M	FCB-205-0112L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-013L, M	FCB-205-0113L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-014L, M	FCB-205-0114L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-015L, M	FCB-205-0115L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-016L, M	FCB-205-0116L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-017L, M	FCB-205-0117L, M	83536-901-04	/1	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/1-018L, M	FCB-205-0118L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-019L, M	FCB-205-0119L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-020L, M	FCB-205-0120L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-021L, M	FCB-205-0121L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-022L, M	FCB-205-0122L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-023L, M	FCB-205-0123L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-024L, M	FCB-205-0124L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-025L, M	FCB-205-0125L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-026L, M	FCB-205-0126L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-027L, M	FCB-205-0127L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-028L, M	FCB-205-0128L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-029L, M	FCB-205-0129L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-030L, M	FCB-205-0130L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-031L, M	FCB-205-0131L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-032L, M	FCB-205-0132L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-033L, M	FCB-205-0133L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-034L, M	FCB-205-0134L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-035L, M	FCB-205-0135L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/1-036L, M	FCB-205-0136L, M	83536-901-04	/1	Tyco Electronics/CII Relays
M83536/2-010L, M	ES2050201CTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-011L, M	ES2050201ATL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-012L, M	ES2050201BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-013L, M	ES2050202CTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-014L, M	ES2050202ATL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-015L, M	ES2050202BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-016L, M	ES2050203CTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-017L, M	ES2050203ATL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-018L, M	ES2050203DTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-019L, M	ES2050401CTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-020L, M	ES2050401ATL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-021L, M	ES2050401BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-022L, M	ES2050402CTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-023L, M	ES2050402ATL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-024L, M	ES2050402BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-025L, M	ES2050403CTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-026L, M	ES2050403ATL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-027L, M	ES2050403DTL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-028L, M	ES2050404BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-029L, M	ES2050018KGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-039L, M	ES2052802BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-040L, M	ES2052803BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-041L, M	ES2050405BGL, M	83536-98-0139	/2	DRI Relays, Inc.
M83536/2-019L, M	M210-A1N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-020L, M	M210-A2N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-021L, M	M210-A4N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-022L, M	M210-D1N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-023L, M	M210-D2A-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-024L, M	M210-D4N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-025L, M	M210-J1N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-026L, M	M210-J2N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-028L, M	M210-E4N-004L, M	83536-158-99, 83536-481-03	/2	Leach International Europe S.A.
M83536/2-001L, M	X-A1V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-002L, M	X-A2V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-003L, M	X-A4V-300L, M	83536-98-0174	/2	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/2-004L, M	X-D1V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-005L, M	X-D2V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-006L, M	X-D4V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-007L, M	X-J1V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-008L, M	X-J2V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-009L, M	X-J7V-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-010L, M	X-A1R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-011L, M	X-A2R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-012L, M	X-A4R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-013L, M	X-D1R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-014L, M	X-D2R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-015L, M	X-D4R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-016L, M	X-J1R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-017L, M	X-J2R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-018L, M	X-J7R-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-019L, M	X-A1N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-020L, M	X-A2N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-021L, M	X-A4N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-022L, M	X-D1N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-023L, M	X-D2N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-024L, M	X-D4N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-025L, M	X-J1N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-026L, M	X-J2N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-027L, M	X-J7N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-028L, M	X-E4N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-030L, M	X-A1W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-031L, M	X-A2W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-032L, M	X-A4W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-033L, M	X-D1W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-034L, M	X-D2W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-035L, M	X-D4W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-036L, M	X-J1W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-037L, M	X-J2W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-038L, M	X-J7W-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-041L, M	X-F4N-300L, M	83536-98-0174	/2	Leach International North America
M83536/2-001L, M	FCB-205-0201L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-003L, M	FCB-205-0202L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-004L, M	FCB-205-0204L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-005L, M	FCB-205-0205L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-006L, M	FCB-205-0206L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-007L, M	FCB-205-0207L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-008L, M	FCB-205-0208L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-009L, M	FCB-205-0209L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-010L, M	FCB-205-0210L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-011L, M	FCB-205-0211L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-012L, M	FCB-205-0212L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-013L, M	FCB-205-0213L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-014L, M	FCB-205-0214L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-016L, M	FCB-205-0216L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-017L, M	FCB-205-0217L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-018L, M	FCB-205-0218L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-019L, M	FCB-205-0219L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-020L, M	FCB-205-0220L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-021L, M	FCB-205-0221L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-021L, M	FCB-205-0202L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-022L, M	FCB-205-0222L, M	83536-901-04	/2	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/2-023L, M	FCB-205-0223L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-024L, M	FCB-205-0224L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-025L, M	FCB-205-0225L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-026L, M	FCB-205-0226L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-027L, M	FCB-205-0227L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-028L, M	FCB-205-0228L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-030L, M	FCB-205-0230L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-031L, M	FCB-205-0231L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-032L, M	FCB-205-0232L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-033L, M	FCB-205-0233L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-034L, M	FCB-205-0234L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-035L, M	FCB-205-0235L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-036L, M	FCB-205-0236L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-037L, M	FCB-205-0237L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/2-038L, M	FCB-205-0238L, M	83536-901-04	/2	Tyco Electronics/CII Relays
M83536/5-009L, M	E4050201CTL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-010L, M	E4050201ATL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-011L, M	E4050201BGL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-012L, M	E4050202CTL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-013L, M	E4050202ATL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-014L, M	E4050202BGL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-015L, M	E4050203CTL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-016L, M	E4050203ATL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-017L, M	E4050401CTL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-018L, M	E4050401ATL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-019L, M	E4050401BGL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-020L, M	E4050402CTL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-021L, M	E4050402ATL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-022L, M	E4050402BGL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-023L, M	E4050403CTL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-024L, M	E4050403ATL, M	83536-98-0140	/5	DRI Relays, Inc.
M83536/5-001L, M	Y-A1C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-002L, M	Y-A2C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-003L, M	Y-A4C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-004L, M	Y-D1C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-005L, M	Y-D2C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-006L, M	Y-D4C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-007L, M	Y-J1C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-008L, M	Y-J2C-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-009L, M	Y-A1B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-010L, M	Y-A2B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-011L, M	Y-A4B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-012L, M	Y-D1B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-013L, M	Y-D2B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-014L, M	Y-D4B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-015L, M	Y-J1B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-016L, M	Y-J2B-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-017L, M	Y-A1A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-018L, M	Y-A2A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-019L, M	Y-A4A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-020L, M	Y-D1A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-021L, M	Y-D2A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-022L, M	Y-D4A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-023L, M	Y-J1A-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-024L, M	Y-J2A-300L, M	83536-98-0204	/5	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/5-025L, M	Y-A1M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-026L, M	Y-A2M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-027L, M	Y-A4M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-028L, M	Y-D1M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-029L, M	Y-D2M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-030L, M	Y-D4M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-031L, M	Y-J1M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-032L, M	Y-J2M-300L, M	83536-98-0204	/5	Leach International North America
M83536/5-001L, M	FCB-405-0501L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-002L, M	FCB-405-0502L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-003L, M	FCB-405-0503L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-004L, M	FCB-405-0504L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-005L, M	FCB-405-0505L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-006L, M	FCB-405-0506L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-007L, M	FCB-405-0507L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-008L, M	FCB-405-0508L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-009L, M	FCB-405-0509L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-010L, M	FCB-405-0510L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-011L, M	FCB-405-0511L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-012L, M	FCB-405-0512L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-013L, M	FCB-405-0513L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-014L, M	FCB-405-0514L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-015L, M	FCB-405-0515L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-016L, M	FCB-405-0516L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-017L, M	FCB-405-0517L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-018L, M	FCB-405-0518L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-019L, M	FCB-405-0519L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-020L, M	FCB-405-0520L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-021L, M	FCB-405-0521L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-022L, M	FCB-405-0522L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-023L, M	FCB-405-0523L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-024L, M	FCB-405-0524L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-025L, M	FCB-405-0525L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-026L, M	FCB-405-0526L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-027L, M	FCB-405-0527L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-028L, M	FCB-405-0528L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-029L, M	FCB-405-0529L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-030L, M	FCB-405-0530L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-031L, M	FCB-405-0531L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/5-032L, M	FCB-405-0532L, M	83536-902-04	/5	Tyco Electronics/CII Relays
M83536/6-009L, M	ES4050201CTL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-010L, M	ES4050201ATL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-011L, M	ES4050201BGL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-012L, M	ES4050202CTL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-013L, M	ES4050202ATL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-014L, M	ES4050202BGL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-015L, M	ES4050203CTL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-016L, M	ES4050203ATL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-017L, M	ES4050401CTL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-018L, M	ES4050401ATL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-019L, M	ES4050401BGL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-020L, M	ES4050402CTL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-021L, M	ES4050402ATL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-022L, M	ES4050402BGL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-023L, M	ES4050403CTL, M	83536-98-0141	/6	DRI Relays, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/6-024L, M	ES4050403ATL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-025L, M	ES4050404BGL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-026L, M	ES4050018KGL, M	83536-98-0141	/6	DRI Relays, Inc.
M83536/6-017L, M	M220-A1N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-018L, M	M220-A2N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-019L, M	M220-A4N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-020L, M	M220-D1N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-021L, M	M220-D2N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-022L, M	M220-D4N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-023L, M	M220-J1N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-024L, M	M220-J2N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6-025L, M	M220-E4N-004L, M	83536-155-99, 83536-480-03	/6	Leach International Europe S.A.
M83536/6/001L, M	Y-A1V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-002L, M	Y-A2V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-003L, M	Y-A4V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-004L, M	Y-D1V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-005L, M	Y-D2V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-006L, M	Y-D4V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-007L, M	Y-J1V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-008L, M	Y-J2V-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-009L, M	Y-A1R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-010L, M	Y-A2R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-011L, M	Y-A4R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-012L, M	Y-D1R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-013L, M	Y-D2R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-014L, M	Y-D4R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-015L, M	Y-J1R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-016L, M	Y-J2R-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-017L, M	Y-A1N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-018L, M	Y-A2N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-019L, M	Y-A4N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-020L, M	Y-D1N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-021L, M	Y-D2N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-022L, M	Y-D4N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-023L, M	Y-J1N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-024L, M	Y-J2N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-025L, M	Y-E4N-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-027L, M	Y-A1W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-028L, M	Y-A2W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-029L, M	Y-A4W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-030L, M	Y-D1W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-031L, M	Y-D2W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-032L, M	Y-D4W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-033L, M	Y-J1W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-034L, M	Y-J2W-300L, M	83536-98-0205	/6	Leach International North America
M83536/6-001L, M	FCB-405-0601L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-002L, M	FCB-405-0602L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-003L, M	FCB-405-0603L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-004L, M	FCB-405-0604L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-005L, M	FCB-405-0605L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-006L, M	FCB-405-0606L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-007L, M	FCB-405-0607L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-008L, M	FCB-405-0608L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-009L, M	FCB-405-0609L, M	83536-902-04	/6	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/6-010L, M	FCB-405-0610L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-011L, M	FCB-405-0611L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-012L, M	FCB-405-0612L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-013L, M	FCB-405-0613L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-014L, M	FCB-405-0614L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-015L, M	FCB-405-0615L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-016L, M	FCB-405-0616L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-017L, M	FCB-405-0617L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-018L, M	FCB-405-0618L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-019L, M	FCB-405-0619L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-020L, M	FCB-405-0620L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-021L, M	FCB-405-0621L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-022L, M	FCB-405-0622L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-023L, M	FCB-405-0623L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-024L, M	FCB-405-0624L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-025L, M	FCB-405-0625L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-026L, M	FCB-405-0626L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-027L, M	FCB-405-0627L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-028L, M	FCB-405-0628L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-029L, M	FCB-405-0629L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-030L, M	FCB-405-0630L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-031L, M	FCB-405-0631L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-032L, M	FCB-405-0632L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-033L, M	FCB-405-0633L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/6-034L, M	FCB-405-0634L, M	83536-902-04	/6	Tyco Electronics/CII Relays
M83536/9-001L, M	BR246-20C1-6V-001L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-002L, M	BR246-20B1-6V-002L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-003L, M	BR246-20A1-6V-003L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-004L, M	BR246-20C2-6V-004L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-005L, M	BR246-20B2-6V-005L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-006L, M	BR246-20A2-6V-006L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-007L, M	BR246-20C3-6V-007L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-008L, M	BR246-20B3-6V-008L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-009L, M	BR246-20G3-6V-009L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-010L, M	BR246-80C1-12V-010L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-011L, M	BR246-80B1-12V-011L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-012L, M	BR246-80A1-12V-012L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-013L, M	BR246-80C2-12V-013L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-014L, M	BR246-80B2-12V-014L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-015L, M	BR246-80A2-12V-015L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-016L, M	BR246-80C3-12V-016L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-017L, M	BR246-80B3-12V-017L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-018L, M	BR246-80G3-12V-018L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-019L, M	BR246-320C1-28V-019L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-020L, M	BR246-320B1-28V-020L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-021L, M	BR246-320A1-28V-021L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-022L, M	BR246-320C2-28V-022L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-023L, M	BR246-320B2-28V-023L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-024L, M	BR246-320A2-28V-024L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-025L, M	BR246-320C3-28V-025L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-026L, M	BR246-320B3-28V-026L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-027L, M	BR246-320G3-28V-027L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-028L, M	BR246-320B2-28V-028L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-029L, M	BR246-320A2-28V-029L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-030L, M	BR246-1000C1-48V-030L, M	83536-98-0187	/9	Babcock, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/9-031L, M	BR246-1000B1-48V-031L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-032L, M	BR246-1000A1-48V-032L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-033L, M	BR246-1000C2-48V-033L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-034L, M	BR246-1000B2-48V-034L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-035L, M	BR246-1000A2-48V-035L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-036L, M	BR246-1000C3-48V-036L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-037L, M	BR246-1000B3-48V-037L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-038L, M	BR246-1000G3-48V-038L, M	83536-98-0187	/9	Babcock, Inc.
M83536/9-010L, M	E2100201ETL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-011L, M	E2100201ATL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-012L, M	E2100201BGL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-013L, M	E2100203ETL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-014L, M	E2100203ATL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-015L, M	E2100203BGL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-016L, M	E2100207ETL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-017L, M	E2100207ATL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-018L, M	E2100207FTL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-019L, M	E2100401ETL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-020L, M	E2100401ATL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-021L, M	E2100401BGL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-022L, M	E2100403ETL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-023L, M	E2100403ATL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-024L, M	E2100403BGL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-025L, M	E2100407ETL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-026L, M	E2100407ATL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-027L, M	E2100407FTL, M	83536-98-0144	/9	DRI Relays, Inc.
M83536/9-010L, M	M300-A1B-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-012L, M	M300-A4B-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-013L, M	M300-D1B-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-015L, M	M300-D4B-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-016L, M	M300-J1B-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-019L, M	M300-A1A-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-021L, M	M300-A4A-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-022L, M	M300-D1A-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-024L, M	M300-D4A-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-025L, M	M300-J1A-004L, M	83536-713-03	/9	Leach International Europe S.A.
M83536/9-001L, M	J-A1C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-002L, M	J-A2C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-003L, M	J-A4C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-004L, M	J-D1C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-005L, M	J-D2C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-006L, M	J-D4C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-007L, M	J-J1C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-008L, M	J-J2C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-009L, M	J-J7C-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-010L, M	J-A1B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-011L, M	J-A2B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-012L, M	J-A4B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-013L, M	J-D1B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-014L, M	J-D2B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-015L, M	J-D4B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-016L, M	J-J1B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-017L, M	J-J2B-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-018L, M	J-J7B-300L, M	83536-98-0123	/9	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/9-019L, M	J-A1A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-020L, M	J-A2A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-021L, M	J-A4A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-022L, M	J-D1A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-023L, M	J-D2A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-024L, M	J-D4A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-025L, M	J-J1A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-026L, M	J-J2A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-027L, M	J-J7A-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-030L, M	J-A1M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-031L, M	J-A2M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-032L, M	J-A4M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-033L, M	J-D1M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-034L, M	J-D2M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-035L, M	J-D4M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-036L, M	J-J1M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-037L, M	J-J2M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-038L, M	J-J7M-300L, M	83536-98-0123	/9	Leach International North America
M83536/9-010L, M	316 200 E 12VccL, M	83536-571-03	/9	STPI
M83536/9-011L, M	316 217 12VccL, M	83536-571-03	/9	STPI
M83536/9-012L, M	316 200 D 12VccL, M	83536-571-03	/9	STPI
M83536/9-013L, M	316 203 E 12VccL, M	83536-571-03	/9	STPI
M83536/9-014L, M	316 230 12VccL, M	83536-571-03	/9	STPI
M83536/9-015L, M	316 203 D 12VccL, M	83536-571-03	/9	STPI
M83536/9-016L, M	316 208 E 12VccL, M	83536-571-03	/9	STPI
M83536/9-017L, M	316 238 12VccL, M	83536-571-03	/9	STPI
M83536/9-018L, M	316 248 E 12VccL, M	83536-571-03	/9	STPI
M83536/9-019L, M	316 200 E 28VccL, M	83536-571-03	/9	STPI
M83536/9-020L, M	316 217 28VccL, M	83536-571-03	/9	STPI
M83536/9-021L, M	316 200 D 28VccL, M	83536-571-03	/9	STPI
M83536/9-022L, M	316 203 E 28VccL, M	83536-571-03	/9	STPI
M83536/9-023L, M	316 230 28VccL, M	83536-571-03	/9	STPI
M83536/9-024L, M	316 203 D 28VccL, M	83536-571-03	/9	STPI
M83536/9-025L, M	316 208 E 28VccL, M	83536-571-03	/9	STPI
M83536/9-026L, M	316 238 28VccL, M	83536-571-03	/9	STPI
M83536/9-027L, M	316 248 E 28VccL, M	83536-571-03	/9	STPI
M83536/9-001L, M	FCA-210-0901L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-002L, M	FCA-210-0902L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-003L, M	FCA-210-0903L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-004L, M	FCA-210-0904L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-005L, M	FCA-210-0905L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-006L, M	FCA-210-0906L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-007L, M	FCA-210-0907L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-008L, M	FCA-210-0908L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-009L, M	FCA-210-0909L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-010L, M	FCA-210-0910L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-011L, M	FCA-210-0911L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-012L, M	FCA-210-0912L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-013L, M	FCA-210-0913L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-014L, M	FCA-210-0914L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-015L, M	FCA-210-0915L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-016L, M	FCA-210-0916L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-017L, M	FCA-210-0917L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-018L, M	FCA-210-0918L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-019L, M	FCA-210-0919L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/9-020L, M	FCA-210-0920L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-021L, M	FCA-210-0921L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-022L, M	FCA-210-0922L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-023L, M	FCA-210-0923L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-024L, M	FCA-210-0924L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-025L, M	FCA-210-0925L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-026L, M	FCA-210-0926L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-027L, M	FCA-210-0927L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-030L, M	FCA-210-0930L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-031L, M	FCA-210-0931L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-032L, M	FCA-210-0932L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-033L, M	FCA-210-0933L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-034L, M	FCA-210-0934L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-035L, M	FCA-210-0935L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-036L, M	FCA-210-0936L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-037L, M	FCA-210-0937L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/9-038L, M	FCA-210-0938L, M	83536-98-0201, 83536-160-99	/9	Tyco Electronics/CII Relays
M83536/10-001L, M	BR246D-20C1-6V-001L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-002L, M	BR246D-20B1-6V-002L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-003L, M	BR246D-20A1-6V-003L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-004L, M	BR246D-20C2-6V-004L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-005L, M	BR246D-20B2-6V-005L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-006L, M	BR246D-20A2-6V-006L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-007L, M	BR246D-20C3-6V-007L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-008L, M	BR246D-20B3-6V-008L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-009L, M	BR246D-20G3-6V-009L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-010L, M	BR246D-80C1-12V-010L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-011L, M	BR246D-80B1-12V-011L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-012L, M	BR246D-80A1-12V-012L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-013L, M	BR246D-80C2-12V-013L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-014L, M	BR246D-80B2-12V-014L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-015L, M	BR246D-80A2-12V-015L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-016L, M	BR246D-80C3-12V-016L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-017L, M	BR246D-80B3-12V-017L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-018L, M	BR246D-80G3-12V-018L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-019L, M	BR246D-320C1-28V-019L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-020L, M	BR246D-320B1-28V-020L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-021L, M	BR246D-320A1-28V-021L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-022L, M	BR246D-320C2-28V-022L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-023L, M	BR246D-320B2-28V-023L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-024L, M	BR246D-320A2-28V-024L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-025L, M	BR246D-320C3-28V-025L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-026L, M	BR246D-320B3-28V-026L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-027L, M	BR246D-320G3-28V-027L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-029L, M	BR246D-1000C1-48V-029L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-030L, M	BR246D-1000B1-48V-030L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-031L, M	BR246D-1000A1-48V-031L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-032L, M	BR246D-1000C2-48V-032L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-033L, M	BR246D-1000B2-48V-033L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-034L, M	BR246D-1000A2-48V-034L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-035L, M	BR246D-1000C3-48V-035L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-036L, M	BR246D-1000B3-48V-036L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-037L, M	BR246D-1000G3-48V-037L, M	83536-98-0182	/10	Babcock, Inc.
M83536/10-010L, M	ES2100201CTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-011L, M	ES2100201ATL, M	83536-98-0145	/10	DRI Relays, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/10-012L, M	ES2100201BGL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-013L, M	ES2100203CTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-014L, M	ES2100203ATL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-015L, M	ES2100203BGL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-016L, M	ES2100207CTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-017L, M	ES2100207ATL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-018L, M	ES2100207FTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-019L, M	ES2100401CTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-020L, M	ES2100401ATL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-021L, M	ES2100401BGL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-022L, M	ES2100402CTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-023L, M	ES2100402ATL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-024L, M	ES2100402BGL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-025L, M	ES2100403CTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-026L, M	ES2100403ATL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-027L, M	ES2100403FTL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-028L, M	ES2100009GGL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-038L, M	ES2102803BGL, M	83536-98-0145	/10	DRI Relays, Inc.
M83536/10-010L, M	M300-A1R-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-012L, M	M300-A4R-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-013L, M	M300-D1R-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-015L, M	M300-D4R-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-016L, M	M300-J1R-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-019L, M	M300-A1N-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-021L, M	M300-A4N-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-022L, M	M300-D1N-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-024L, M	M300-D4N-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-025L, M	M300-J1N-004L, M	83536-713-03	/10	Leach International Europe S.A.
M83536/10-001L, M	J-A1V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-002L, M	J-A2V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-003L, M	J-A4V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-004L, M	J-D1V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-005L, M	J-D2V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-006L, M	J-D4V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-007L, M	J-J1V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-008L, M	J-J2V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-009L, M	J-J7V-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-010L, M	J-A1R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-011L, M	J-A2R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-012L, M	J-A4R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-013L, M	J-D1R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-014L, M	J-D2R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-015L, M	J-D4R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-016L, M	J-J1R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-017L, M	J-J2R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-018L, M	J-J7R-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-019L, M	J-A1N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-020L, M	J-A2N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-021L, M	J-A4N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-022L, M	J-D1N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-023L, M	J-D2N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-024L, M	J-D4N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-025L, M	J-J1N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-026L, M	J-J2N-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-027L, M	J-J7N-300L, M	83536-98-0124	/10	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/10-029L, M	J-A1W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-030L, M	J-A2W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-031L, M	J-A4W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-032L, M	J-D1W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-033L, M	J-D2W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-034L, M	J-D4W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-035L, M	J-J1W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-036L, M	J-J2W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-037L, M	J-J7W-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-038L, M	J-D4A-300L, M	83536-98-0124	/10	Leach International North America
M83536/10-010L, M	316 200 EP 12VccL, M	83536-571-03	/10	STPI
M83536/10-011L, M	316 217 P 12VccL, M	83536-571-03	/10	STPI
M83536/10-012L, M	316 200 DP 12VccL, M	83536-571-03	/10	STPI
M83536/10-013L, M	316 203 EP 12VccL, M	83536-571-03	/10	STPI
M83536/10-014L, M	316 230 P 12VccL, M	83536-571-03	/10	STPI
M83536/10-015L, M	316 203 DP 12VccL, M	83536-571-03	/10	STPI
M83536/10-016L, M	316 208 EP 12VccL, M	83536-571-03	/10	STPI
M83536/10-017L, M	316 238 P 12VccL, M	83536-571-03	/10	STPI
M83536/10-018L, M	316 248 EP 12VccL, M	83536-571-03	/10	STPI
M83536/10-019L, M	316 200 EP 28VccL, M	83536-571-03	/10	STPI
M83536/10-020L, M	316 217 P 28VccL, M	83536-571-03	/10	STPI
M83536/10-021L, M	316 200 DP 28VccL, M	83536-571-03	/10	STPI
M83536/10-022L, M	316 203 EP 28VccL, M	83536-571-03	/10	STPI
M83536/10-023L, M	316 230 P 28VccL, M	83536-571-03	/10	STPI
M83536/10-024L, M	316 203 DP 28VccL, M	83536-571-03	/10	STPI
M83536/10-025L, M	316 208 EP 28VccL, M	83536-571-03	/10	STPI
M83536/10-026L, M	316 238 P 28VccL, M	83536-571-03	/10	STPI
M83536/10-027L, M	316 248 EP 28VccL, M	83536-571-03	/10	STPI
M83536/10-038L, M	316 203 DP 28VccL, M	83536-571-03	/10	STPI
M83536/10-001L, M	FCA-210-1001L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-003L, M	FCA-210-1003L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-004L, M	FCA-210-1004L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-005L, M	FCA-210-1005L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-006L, M	FCA-210-1006L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-007L, M	FCA-210-1007L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-008L, M	FCA-210-1008L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-009L, M	FCA-210-1009L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-010L, M	FCA-210-1010L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-011L, M	FCA-210-1011L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-012L, M	FCA-210-1012L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-013L, M	FCA-210-1013L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-014L, M	FCA-210-1014L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-016L, M	FCA-210-1016L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-017L, M	FCA-210-1017L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-018L, M	FCA-210-1018L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-019L, M	FCA-210-1020L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-020L, M	FCA-210-1020L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-021L, M	FCA-210-1021L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-022L, M	FCA-210-1022L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-023L, M	FCA-210-1023L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-024L, M	FCA-210-1024L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-025L, M	FCA-210-1025L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-026L, M	FCA-210-1026L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-027L, M	FCA-210-1027L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-029L, M	FCA-210-1029L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/10-030L, M	FCA-210-1030L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-031L, M	FCA-210-1031L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-032L, M	FCA-210-1032L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-033L, M	FCA-210-1033L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-034L, M	FCA-210-1034L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-035L, M	FCA-210-1035L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-036L, M	FCA-210-1036L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-037L, M	FCA-210-1037L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/10-038L, M	FCA-210-1038L, M	83536-98-0202, 83536-160-99	/10	Tyco Electronics/CII Relays
M83536/11-001L	EA2100704ATL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-002L	EA2100704CGL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-005L	EA2100804ETL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-006L	EA2100804ATL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-007L	EA2100804CGL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-008L	EA2100708ATL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-009L	EA2100808ATL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-010L	EA2100802ETL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-011L	EA2100802ATL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-012L	EA2100709CGL	83536-98-0155	/11	DRI Relays, Inc.
M83536/11-001L	JA-D2F-300L	83536-98-0209	/11	Leach International North America
M83536/11-002L	JA-D4F-300L	83536-98-0209	/11	Leach International North America
M83536/11-005L	JA-D1K-300L	83536-98-0209	/11	Leach International North America
M83536/11-006L	JA-D2K-300L	83536-98-0209	/11	Leach International North America
M83536/11-007L	JA-D4K-300L	83536-98-0209	/11	Leach International North America
M83536/11-008L	JA-J2F-300L	83536-98-0209	/11	Leach International North America
M83536/11-009L	JA-J2K-300L	83536-98-0209	/11	Leach International North America
M83536/11-010L	JA-A1K-300L	83536-98-0209	/11	Leach International North America
M83536/11-011L	JA-A2K-300L	83536-98-0209	/11	Leach International North America
M83536/11-012L	JA-B4F-300L	83536-98-0209	/11	Leach International North America
M83536/11-001L, M	316 230 115V 400HzL, M	83536-079-01	/11	STPI
M83536/11-002L, M	316 203 D 115V 400HzL, M	83536-079-01	/11	STPI
M83536/11-005L, M	316 203 E 115V 50/60/400HzL, M	83536-079-01	/11	STPI
M83536/11-006L, M	316 230 115V 50/60/400HzL, M	83536-079-01	/11	STPI
M83536/11-007L, M	316 203 D 115V 50/60/400HzL, M	83536-079-01	/11	STPI
M83536/11-008L, M	316 238 115V 400HzL, M	83536-079-01	/11	STPI
M83536/11-009L, M	316 238 115V 50/60/400HzL, M	83536-079-01	/11	STPI
M83536/11-010L, M	316 200 E 115V 50/60/400HzL, M	83536-079-01	/11	STPI
M83536/11-011L, M	316 217 115V 50/60/400HzL, M	83536-079-01	/11	STPI
M83536/12-001L	BR247-38B2-6V-001L	83536-98-0210	/12	Babcock, Inc.
M83536/12-002L	BR247-38A2-6V-002L	83536-98-0210	/12	Babcock, Inc.
M83536/12-003L	BR247-38B3-6V-003L	83536-98-0210	/12	Babcock, Inc.
M83536/12-004L	BR247-150B2-12V-004L	83536-98-0210	/12	Babcock, Inc.
M83536/12-005L	BR247-150A2-12V-005L	83536-98-0210	/12	Babcock, Inc.
M83536/12-006L	BR247-150B3-12V-006L	83536-98-0210	/12	Babcock, Inc.
M83536/12-007L	BR247-600B2-28V-007L	83536-98-0210	/12	Babcock, Inc.
M83536/12-008L	BR247-600A2-28V-008L	83536-98-0210	/12	Babcock, Inc.
M83536/12-009L	BR247-600B3-28V-009L	83536-98-0210	/12	Babcock, Inc.
M83536/12-010L	BR247-1550B2-48V-0010L	83536-98-0210	/12	Babcock, Inc.
M83536/12-011L	BR247-1550A2-48V-0011L	83536-98-0210	/12	Babcock, Inc.
M83536/12-012L	BR247-1550B3-48V-0012L	83536-98-0210	/12	Babcock, Inc.
M83536/12-004L	EL2100203ATL	83536-98-0215	/12	DRI Relays, Inc.
M83536/12-005L	EL2100203CGL	83536-98-0215	/12	DRI Relays, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/12-006L	EL2100208ATL	83536-98-0215	/12	DRI Relays, Inc.
M83536/12-007L	EL2100403ATL	83536-98-0215	/12	DRI Relays, Inc.
M83536/12-008L	EL2100403CGL	83536-98-0215	/12	DRI Relays, Inc.
M83536/12-009L	EL2100408ATL	83536-98-0215	/12	DRI Relays, Inc.
M83536/12-001L	JL-D2C-300L	83536-98-0162	/12	Leach International North America
M83536/12-002L	JL-D4C-300L	83536-98-0162	/12	Leach International North America
M83536/12-003L	JL-J2C-300L	83536-98-0162	/12	Leach International North America
M83536/12-004L	JL-D2B-300L	83536-98-0162	/12	Leach International North America
M83536/12-005L	JL-D4B-300L	83536-98-0162	/12	Leach International North America
M83536/12-006L	JL-J2B-300L	83536-98-0162	/12	Leach International North America
M83536/12-007L	JL-D2A-300L	83536-98-0162	/12	Leach International North America
M83536/12-008L	JL-D4A-300L	83536-98-0162	/12	Leach International North America
M83536/12-009L	JL-J2A-300L	83536-98-0162	/12	Leach International North America
M83536/13-001L	BR247D-38B2-6V-01L	83536-98-0211	/13	Babcock, Inc.
M83536/13-002L	BR247D-38A2-6V-002L	83536-98-0211	/13	Babcock, Inc.
M83536/13-003L	BR247D-38B3-6V-003L	83536-98-0211	/13	Babcock, Inc.
M83536/13-004L	BR247D-150B2-12V-004L	83536-98-0211	/13	Babcock, Inc.
M83536/13-005L	BR247D-150AB2-12V-005L	83536-98-0211	/13	Babcock, Inc.
M83536/13-006L	BR247D-150B3-12V-006L	83536-98-0211	/13	Babcock, Inc.
M83536/13-007L	BR247D-600B2-28V-007L	83536-98-0211	/13	Babcock, Inc.
M83536/13-008L	BR247D-600A2-28V-008L	83536-98-0211	/13	Babcock, Inc.
M83536/13-009L	BR247D-600B3-28V-009L	83536-98-0211	/13	Babcock, Inc.
M83536/13-011L	BR247D-1550B2-48V-011L	83536-98-0211	/13	Babcock, Inc.
M83536/13-012L	BR147D-1550A2-48V-012L	83536-98-0211	/13	Babcock, Inc.
M83536/13-013L	BR247D-1550B3-48V-013L	83536-98-0211	/13	Babcock, Inc.
M83536/13-004L	ELS2100203ATL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-005L	ELS2100203CGL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-006L	ELS2100208ATL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-007L	ELS2100403ATL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-008L	ELS2100403CGL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-009L	ELS2100408ATL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-010L	ELS2100409GGL	83536-98-0216	/13	DRI Relays, Inc.
M83536/13-001L	JL-D2V-300L	83536-98-0163	/13	Leach International North America
M83536/13-002L	JL-D4V-300L	83536-98-0163	/13	Leach International North America
M83536/13-003L	JL-J2V-300L	83536-98-0163	/13	Leach International North America
M83536/13-004L	JL-D2R-300L	83536-98-0163	/13	Leach International North America
M83536/13-005L	JL-D4R-300L	83536-98-0163	/13	Leach International North America
M83536/13-006L	JL-J2R-300L	83536-98-0163	/13	Leach International North America
M83536/13-007L	JL-D2N-300L	83536-98-0163	/13	Leach International North America
M83536/13-008L	JL-D4N-300L	83536-98-0163	/13	Leach International North America
M83536/13-009L	JL-B4N-300L	83536-98-0163	/13	Leach International North America
M83536/13-010L	JL-B4N-300L	83536-98-0163	/13	Leach International North America
M83536/15-001L, M	BR230-20C1-6V-001L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-002L, M	BR230-20B1-6V-002L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-003L, M	BR230-20A1-6V-003L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-004L, M	BR230-20C2-6V-004L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-005L, M	BR230-20B2-6V-005L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-006L, M	BR230-20A2-6V-006L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-007L, M	BR230-20C3-6V-007L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-008L, M	BR230-20B3-6V-008L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-009L, M	BR230-78C1-12V-009L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-010L, M	BR230-78B1-12V-010L, M	83536-98-0169	/15	Babcock, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/15-011L, M	BR230-78A1-12V-011L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-012L, M	BR230-78C2-12V-012L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-013L, M	BR230-78B2-12V-013L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-014L, M	BR230-78A2-12V-014L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-015L, M	BR230-78C3-12V-015L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-016L, M	BR230-78B3-12V-016L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-017L, M	BR230-290C1-28V-017L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-018L, M	BR230-290B1-28V-018L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-019L, M	BR230-290A1-28V-019L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-020L, M	BR230-290C2-28V-020L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-021L, M	BR230-290B2-28V-021L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-022L, M	BR230-290A2-28V-022L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-023L, M	BR230-290C3-28V-023L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-024L, M	BR230-290B3-28V-024L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-025L, M	BR230-890C1-48V-025L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-026L, M	BR230-890B1-48V-026L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-027L, M	BR230-890A1-48V-027L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-028L, M	BR230-890C2-48V-028L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-029L, M	BR230-890B2-48V-029L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-030L, M	BR230-890A2-48V-030L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-031L, M	BR230-890C3-48V-031L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-032L, M	BR230-890B3-48V-032L, M	83536-98-0169	/15	Babcock, Inc.
M83536/15-009L, M	E4100201ETL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-010L, M	E4100201ATL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-011L, M	E4100201BGL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-012L, M	E4100202ETL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-013L, M	E4100202ATL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-014L, M	E4100202BGL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-015L, M	E4100203ETL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-016L, M	E4100203ATL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-017L, M	E4100401ETL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-018L, M	E4100401ATL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-019L, M	E4100401BGL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-020L, M	E4100402ETL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-021L, M	E4100402ATL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-022L, M	E4100402BGL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-023L, M	E4100403ETL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-024L, M	E4100403-ATL, M	83536-98-0146	/15	DRI Relays, Inc.
M83536/15-009L, M	M400-A1B-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-010L, M	M400-A2B-004L, M	83536-1844-07	/15	Leach International Europe S.A.
M83536/15-011L, M	M400-A4B-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-012L, M	M400-D1B-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-013L, M	M400-D2B-004L, M	83536-1844-07	/15	Leach International Europe S.A.
M83536/15-014L, M	M400-D4B-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-015L, M	M400-J1B-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-016L, M	M400-J2B-004L, M	83536-1844-07	/15	Leach International Europe S.A.
M83536/15-017L, M	M400-A1A-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-018L, M	M400-A2A-004L, M	83536-1844-07	/15	Leach International Europe S.A.
M83536/15-019L, M	M400-A4A-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-020L, M	M400-D1A-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-021L, M	M400-D2A-004L, M	83536-1844-07	/15	Leach International Europe S.A.
M83536/15-022L, M	M400-D4A-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-023L, M	M400-J1A-004L, M	83536-714-03	/15	Leach International Europe S.A.
M83536/15-024L, M	M400-J2A-004L, M	83536-1844-07	/15	Leach International Europe S.A.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/15-001L, M	K-A1C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-002L, M	K-A2C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-003L, M	K-A4C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-004L, M	K-D1C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-005L, M	K-D2C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-006L, M	K-D4C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-007L, M	K-J1C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-008L, M	K-J2C-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-009L, M	K-A1B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-010L, M	K-A2B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-011L, M	K-A4B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-012L, M	K-D1B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-013L, M	K-D2B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-014L, M	K-D4B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-015L, M	K-J1B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-016L, M	K-J2B-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-017L, M	K-A1A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-018L, M	K-A2A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-019L, M	K-A4A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-020L, M	K-D1A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-021L, M	K-D2A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-022L, M	K-D4A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-023L, M	K-J1A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-024L, M	K-J2A-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-025L, M	K-A1M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-026L, M	K-A2M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-027L, M	K-A4M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-028L, M	K-D1M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-029L, M	K-D2M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-030L, M	K-D4M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-031L, M	K-J1M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-032L, M	K-J2M-300L, M	83536-98-0171	/15	Leach International North America
M83536/15-001L, M	FCA-410-1501L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-002L, M	FCA-410-1502L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-003L, M	FCA-410-1503L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-004L, M	FCA-410-1504L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-005L, M	FCA-410-1505L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-006L, M	FCA-410-1506L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-007L, M	FCA-410-1507L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-008L, M	FCA-410-1508L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-009L, M	FCA-410-1509L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-010L, M	FCA-410-1510L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-011L, M	FCA-410-1511L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-012L, M	FCA-410-1512L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-013L, M	FCA-410-1513L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-014L, M	FCA-410-1514L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-015L, M	FCA-410-1515L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-016L, M	FCA-410-1516L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-017L, M	FCA-410-1517L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-018L, M	FCA-410-1518L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-019L, M	FCA-410-1519L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-020L, M	FCA-410-1520L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-021L, M	FCA-410-1521L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-022L, M	FCA-410-1522L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-023L, M	FCA-410-1523L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-024L, M	FCA-410-1524L, M	83536-901-04	/15	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/15-025L, M	FCA-410-1525L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-026L, M	FCA-410-1526L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-027L, M	FCA-410-1527L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-028L, M	FCA-410-1528L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-029L, M	FCA-410-1529L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-030L, M	FCA-410-1530L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-031L, M	FCA-410-1531L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/15-032L, M	FCA-410-1532L, M	83536-901-04	/15	Tyco Electronics/CII Relays
M83536/16-001L, M	BR230D-20C1-6V-001L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-002L, M	BR230D-20B1-6V-002L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-003L, M	BR230D-20A1-6V-003L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-004L, M	BR230D-20C2-6V-004L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-005L, M	BR230D-20B2-6V-005L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-006L, M	BR230D-20A2-6V-006L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-007L, M	BR230D-20C3-6V-007L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-008L, M	BR230D-20B3-6V-008L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-009L, M	BR230D-78C1-12V-009L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-010L, M	BR230D-78B1-12V-010L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-011L, M	BR230D-78A1-12V-011L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-012L, M	BR230D-78C2-12V-012L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-013L, M	BR230D-78B2-12V-013L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-014L, M	BR230D-78A2-12V-014L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-015L, M	BR230D-78C3-12V-015L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-016L, M	BR230D-78B3-12V-016L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-017L, M	BR230D-290C1-28V-017L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-018L, M	BR230D-290B1-28V-018L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-019L, M	BR230D-290A1-28V-019L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-020L, M	BR230D-290C2-28V-020L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-021L, M	BR230D-290B2-28V-021L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-022L, M	BR230D-290A2-28V-022L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-023L, M	BR230D-290C3-28V-023L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-024L, M	BR230D-290B3-28V-024L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-026L, M	BR230D-890C1-48V-026L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-027L, M	BR230D-890B1-48V-027L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-028L, M	BR230D-890A1-48V-028L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-029L, M	BR230D-890C2-48V-029L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-030L, M	BR230D-890B2-48V-030L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-031L, M	BR230D-890A2-48V-031L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-032L, M	BR230D-890C3-48V-032L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-033L, M	BR230D-890B3-48V-033L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-034L, M	BR230D-S0175L, M	83536-98-0170	/16	Babcock, Inc.
M83536/16-009L, M	ES4100201ETL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-010L, M	ES4100201ATL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-011L, M	ES4100201BGL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-012L, M	ES4100202ETL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-013L, M	ES4100202ATL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-014L, M	ES4100202BGL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-015L, M	ES4100203ETL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-016L, M	ES4100203ATL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-017L, M	ES4100401ETL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-018L, M	ES4100401ATL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-019L, M	ES4100401BGL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-020L, M	ES4100402ETL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-021L, M	ES4100402ATL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-022L, M	ES4100402BGL, M	83536-98-0147	/16	DRI Relays, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/16-023L, M	ES4100403ETL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-024L, M	ES4100403ATL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-025L, M	ES4100009GGL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-034L, M	ES4102802BGL, M	83536-98-0147	/16	DRI Relays, Inc.
M83536/16-009L, M	M400-A1R-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-010L, M	M400-A2R-004L, M	83536-1844-07	/16	Leach International Europe S.A.
M83536/16-011L, M	M400-A4R-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-012L, M	M400-D1R-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-013L, M	M400-D2R-004L, M	83536-1844-07	/16	Leach International Europe S.A.
M83536/16-014L, M	M400-D4R-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-015L, M	M400-J1R-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-016L, M	M400-J2R-004L, M	83536-1844-07	/16	Leach International Europe S.A.
M83536/16-017L, M	M400-A1N-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-018L, M	M400-A2N-004L, M	83536-1844-07	/16	Leach International Europe S.A.
M83536/16-019L, M	M400-A4N-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-020L, M	M400-D1N-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-021L, M	M400-D2N-004L, M	83536-1844-07	/16	Leach International Europe S.A.
M83536/16-022L, M	M400-D4N-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-023L, M	M400-J1N-004L, M	83536-714-03	/16	Leach International Europe S.A.
M83536/16-024L, M	M400-J2N-004L, M	83536-1844-07	/16	Leach International Europe S.A.
M83536/16-001L, M	K-A1V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-002L, M	K-A2V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-003L, M	K-A4V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-004L, M	K-D1V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-005L, M	K-D2V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-006L, M	K-D4V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-007L, M	K-J1V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-008L, M	K-J2V-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-009L, M	K-A1R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-010L, M	K-A2R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-011L, M	K-A4R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-012L, M	K-D1R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-013L, M	K-D2R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-014L, M	K-D4R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-015L, M	K-J1R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-016L, M	K-J2R-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-017L, M	K-A1N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-018L, M	K-A2N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-019L, M	K-A4N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-020L, M	K-D1N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-021L, M	K-D2N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-022L, M	K-D4N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-023L, M	K-J1N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-024L, M	K-J2N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-025L, M	K-B4N-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-026L, M	K-A1W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-027L, M	K-A2W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-028L, M	K-A4W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-029L, L	K-D1W-300L, L	83536-98-0172	/16	Leach International North America
M83536/16-030L, M	K-D2W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-031L, M	K-D4W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-032L, M	K-J1W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-033L, M	K-J2W-300L, M	83536-98-0172	/16	Leach International North America
M83536/16-034L, M	K-D4A-304L, M	83536-98-0172	/16	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/16-001L, M	FCA-410-1601L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-003L, M	FCA-410-1603L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-004L, M	FCA-410-1604L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-005L, M	FCA-410-1605L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-006L, M	FCA-410-1606L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-007L, M	FCA-410-1607L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-008L, M	FCA-410-1608L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-009L, M	FCA-410-1609L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-010L, M	FCA-410-1610L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-011L, M	FCA-410-1611L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-012L, M	FCA-410-1612L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-013L, M	FCA-410-1613L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-015L, M	FCA-410-1615L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-016L, M	FCA-410-1616L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-017L, M	FCA-410-1617L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-018L, M	FCA-410-1618L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-019L, M	FCA-410-1619L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-020L, M	FCA-410-1620L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-021L, M	FCA-410-1621L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-022L, M	FCA-410-1622L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-023L, M	FCA-410-1623L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-024L, M	FCA-410-1624L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-026L, M	FCA-410-1626L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-027L, M	FCA-410-1627L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-028L, M	FCA-410-1628L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-029L, M	FCA-410-1629L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-030L, M	FCA-410-1630L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-031L, M	FCA-410-1631L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-033L, M	FCA-410-1633L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/16-034L, M	FCA-410-1634L, M	83536-901-04	/16	Tyco Electronics/CII Relays
M83536/17-001L	EA4100702ATL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-002L	EA4100702CGL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-003L	EA4100802JTL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-004L	EA4100802ATL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-005L	EA4100802CGL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-006L	EA4100703ATL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-007L	EA4100803ATL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-008L	EA4100801JTL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-009L	EA4100801ATL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-010L	EA4100709HGL	83536-98-0156	/17	DRI Relays, Inc.
M83536/17-001L	KA-D2F-300L	83536-98-0203	/17	Leach International North America
M83536/17-002L	KA-D4F-300L	83536-98-0203	/17	Leach International North America
M83536/17-003L	KA-D1K-300L	83536-98-0203	/17	Leach International North America
M83536/17-004L	KA-D2F-300L	83536-98-0203	/17	Leach International North America
M83536/17-005L	KA-D4F-300L	83536-98-0203	/17	Leach International North America
M83536/17-006L	KA-J2F-300L	83536-98-0203	/17	Leach International North America
M83536/17-007L	KA-J2K-300L	83536-98-0203	/17	Leach International North America
M83536/17-008L	KA-A1K-300L	83536-98-0203	/17	Leach International North America
M83536/17-009L	KA-A2K-300L	83536-98-0203	/17	Leach International North America
M83536/18-001L	BR231-28B2-6V-001L	83536-98-0166	/18	Babcock, Inc.
M83536/18-002L	BR231-28A2-6V-002L	83536-98-0166	/18	Babcock, Inc.
M83536/18-003L	BR231-28B3-6V-003L	83536-98-0166	/18	Babcock, Inc.
M83536/18-004L	BR231-112B2-12V-004L	83536-98-0166	/18	Babcock, Inc.
M83536/18-005L	BR231-112A2-12V-005L	83536-98-0166	/18	Babcock, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/18-006L	BR231-112B3-12V-006L	83536-98-0166	/18	Babcock, Inc.
M83536/18-007L	BR231-450B2-28V-007L	83536-98-0166	/18	Babcock, Inc.
M83536/18-008L	BR231-450A2-28V-008L	83536-98-0166	/18	Babcock, Inc.
M83536/18-009L	BR231-450B3-28V-009L	83536-98-0166	/18	Babcock, Inc.
M83536/18-011L	BR231-1500B2-48V-011L	83536-98-0166	/18	Babcock, Inc.
M83536/18-012L	BR231-1500A2-48V-012L	83536-98-0166	/18	Babcock, Inc.
M83536/18-013L	BR231-1500B3-48V-013L	83536-98-0166	/18	Babcock, Inc.
M83536/18-004L	EL4100202ATL	83536-98-0217	/18	DRI Relays, Inc.
M83536/18-005L	EL4100202ETL	83536-98-0217	/18	DRI Relays, Inc.
M83536/18-006L	EL4100203ATL	83536-98-0217	/18	DRI Relays, Inc.
M83536/18-007L	EL4100402ATL	83536-98-0217	/18	DRI Relays, Inc.
M83536/18-008L	EL4100402BGL	83536-98-0217	/18	DRI Relays, Inc.
M83536/18-009L	EL4100403ATL	83536-98-0217	/18	DRI Relays, Inc.
M83536/18-001L	KL-D2C-300L	83536-98-0164	/18	Leach International North America
M83536/18-002L	KL-D4C-300L	83536-98-0164	/18	Leach International North America
M83536/18-003L	KL-J2C-300L	83536-98-0164	/18	Leach International North America
M83536/18-004L	KL-D2B-300L	83536-98-0164	/18	Leach International North America
M83536/18-005L	KL-D4B-300L	83536-98-0164	/18	Leach International North America
M83536/18-006L	KL-J2B-300L	83536-98-0164	/18	Leach International North America
M83536/18-007L	KL-D2A-300L	83536-98-0164	/18	Leach International North America
M83536/18-008L	KL-D4A-300L	83536-98-0164	/18	Leach International North America
M83536/18-009L	KL-J2A-300L	83536-98-0164	/18	Leach International North America
M83536/18-010L	KA-B4F-300L	83536-98-0164	/18	Leach International North America
M83536/18-011L	KL-D2M-300L	83536-98-0164	/18	Leach International North America
M83536/18-012L	KL-D4M-300L	83536-98-0164	/18	Leach International North America
M83536/18-013L	KL-J2M-300L	83536-98-0164	/18	Leach International North America
M83536/19-001L	BR231D-28B2-6V-001L	83536-98-0167	/19	Babcock, Inc.
M83536/19-002L	BR231D-28A2-6V-002L	83536-98-0167	/19	Babcock, Inc.
M83536/19-003L	BR231D-28B3-6V-003L	83536-98-0167	/19	Babcock, Inc.
M83536/19-004L	BR231D-112B2-12V-004L	83536-98-0167	/19	Babcock, Inc.
M83536/19-005L	BR231D-112A2-12V-005L	83536-98-0167	/19	Babcock, Inc.
M83536/19-006L	BR231D-112B3-12V-006L	83536-98-0167	/19	Babcock, Inc.
M83536/19-007L	BR231D-450B2-28V-007L	83536-98-0167	/19	Babcock, Inc.
M83536/19-008L	BR231D-450A2-28V-008L	83536-98-0167	/19	Babcock, Inc.
M83536/19-009L	BR231D-450B3-28V-009L	83536-98-0167	/19	Babcock, Inc.
M83536/19-011L	BR231D-1500B2-48V-011L	83536-98-0167	/19	Babcock, Inc.
M83536/19-012L	BR231D-1500A2-48V-012L	83536-98-0167	/19	Babcock, Inc.
M83536/19-013L	BR231D-1500B3-48V-013L	83536-98-0167	/19	Babcock, Inc.
M83536/19-004L	ELS4100202ATL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-005L	ELS4100202ETL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-006L	ELS4100203ATL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-007L	ELS4100402ATL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-008L	ELS4100402BGL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-009L	ELS4100403ATL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-010L	ELS4100409GGL	83536-98-0218	/19	DRI Relays, Inc.
M83536/19-001L	KL-D2V-300L	83536-98-0165	/19	Leach International North America
M83536/19-002L	KL-D4V-300L	83536-98-0165	/19	Leach International North America
M83536/19-003L	KL-J2V-300L	83536-98-0165	/19	Leach International North America
M83536/19-004L	KL-D2R-300L	83536-98-0165	/19	Leach International North America
M83536/19-005L	KL-D4R-300L	83536-98-0165	/19	Leach International North America
M83536/19-006L	KL-J2R-300L	83536-98-0165	/19	Leach International North America
M83536/19-007L	KL-D2N-300L	83536-98-0165	/19	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/19-008L	KL-D4N-300L	83536-98-0165	/19	Leach International North America
M83536/19-009L	KL-J2N-300L	83536-98-0165	/19	Leach International North America
M83536/19-011L	KL-D2W-300L	83536-98-0165	/19	Leach International North America
M83536/19-012L	KL-D4W-300L	83536-98-0165	/19	Leach International North America
M83536/19-013L	KL-J2W-300L	83536-98-0165	/19	Leach International North America
M83536/21-009L, M	E3100201CTL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-010L, M	E3100201ATL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-011L, M	E3100201BGL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-012L, M	E3100202CTL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-013L, M	E3100202ATL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-014L, M	E3100202BGL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-015L, M	E3100203CTL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-016L, M	E3100203ATL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-017L, M	E3100401CTL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-018L, M	E3100401ATL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-019L, M	E3100401BGL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-020L, M	E3100402CTL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-021L, M	E3100402ATL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-022L, M	E3100402BGL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-023L, M	E3100403CTL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-024L, M	E3100403ATL, M	83536-98-0142	/21	DRI Relays, Inc.
M83536/21-018L, M	M230-A2A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-017L, M	M230-A1A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-019L, M	M230-A4A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-020L, M	M230-D1A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-021L, M	M230-D2A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-023L, M	M230-J1A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-024L, M	M230-J2A-004L, M	83536-555-03	/21	Leach International Europe S.A.
M83536/21-001L, M	YC-A1C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-002L, M	YC-A2C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-003L, M	YC-A4C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-004L, M	YC-D1C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-005L, M	YC-D2C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-006L, M	YC-D4C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-007L, M	YC-J1C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-008L, M	YC-J2C-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-009L, M	YC-A1B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-010L, M	YC-A2B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-011L, M	YC-A4B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-012L, M	YC-D1B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-013L, M	YC-D2B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-014L, M	YC-D4B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-015L, M	YC-J1B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-016L, M	YC-J2B-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-017L, M	YC-A1A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-018L, M	YC-A2A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-019L, M	YC-A4A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-020L, M	YC-D1A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-021L, M	YC-D2A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-022L, M	YC-D4A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-023L, M	YC-J1A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-024L, M	YC-J2A-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-025L, M	YC-A1M-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-026L, M	YC-A2M-300L, M	83536-98-0229	/21	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/21-027L, M	YC-A4M-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-028L, M	YC-D1M-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-029L, M	YC-D2M-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-030L, M	YC-D4M-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-031L, M	YC-J1M-300L, M	83536-98-0229	/21	Leach International North America
M83536/21-032L, M	YC-J2M-300L, M	83536-98-0229	/21	Leach International North America
M83536/22-009L, M	ES3100201CTL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-010L, M	ES3100201ATL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-011L, M	ES3100201BGL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-012L, M	ES3100202CTL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-013L, M	ES3100202ATL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-014L, M	ES3100202BGL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-015L, M	ES3100203CTL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-016L, M	ES3100203ATL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-017L, M	ES3100401CTL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-018L, M	ES3100401ATL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-019L, M	ES3100401BGL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-020L, M	ES3100402CTL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-021L, M	ES3100402ATL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-022L, M	ES3100402BGL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-023L, M	ES3100403CTL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-024L, M	ES3100403ATL, M	83536-98-0143	/22	DRI Relays, Inc.
M83536/22-025L, M	ES3100404BGL, M	83536-98-0142	/22	DRI Relays, Inc.
M83536/22-018L, M	M230-A2N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-017L, M	M230-A1N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-019L, M	M230-A4N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-020L, M	M230-D1N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-021L, M	M230-D2N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-023L, M	M230-J1N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-024L, M	M230-J2N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-025L, M	M230-E4N-004L, M	83536-555-03	/22	Leach International Europe S.A.
M83536/22-001L, M	YC-A1V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-002L, M	YC-A2V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-003L, M	YC-A4V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-004L, M	YC-D1V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-005L, M	YC-D2V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-006L, M	YC-D4V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-007L, M	YC-J1V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-008L, M	YC-J2V-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-009L, M	YC-A1R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-010L, M	YC-A2R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-011L, M	YC-A4R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-012L, M	YC-D1R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-013L, M	YC-D2R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-014L, M	YC-D4R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-015L, M	YC-J1R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-016L, M	YC-J2R-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-017L, M	YC-A1N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-018L, M	YC-A2N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-019L, M	YC-A4N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-020L, M	YC-D1N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-021L, M	YC-D2N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-022L, M	YC-D4N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-023L, M	YC-J1N-300L, M	83536-98-0230	/22	Leach International North America

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/22-024L, M	YC-J2N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-025L, M	YC-E4N-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-026L, M	YC-A1W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-027L, M	YC-A2W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-028L, M	YC-A4W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-029L, M	YC-D1W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-030L, M	YC-D2W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-031L, M	YC-D4W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-032L, M	YC-J1W-300L, M	83536-98-0230	/22	Leach International North America
M83536/22-033L, M	YC-J2W-300L, M	83536-98-0230	/22	Leach International North America
M83536/25-001L	E6100402ATL	83536-98-0136	/25	DRI Relays, Inc.
M83536/25-002L	E6100402BGL	83536-98-0136	/25	DRI Relays, Inc.
M83536/25-001L	FSA-610-2501L	83536-98-0175	/25	MSD, Inc.
M83536/25-002L	FSA-610-2502L	83536-98-0175	/25	MSD, Inc.
M83536/26-001L	ES6100402ATL	83536-98-0137	/26	DRI Relays, Inc.
M83536/26-002L	ES6100402BGL	83536-98-0137	/26	DRI Relays, Inc.
M83536/26-001L	FCA-610-2601L	83536-98-0176	/26	MSD, Inc.
M83536/26-002L	FCA-610-2602L	83536-98-0176	/26	MSD, Inc.
M83536/32-001L	BR235-290C2-28V-001L	83536-98-0113	/32	Babcock, Inc.
M83536/32-002L	BR235-290B2-28V-002L	83536-98-0113	/32	Babcock, Inc.
M83536/32-003L	BR235-290A2-28V-003L	83536-98-0113	/32	Babcock, Inc.
M83536/32-004L	BR235-290C3-28V-004L	83536-98-0113	/32	Babcock, Inc.
M83536/32-005L	BR235-290B3-28V-005L	83536-98-0113	/32	Babcock, Inc.
M83536/32-001L	E3250402CTL	83536-98-0219	/32	DRI India
M83536/32-002L	E3250402ATL	83536-98-0219	/32	DRI India
M83536/32-003L	E3250402BGL	83536-98-0219	/32	DRI India
M83536/32-004L	E3250403CTL	83536-98-0219	/32	DRI India
M83536/32-005L	E3250403ATL	83536-98-0219	/32	DRI India
M83536/32-001L	E3250402CTL	83536-98-0219	/32	DRI Relays, Inc.
M83536/32-002L	E3250402ATL	83536-98-0219	/32	DRI Relays, Inc.
M83536/32-003L	E3250402BGL	83536-98-0219	/32	DRI Relays, Inc.
M83536/32-004L	E3250403CTL	83536-98-0219	/32	DRI Relays, Inc.
M83536/32-005L	E3250403ATL	83536-98-0219	/32	DRI Relays, Inc.
M83536/32-001L	KC-D1A-300L	83536-98-0121	/32	Leach International North America
M83536/32-002L	KC-D2A-300L	83536-98-0121	/32	Leach International North America
M83536/32-003L	KC-D4A-300L	83536-98-0121	/32	Leach International North America
M83536/32-004L	KC-J1A-300L	83536-98-0121	/32	Leach International North America
M83536/32-005L	KC-J2A-300L	83536-98-0121	/32	Leach International North America
M83536/32-001L	FCA-325-3201L	83536-98-0206	/32	Tyco Electronics/CII Relays
M83536/32-002L	FCA-325-3202L	83536-98-0206	/32	Tyco Electronics/CII Relays
M83536/32-003L	FCA-325-3203L	83536-98-0206	/32	Tyco Electronics/CII Relays
M83536/32-004L	FCA-325-3204L	83536-98-0206	/32	Tyco Electronics/CII Relays
M83536/32-005L	FCA-325-3205L	83536-98-0206	/32	Tyco Electronics/CII Relays
M83536/33-001L	BR235D-290C2-28V-001L	83536-98-0114	/33	Babcock, Inc.
M83536/33-002L	BR235D-290B2-28V-002L	83536-98-0114	/33	Babcock, Inc.
M83536/33-003L	BR235D-290A2-28V-003L	83536-98-0114	/33	Babcock, Inc.
M83536/33-004L	BR235D-290C3-28V-004L	83536-98-0114	/33	Babcock, Inc.
M83536/33-005L	BR235D-290B3-28V-005L	83536-98-0114	/33	Babcock, Inc.

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/33-002L	ES3250402ATL	83536-98-0220	/33	DRI India
M83536/33-004L	ES3250403CTL	83536-98-0220	/33	DRI India
M83536/33-005L	ES3250403ATL	83536-98-0220	/33	DRI India
M83536/33-001L	ES3250402CTL	83536-98-0220	/33	DRI Relays, Inc.
M83536/33-003L	ES3250402BGL	83536-98-0220	/33	DRI Relays, Inc.
M83536/33-001L	KC-D1N-300L	83536-98-0122	/33	Leach International North America
M83536/33-002L	KC-D2N-300L	83536-98-0122	/33	Leach International North America
M83536/33-003L	KC-D4N-300L	83536-98-0122	/33	Leach International North America
M83536/33-004L	KC-J1N-300L	83536-98-0122	/33	Leach International North America
M83536/33-005L	KC-J2N-300L	83536-98-0122	/33	Leach International North America
M83536/33-001L	FCA-325-3301L	83536-98-0207	/33	Tyco Electronics/CII Relays
M83536/33-002L	FCA-325-3302L	83536-98-0207	/33	Tyco Electronics/CII Relays
M83536/33-003L	FCA-325-3303L	83536-98-0207	/33	Tyco Electronics/CII Relays
M83536/33-004L	FCA-325-3304L	83536-98-0207	/33	Tyco Electronics/CII Relays
M83536/33-005L	FCA-325-3305L	83536-98-0207	/33	Tyco Electronics/CII Relays
M83536/34-019L, M	E1100401CTL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-020L, M	E1100401ATL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-021L, M	E1100401BGL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-022L, M	E1100402CTL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-023L, M	E1100402ATL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-024L, M	E1100402BGL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-025L, M	E1100403CTL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-026L, M	E1100403ATL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-027L, M	E1100403DTL, M	83536-041-00	/34	DRI Relays, Inc.
M83536/34-022L, M	M215-D1A-004L, M	83536-129-00, 83536-158-99	/34	Leach International Europe S.A.
M83536/34-024L, M	M215-D4A-004L, M	83536-129-00, 83536-158-99	/34	Leach International Europe S.A.
M83536/35-019L, M	ES1100401CTL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-020L, M	ES1100401ATL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-021L, M	ES1100401BGL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-022L, M	ES1100402CTL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-023L, M	ES1100402ATL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-024L, M	ES1100402BGL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-025L, M	ES1100403CTL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-026L, M	ES1100403ATL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-027L, M	ES1100403DTL, M	83536-041-00	/35	DRI Relays, Inc.
M83536/35-022L, M	M215-D1N-004L, M	83536-129-00, 83536-158-99	/35	Leach International Europe S.A.
M83536/35-024L, M	M215-D4N-004L, M	83536-129-00, 83536-158-99	/35	Leach International Europe S.A.
M83536/36-001L	JS-D2A-300L	83536-1673-06	/36	Leach International North America
M83536/36-002L	JS-D4A-300L	83536-1673-06	/36	Leach International North America
M83536/36-003L	JC-D1A-300L	83536-1673-06	/36	Leach International North America
M83536/36-004L	JC-D2S-300L	83536-1673-06	/36	Leach International North America
M83536/36-005L	JC-D4A-300L	83536-1673-06	/36	Leach International North America
M83536/36-006L	JC-J1A-300L	83536-1673-06	/36	Leach International North America
M83536/36-007L	JC-J2A-300L	83536-1673-06	/36	Leach International North America
M83536/36-008L	JS-J2A-300L	83536-1673-06	/36	Leach International North America
M83536/36-001L	FCA-125-3601L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/36-002L	FCA-125-3602L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/36-003L	FCA-125-3603L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/36-004L	FCA-125-3604L	83536-986-04	/36	Tyco Electronics/CII Relays

GOVERNMENT DESIGNATION	MANUFACTURER'S DESIGNATION OR TYPE NUMBER	TEST OR QUALIFICATION REFERENCE	SPECIFI- CATION SHEET	SUPPLIER'S NAME (ADDRESS ON LAST PAGE)
M83536/36-005L	FCA-125-3605L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/36-006L	FCA-125-3606L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/36-007L	FCA-125-3607L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/36-008L	FCA-125-3608L	83536-986-04	/36	Tyco Electronics/CII Relays
M83536/37-001L	JC-D1N-300L	83536-1673-06	/37	Leach International North America
M83536/37-002L	JC-D2N-300L	83536-1673-06	/37	Leach International North America
M83536/37-003L	JC-D4N-300L	83536-1673-06	/37	Leach International North America
M83536/37-004L	JC-J1N-300L	83536-1673-06	/37	Leach International North America
M83536/37-005L	JC-J2N-300L	83536-1673-06	/37	Leach International North America
M83536/37-001L	FCA-125-3701L	83536-986-04	/37	Tyco Electronics/CII Relays
M83536/37-002L	FCA-125-3702L	83536-986-04	/37	Tyco Electronics/CII Relays
M83536/37-003L	FCA-125-3703L	83536-986-04	/37	Tyco Electronics/CII Relays
M83536/37-004L	FCA-125-3704L	83536-986-04	/37	Tyco Electronics/CII Relays
M83536/37-005L	FCA-125-3705L	83536-986-04	/37	Tyco Electronics/CII Relays

Manufacturer and Supplier Location Information

Manufacturer: Babcock, Inc. (CAGE Code: 56623)

Location: 14930 East Alondra Blvd., La Mirada, CA 90638-5752, US

Assembly Plants: None Listed**Plants:**

1. Same Address as Manufacturer

Authorized Distributors:

1. Norstan Electronics, 1911 E. Carnegie Ave., Santa Ana, CA 92705, US

Manufacturer: DRI Relays, Inc. (CAGE Code: 99699)

Location: 55 Engineers Road, Hauppauge, NY 11788, US

Assembly Plants: None Listed**Plants:**

1. DRI India, CAGE Code: SFG35, No. 27, 1st Cross, 2nd Phase, Doddanekundi Industrial Area, Whitefield Road, Mahadevapura, Bangalore, 560048, India
2. Same Address as Manufacturer

Authorized Distributors:

1. Airtechnics, Inc., PO Box 3466, 230 Ida, Wichita, KS 67201,
2. Cantwell Collen, 1131 South Service Rd., West, Oakville, Ontario L6L 6K4, Canada
3. Jaco Electronics, 145 Oser Ave., Hauppauge, NY 11788,
4. Pan Pacific Electronics Inc., 3928 150th Ave., Redmond, WA 98052,
5. RSI, 1701 Dalshank, Pflugerville, TX

Manufacturer: Leach International Europe S.A. (CAGE Code: F0219)

Location: 2, Rue Goethe, F-57430 Sarrable, France

Assembly Plants: None Listed**Plants:**

1. Same Address as Manufacturer

Distributors: None Listed

Manufacturer and Supplier Location Information

Manufacturer: Leach International North America (CAGE Code: 58657)

Location: North America, P.O. Box 5032, 6900 Orangethorpe Avenue, Buena Park, CA 90622-5032, US

Assembly Plants: None Listed**Plants:**

1. Same Address as Manufacturer

Authorized Distributors:

1. Avent Electronics Marketing, 140 Technology Drive, Suite 400, Irvine, CA 92718,
2. Avent Electronics Marketing, 3783 Rider Trail South, Earth City, MO 63045,
3. Avent Electronics Marketing, 44191 Plymouth Oaks Boulevard, Plymouth, MI 48170,
4. Avent Electronics Marketing, 4975 Bradford Drive, Huntsville, AL 35805,
5. Avent Electronics Marketing, 9401 James Avenue S., #140, Bloomington, MN 55431,
6. Avnet Electronics Marketing, 390 Rabro Drive, Hauppauge, NY 14623,
7. Avnet Electronics Marketing, 12211 Technology Boulevard, Austin, TX 78727,
8. Avnet Electronics Marketing, 3425 Corporate Way, G&A, Duluth, GA 30136,
9. Avnet Electronics Marketing, 3505 Boca Chica Boulevard, #201, Brownsville, TX 78521,
10. Avnet Electronics Marketing, 655 W. Carmel Drive, #160, Carmel, IN 46032,
11. Avnet Electronics Marketing, (Ottawa District), 190 Colonnade Road, Nepean, Ontario, Canada
12. Avnet Electronics Marketing, (Toronto District), 6705 Millcreek Drive, #1, Mississauga, Ontario, Canada L5N 5R9
13. Avnet Electronics Marketing, 10 Lanidex Plaza West, Parsippany, NJ 07054,
14. Avnet Electronics Marketing, 10500 Richmond Avenue, #112, Houston, TX 77042,
15. Avnet Electronics Marketing, 1057 E. Henrietta Road, Rochester, NY 14623,
16. Avnet Electronics Marketing, 10-D Centennial Drive, Peabody, MA 01960,
17. Avnet Electronics Marketing, 1100 East 6600 South, #120, Salt Lake City, UT 84121,
18. Avnet Electronics Marketing, 11333 Page Mill Road, Dallas, TX 75243,
19. Avnet Electronics Marketing, 1157 Highland Avenue, #207, Cheshire, CT 06410,
20. Avnet Electronics Marketing, 11-A Founders Boulevard, El Paso, TX 79906,
21. Avnet Electronics Marketing, 12206 East 51st Street, Tulsa, OK 74146,
22. Avnet Electronics Marketing, 12503 E. Euclid Drive, #20, Denver, CO 80111,
23. Avnet Electronics Marketing, 2105 Lundy Avenue, San Jose, CA 95131,
24. Avnet Electronics Marketing, 21150 Califa Street, Woodland Hills, CA 91327,
25. Avnet Electronics Marketing, 2601 Wyoming Boulevard, N.E., Albuquerque, NM 87109,
26. Avnet Electronics Marketing, 2617 South 46th, Phoenix, AZ 85034,
27. Avnet Electronics Marketing, 3030 Salt Creek Lane, #300, Chicago, IL 60005,
28. Avnet Electronics Marketing, 30775 Bainbridge Road, Solon, OH 44139,
29. Avnet Electronics Marketing, 3350 NW 53rd Street, #105-107, Ft. Lauderdale, FL 33309,
30. Avnet Electronics Marketing, 4545 Viewridge Avenue, San Diego, CA 92123,
31. Avnet Electronics Marketing, 5234 Green's Dairy Road, Raleigh, NC 27604,
32. Avnet Electronics Marketing, 5516 Rio Vista Drive, Clearwater, FL 34620,
33. Avnet Electronics Marketing, 5792 Widewaters Parkway, Syracuse, NY 13214,
34. Avnet Electronics Marketing, 580 Menle Drive, #2, Rocklin, CA 95765,
35. Avnet Electronics Marketing, 7000 Atrium Way, #6, Mr. Laurel, NJ 08054,
36. Avnet Electronics Marketing, 7079 University Boulevard, Winter Park, FL 32792,
37. Avnet Electronics Marketing, 7134 Columbus Gateway Drive, Columbia, MD 21046,
38. Avnet Electronics Marketing, 7575 Transcanda Highway, St. Laurent, Quebec, Canada H4T 1V6
39. Avnet Electronics Marketing, 777-L Dearborn Park Lane, Worthington, OH 43085,
40. Avnet Electronics Marketing, 8214 154th Avenue, N.E., Redmond, WA 98052,
41. Avnet Electronics Marketing, 8610 Commerce Court, Burnaby, British Columbia, Canada V5A 4N6
42. Avnet Electronics Marketing, 9200 Indian Creek Parkway, Overland Park, KS 66210,
43. Avnet Electronics Marketing, 9750 S.W. Nimbus Avenue, Beaverton, OR 97005,
44. Avnet Electronics Marketing, W232 N2960 Roundy Circle West, Pewaukee, WI 53072,
45. Avnet Electronics Marketing/Electro Air, (Category A), 500 Lake Ridge Drive, S.E., Smyrna, GA 30082,
46. Flame Enterprises, (Category A), 20945 Osborn Street, Canoga Park, CA 91304,

Manufacturer and Supplier Location Information

Manufacturer: MSD, Inc. (CAGE Code: 00213)

Location: 700 Orange Street, Darlington, SC 29532, US

Assembly Plants: None Listed

Plants:

1. Same Address as Manufacturer

Authorized Distributors:

1. All Tech Electronics, 9 Skyline Drive, Hawthorne, NY 10532,
2. Associated Aircraft, 5021 West Jefferson Blvd., Dallas, TX 75211,
3. Flame Enterprises, 20945 Osborne Street, Canoga Park, CA 92705,
4. Norstan Electronics, 1911 East Carnegie Ave., Santa Ana, CA 92705,
5. Sherburn Electronics, P.O. Box 11237, 175 Commerce Dr., Hauppauge, NY 11788,

Manufacturer: STPI (CAGE Code: F0294)

Location: 17 rue Vicq d'Azir, Paris F-75010, France

Assembly Plants: None Listed

Plants:

1. Same Address as Manufacturer

Distributors: None Listed

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Assembly Plants: None Listed

Plants:

1. Same Address as Manufacturer

Authorized Distributors:

1. 10HUGHES PETERSMAIN WHSE, 8000 Technology Blvd., Huber Heights, OH 45424, US
2. A & M ELECTRONICS SUPPLY INC, 4254 Bluebonnet Dr, STAFFORD, TX 77477, US
3. A E Petsche Co, 2112 W Division St, Arlington, TX 76012, US
4. A. E. PETSCH CO. INC., 1151 N FIESTA BLVD, GILBERT, AZ 85233, US
5. A. E. PETSCH CO. INC., 16643 HYMUS BLVD., KIRKLAND QUEBEC, H9H 4R9, CA
6. A. E. PETSCH CO. INC., 4545 W. HARRY ST., WICHITA, KS 67209, US
7. A. E. PETSCH CO. INC., BLDG. 8 STE. E, 2525 W. CASINO RD., EVERETT, WA 98204, US
8. A. E. PETSCH CO. INC., KENNEDY INDUSTRIAL PARK, 920 RIVER ST. STE. G/H, WINDSOR, CT 06095, US
9. A. E. PETSCH CO. INC., STE 225, 2905 PREMIERE PKWY, DULUTH, GA 30097, US
10. A. E. PETSCH CO., 2112 W. DIVISION ST., ARLINGTON, TX 76012, US
11. A. E. PETSCH, 119 SOUTH BLVD STE 2, SALISBURY, MD 21801, US
12. A.E. Petsche Co Inc, 2112 W Division St, Arlington, TX 76012, US
13. Active Electronics, Ste 321373 Veterans Mem Hwy, Hauppauge, NY 11788, US
14. Actronix Inc., 5001 S. Towne Dr., New Berlin, WI 53151, US
15. Adtech System Co Ltd, Room # 1216 DA-Dong, Jungangyutong # 1258, Gurobon-dong Guro-gu, Seoul-City, KR
16. AE Petsche Canada, 2112 W Division St, Arlington, TX 76012, US
17. AE Petsche Company Inc, 16643 Hymus Blvd, Kirkland, QC H9H 4, US
18. AERO INTERNATIONAL, 22977 EAGLEWOOD CT., STERLING, VA 20166, US
19. AEROTECH WORLD TRADE CORP, 11 NEW KING ST., WHITE PLAINS, NY 10604, US
20. AESCO ELECTRONICS INC, 210 S. MEADOW RD., PLYMOUTH, MA 02360, US
21. AESCO ELECTRONICS INC, 2230 Picton Pkwy, Akron, OH 44312, US
22. AESCO ELECTRONICS INC, 663-D PARK MEADOW RD., WESTERVILLE, OH 43081, US
23. Aesco Electronics, 2230 Picton Pkwy, Akron, OH 44312, US
24. Aircraft & Commercial Enterprises, 12400 E 75th St S, Derby, KS 67037, US
25. AIRTECHNICS INC., 3851 N. WEBB RD., WICHITA, KS 67226, US
26. ALL AMERICAN SEMICONDUCTOR, 14976 NW GREENBRIER PKWY, BEAVERTON, OR 97006, US
27. ALL AMERICAN SEMICONDUCTOR, 16175 NW. 52ND AVE., MIAMI, FL 33014, US
28. ALL AMERICAN SEMICONDUCTOR, 48376 MILMONT DR., FREMONT, CA 94538, US
29. ALL AMERICAN SEMICONDUCTOR, STE 204, 7575 W 103RD AVE, WESTMINSTER, CO 80021, US
30. ALLIED ELECTRONICS INC, 7151 JACK NEWELL BLVD S, FORT WORTH, TX 76118, US
31. ALLIED ELECTRONICS INC., STE. 100, 6830 VIA DEL ORO, SAN JOSE, CA 95119, US
32. AMERICAN WIRE & TERMINAL, UNIT 2, 460 FLORIDA CENTRAL PKWY, LONGWOOD, FL 32750, US
33. Anchor Electronics, 348 Hillside Ave., Williston Park, NY 11596, US
34. Anixter Pentacon, 21123 Nordhoff St, CHATSWORTH, CA 91311, US
35. ARNOLD INDUSTRIES INC, 80 SHAWMUT RD, CANTON, MA 02021, US
36. Arrow Bell Components, 300 North Rivermede Road, Concord, ON L4K 3, US
37. ARROW ELECTRONICS COMP, B/T-CONSIGNMENT, C/O ACT ELECT. INC, 1801 FULTON DRIVE, CORINTH, MS 38834, US
38. ARROW ELECTRONICS INC, AEC DIVISION, 6675 PARKLAND BLVD, SOLON, OH 44139, US
39. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 1162 SPRING LAKE DR, ITASCA, IL 60143, US
40. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 20935 WARNER CENTER LN, WOODLAND HILLS, CA 91367, US
41. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 4731 RIPLEY DR STE A, EL PASO, TX 79922, US
42. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 6982 HILLSDALE CT, INDIANAPOLIS, IN 46250, US
43. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 7677 PARAGON RD STE A, DAYTON, OH 45459, US
44. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 860 N MAIN ST EXT, WALLINGFORD, CT 06492, US
45. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, 9800J PATUXENT WOODS DR, COLUMBIA, MD 21046, US
46. ARROW ELECTRONICS INC, ARROW/BELL COMPONENTS, STE E, 4250 RIVER GREEN PKWY, DULUTH, GA 30096, US
47. ARROW ELECTRONICS INC, ARROW/RICHEY ELECTRONICS, 55 SKYLINE DR STE 2500, LAKE MARY, FL 32746, US
48. ARROW ELECTRONICS INC, COMPONENTS GROUP, 6800 COLLEGE BLVD STE 501, OVERLAND PARK, KS 66211, US
49. ARROW ELECTRONICS INC. AK, ARROW KITTING, 665 MAESTRO DR., RENO, NV 89511, US
50. ARROW ELECTRONICS INC. CP, 44760 HELM ST, PLYMOUTH, MI 48170, US
51. ARROW ELECTRONICS INC. DE, ARROW/BELL COMPONENTS, 7459 S. LIMA ST., ENGLEWOOD, CO 80112, US
52. ARROW ELECTRONICS INC. DL, ARROW/BELL COMPONENTS, 6340 INTERNATIONAL PKWY., PLANO, TX 75093, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

53. ARROW ELECTRONICS INC. FL, ARROW/BELL COMPONENTS, STE. 160, 13800 NW. 14TH ST., SUNRISE, FL 33323, US
54. ARROW ELECTRONICS INC. GO, SEMICONDUCTOR GROUP, FOOTHILLS CORP. PLZ., 27121 TOWNE CTR. DR. #100, FOOTHILL RANCH, CA 92610, US
55. ARROW ELECTRONICS INC. GW, SEMICONDUCTOR GROUP, 200 N. PATRICK BLVD., BROOKFIELD, WI 53045, US
56. ARROW ELECTRONICS INC. HO, ARROW/BELL COMPONENTS, STE 120, 2901 WILCREST DR, HOUSTON, TX 77042, US
57. ARROW ELECTRONICS INC. HU, ARROW/BELL COMPONENTS, 4930 G CORP. DR., HUNTSVILLE, AL 35805, US
58. ARROW ELECTRONICS INC. ID, ARROW ELECTRONICS INTL, INDIA, 120 COMMERCE DR., HAUPPAUGE, NY 11788, US
59. ARROW ELECTRONICS INC. JA, CMS DISTRIBUTION GROUP, 9233 WATERFORD CENTRE BLV, AUSTIN, TX 78758, US
60. ARROW ELECTRONICS INC. MS, ARROW/BELL COMPONENTS, 7697 ANAGRAM DR., EDEN PRAIRIE, MN 55344, US
61. ARROW ELECTRONICS INC. NE, ARROW/BELL COMPONENTS, 35 UPTON DR., WILMINGTON, MA 01887, US
62. ARROW ELECTRONICS INC. NJ, ARROW/BELL COMPONENTS, 100 SOUTH JEFFERSON RD, WHIPPANY, NJ 07981, US
63. ARROW ELECTRONICS INC. OQ, ARROW/BELL COMPONENTS, 25 HUB DR., MELVILLE, NY 11747, US
64. ARROW ELECTRONICS INC. OU, FLEXTRONICS MEXICO POS, CMS MEXICO, C LATERAL SUR #579 PERIF, ZAPOPAN JALISCO, MX
65. ARROW ELECTRONICS INC. PH, ARROW/BELL COMPONENTS, 355 BUSINESS CENTER DR., HORSHAM, PA 19044, US
66. ARROW ELECTRONICS INC. PL, ARROW/BELL COMPONENTS, BLDG. E, 9500 SW NIMBUS AVE., BEAVERTON, OR 97008, US
67. ARROW ELECTRONICS INC. PT, ARROW/BELL COMPONENTS, 3245 OLD FRANKSTOWN RD., PITTSBURGH, PA 15239, US
68. ARROW ELECTRONICS INC. PX, ARROW/BELL COMPONENTS, 2552 W. EIRE DR. STE. 101, TEMPE, AZ 85282, US
69. ARROW ELECTRONICS INC. QB, ARROW ALLIANCE, NEWBRIDGE 88 HINES RD., KANATA ONTARIO, K2K 2T8, CA
70. ARROW ELECTRONICS INC. QG, ARROW ALLIANCE, NORTEL CANADA, 1255 TRANS-CANADA HWY 100, DORVAL QUEBEC, CA
71. ARROW ELECTRONICS INC. QM, ARROW/BELL COMPONENTS, 19180 TRANS-CANADA HWY, BAIE D'URFE, QUEBEC, H9X 3S4, CA
72. ARROW ELECTRONICS INC. QO, ARROW/BELL COMPONENTS, 88 HINES RD., KANATA ONTARIO, K2K 2T8, CA
73. ARROW ELECTRONICS INC. QT, ARROW/BELL COMPONENTS, 171 SUPERIOR BLVD., MISSISSAUGA ONTARIO, L5T 2L6, CA
74. ARROW ELECTRONICS INC. QV, ARROW/BELL COMPONENTS, 8555 COMMERCE CT., BURNABY BC, V5A 4N4, CA
75. ARROW ELECTRONICS INC. RA, ARROW/BELL COMPONENTS, 200 PERIMETER PK, STE D, MORRISVILLE, NC 27560, US
76. ARROW ELECTRONICS INC. RO, ARROW/BELL COMPONENTS, 2165 BRIGHTON HENRIETTA, TOWNLINE RD., ROCHESTER, NY 14623, US
77. ARROW ELECTRONICS INC. SA, ARROW/BELL COMPONENTS, 2440 S. 1070 W. STE. A, SALT LAKE CITY, UT 84119, US
78. ARROW ELECTRONICS INC. SD, ARROW/BELL COMPONENTS, 9511 RIDGEHAVEN CT., SAN DIEGO, CA 92123, US
79. ARROW ELECTRONICS INC. SE, ARROW/BELL COMPONENTS, BLDG. B - STE. A, 3310 146TH PL. SE, BELLEVUE, WA 98007, US
80. ARROW ELECTRONICS INC. SF, ARROW/BELL COMPONENTS, 3000 BOWERS AVE., SANTA CLARA, CA 95051, US
81. ARROW ELECTRONICS INC. SL, ARROW/BELL COMPONENTS, 514 EARTH CITY EXPWY, ST LOUIS, MO 63045, US
82. ARROW ELECTRONICS INC. SM, ARROW/BELL COMPONENTS, STE. 105, 3300 DOUGLAS BLVD., ROSEVILLE, CA 95661, US
83. ARROW ELECTRONICS INC. TM, ARROW ADVANTAGE, 18640 LAKE DR. E., CHANHASSEN, MN 55317, US
84. ARROW ELECTRONICS INC. TQ, ARROW ADVANTAGE, 155 CHAIN LAKE DR. #27, HALIFAX NOVA SCOTIA, B3S 1B3, CA
85. ARROW ELECTRONICS INC. TU, ARROW/BELL COMPONENTS, STE. 101, 12111 E. 51ST ST., TULSA, OK 74146, US
86. ARROW ELECTRONICS INC. WI, ARROW/BELL COMPONENTS, 200 N. PATRICK BLVD., BROOKFIELD, WI 53045, US
87. ARROW ELECTRONICS INC. WK, ARROW/BELL COMPONENTS, 5920 11 ST. SE. STE. 10, CALGARY ALBERTA, T2H 2M4, CA
88. ARROW ELECTRONICS INC. WL, ARROW/BELL COMPONENTS, 10630 172 ST., EDMONTON ALBERTA, T5S 1H8, CA
89. ARROW ELECTRONICS INC. XK, PRIMARY DISTRIBUTION CTRS, LENEXA, 9801 LEGLER RD., LENEXA, KS 66219, US
90. Arrow Electronics, 25 Hub Dr., Melville, NY 11747, US
91. ARROW ELECTRONICS, 4731 RIPLEY DR, EL PASO, TX 79922, US
92. ARROW ELECTRONICS, DN, DICOPEL/ARROW, FRANCISCO PIMENTAL 98, COL. SAN RAFAEL CP., DF 06470, MX
93. ARROW ELECTRONICS, PDC, 1251 S. ROCKEFELLER AVE., ONTARIO, CA 91761, US
94. ARROW ELECTRONICS, PDC, A/T-VALUE ADDED, POWER SUPPLY INTEGR CTR, 2875 BAYVIEW DR, FREMONT, CA 94538, US
95. ARROW-NAC, B/T-PRIMARY DIST CENTER, POWER PRODUCTS SERVICES, 1955 E.SKY HARBOR CIRCLE, PHOENIX, AZ 85034, US
96. ARROW-NAC, PRIMARY DIST.CTR.MILITARY, 665 MAESTRO DR, RENO, NV 89511, US
97. Atlanta Hardware, 48-75 36th St, Long Island City, NY 11101, US
98. AUTELIN , S.A. DE C.V., VALLARTA 720 NTE., COL. CENTRO, MONTERREY NUEVO LEON, MONTERREY NUEVO LE, NL 64000, US
99. AVED ELECTRONICS INC, DON'T ACTIVATE, SEE STD &, ADD'L INSTR FOR REFERRAL, 59 TECHNOLOGY DR., LOWELL, MA 01851, U:
100. Avnet Canada, 6705 Millcreek Drive, Unit 1, Mississauga, ON L5N 5, US
101. AVNET ELECTRONICS MKTG, 10 Centennial Dr, Peabody, MA 01960, US
102. AVNET EM, C/O G E FANUC, 2500 AUSTIN DR, CHARLOTTESVILLE, VA 22911, US
103. AVNET EM/CENTRAL MEXICO, AVE ITESO NO 8900 IDIFICIO, 1B PARQ INDL TECNOLÓGICO, TLAQUEPAQUE JALISCO, 45080, MX
104. Avnet EMG, 10 Centennial Dr, Peabody, MA 01960, US
105. AVNET EMG, 10 CENTENNIAL DR., PEABODY, MA 01960, US
106. AVNET EMG, 10 LANIDEX PLAZA W., PARSIPPANY, NJ 07054, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

107. AVNET EMG, 1057 E. HENRIETTA RD., ROCHESTER, NY 14623, US
108. AVNET EMG, 10805 RANCHO BERNARDO RD, SAN DIEGO, CA 92127, US
109. AVNET EMG, 13750 SHORELINE DR., EARTH CITY, MO 63045, US
110. AVNET EMG, 15580 SW JAY ST., BEAVERTON, OR 97006, US
111. AVNET EMG, 1840 MCCARTHY BLVD, MILPITAS, CA 95035, US
112. AVNET EMG, 190 COLONNADE RD NE PEAN ON K2E 7J5, CA
113. AVNET EMG, 20 STERLING DR., WALLINGFORD, CT 06492, US
114. AVNET EMG, 2021 LAKESIDE BLVD, RICHARDSON, TX 75082, US
115. AVNET EMG, 21155 CALIFA AVE., WOODLAND HILLS, CA 91367, US
116. AVNET EMG, 2200 WILLIAM D TATE AVE., GRAPEVINE, TX 76051, US
117. AVNET EMG, 2301 N FORBES BLVD, TUCSON, AZ 85745, US
118. AVNET EMG, 2617 S 46TH ST, PHOENIX, AZ 85034, US
119. AVNET EMG, 2712 N MCCOLL RD, MCALLEN, TX 78501, US
120. AVNET EMG, 3030 SALT CREEK LN. #300, ARLINGTON HEIGHTS, IL 60005, US
121. AVNET EMG, 3475 CORPORATE WAY, DULUTH, GA 30096, US
122. AVNET EMG, 380 PARK PL STE 170, CLEARWATER, FL 33759, US
123. AVNET EMG, 4975 BRADFORD DR, HUNTSVILLE, AL 35805, US
124. AVNET EMG, 60 S MCKEMY AVE, CHANDLER, AZ 85226, US
125. AVNET EMG, 6705 MILLCREEK DR UNIT 1 MISSISSAUGA ON L5N 5M4, CA
126. AVNET EMG, 7000 ATRIUM WAY STE. 6, MOUNT LAUREL, NJ 08054, US
127. AVNET EMG, 8610 COMMERCE CT BURNABY BC V5A 4N6, CA
128. AVNET EMG, 8705 KELLAM BLVD, LAREDO, TX 78045, US
129. AVNET EMG, AVNET PUERTO RICO, 1661 PENASCO STREET, PARADISE SAN JUAN, 00962, PR
130. AVNET EMG, C/O CISCO SYSTEMS, 45885 HOTCHKISS ST, FREMONT, CA 94539, US
131. AVNET EMG, STE 100, 10785 WILLOWS RD NE, REDMOND, WA 98052, US
132. AVNET EMG, STE 100, 430 EXCHANGE, IRVINE, CA 92602, US
133. AVNET EMG, STE 100, 630 W CARMEL DR, CARMEL, IN 46032, US
134. AVNET EMG, STE 103, 12206 E 51ST ST, TULSA, OK 74146, US
135. AVNET EMG, STE 110, 3 BUTTERFIELD TRL, EL PASO, TX 79906, US
136. AVNET EMG, STE 140, 135 ENGINEERS RD, HAUPPAUGE, NY 11788, US
137. AVNET EMG, STE 150, 2501 DISCOVERY DR, ORLANDO, FL 32826, US
138. AVNET EMG, STE 150, 2740 AMERICAN BLVD WEST, BLOOMINGTON, MN 55431, US
139. AVNET EMG, STE 250 BLDG G, 9601 AMBER GLEN BLVD, AUSTIN, TX 78729, US
140. AVNET EMG, STE 250, 30575 BAINBRIDGE RD, SOLON, OH 44139, US
141. AVNET EMG, STE 600, 9200 INDIAN CREEK PKWY., OVERLAND PARK, KS 66210, US
142. AVNET EMG, STE A, 350 WORTHINGTON RD, WESTERVILLE, OH 43082, US
143. AVNET EMG, STE G, 1847 MERCER RD, LEXINGTON, KY 40511, US
144. AVNET EMG, STE. 100, 7134 COLUMBIA GATEWAY DR., COLUMBIA, MD 21046, US
145. AVNET EMG, STE. 112, 10500 RICHMOND AVE., HOUSTON, TX 77042, US
146. AVNET EMG, STE. 1300, 44191 PLYMOUTH OAKS BLVD., PLYMOUTH, MI 48170, US
147. AVNET EMG, STE. 2, 580 MENLO DR., ROCKLIN, CA 95765, US
148. AVNET EMG, STE. 220, 2855 E. COTTONWOOD PKWY., SALT LAKE CITY, UT 84121, US
149. AVNET EMG, STE. 500, 5511 CAPITAL CENTER DR., RALEIGH, NC 27606, US
150. AVNET EMG, STE. 600, 7575 TRANS CANADA HWY, SAINT-LAURENT QC H4T 1V6, CA
151. AVNET EMG, STE. C, 12600 E. ARAPAHOE RD., ENGLEWOOD, CO 80112, US
152. AVNET EMG, W232 N2960 ROUNDYS, CIRCLE W STE 200, PEWAUKEE, WI 53072, US
153. AVNET MTY, MONTERREY ST, MONTERREY, NUEVO LEON, 66600, MX
154. AVNET, CHIHUAHUA ST, CHIHUAHUA, CHIHUAHUA, 31109, MX
155. AVNET/ KENT ELECTRONICS, 10 Centennial Dr, Peabody, MA 01960, US
156. AZTEC COMPONENTS INC., 1201 ACTIVITY DR, VISTA, CA 92081, US
157. B G ELECTRONICS, 1610 I35 N. #211, CARROLLTON, TX 75006, US
158. BERND GROUP INC, 1792 ROYAL OAKS PL W, dunedin, FL 34698, US
159. BG Technologies, 2301 Denton Dr, Austin, TX 78758, US
160. Bisco Industries, 1500 N. Lakeview Ave., Anaheim, CA 92807, US
161. BJG Electronics Inc., Bethpage, NY 11714, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

162. BJG ELECTRONICS INC., 141 REMINGTON BLVD, RONKONKOMA, NY 11779, US
163. BJG ELECTRONICS INC., 1535 COGSWELL ST., SUITE B-8, ROCKLEDGE, FL 32955, US
164. BK CONTROLS INC., 801 HILLTOP DR., ITASCA, IL 60143, US
165. BLUFF CITY DISTRIBUTING, 3339 FONTAINE DR., MEMPHIS, TN 38116, US
166. BLUFF CITY ELECTRONICS, 724 AIRWAYS BLVD, JACKSON, TN 38301, US
167. BOSSARD NORTH AMERICA, 4409 HALTOM RD, HALTOM CITY, TX 76117, US
168. BOSSARD NORTH AMERICA, 6210 EXECUTIVE BLVD, DAYTON, OH 45424, US
169. BOSSARD NORTH AMERICA, 6521 PRODUCTION DR, CEDAR FALLS, IA 50613, US
170. BOSSARD NORTH AMERICA, 8940 SORENSEN AVEVD, SANTA FE SPRINGS, CA 90670, US
171. BRUCKNER SUPPLY CO INC, 185 THORN HILL DR., WARRENDALE, PA 15086, US
172. BRUCKNER SUPPLY CO INC, 36 HARBOR PARK DR., PORT WASHINGTON, NY 11050, US
173. Cable Accessories Ltd, Unit 5 Red Cow Interchange EstTurnpike Road, Ballymount 22, Dublin, IE
174. CABYTER, S.A. DE C.V., AZUCENAS #147, VILLA DE LAS FLORES 1a SECC., COACALCO, EDO. DE MEXICO, COACALCO, EDO. DE, ME 55710, US
175. CALGREG ELECTRONICS INC, 60 ALHAMBRA RD, WARWICK, RI 02886, US
176. CALVERT WIRE & CABLE CORP, 5091 W 164TH STREET, BROOKPARK, OH 44142, US
177. CARLTON-BATES CO, Little Rock, AR 72219, US
178. CARLTON-BATES COMPANY, (BR1927), 2550 HARLEY DR, MARYLAND HEIGHTS, MO 63043, US
179. CARLTON-BATES COMPANY, 1050 CHRIS CIR, WEST COLUMBIA, SC 29169, US
180. CARLTON-BATES COMPANY, 1366 W NORTH CARRIER PKWY, GRAND PRAIRIE, TX 75050, US
181. CARLTON-BATES COMPANY, 13805 WEST RD STE 250, HOUSTON, TX 77041, US
182. CARLTON-BATES COMPANY, 1400 N MICHAEL DR, WOOD DALE, IL 60191, US
183. CARLTON-BATES COMPANY, 1430 W POINT DR STE M, CHARLOTTE, NC 28214, US
184. CARLTON-BATES COMPANY, 1893 ELM TREE DR, NASHVILLE, TN 37210, US
185. CARLTON-BATES COMPANY, 2150 BOGGS RD STE 660, DULUTH, GA 30096, US
186. CARLTON-BATES COMPANY, 2321A E OLIVE CT, SPRINGFIELD, MO 65802, US
187. CARLTON-BATES COMPANY, 2558 PEARL BUCK RD, BRISTOL, PA 19007, US
188. CARLTON-BATES COMPANY, 306 E NAKOMA ST STE A, SAN ANTONIO, TX 78216, US
189. CARLTON-BATES COMPANY, 3600 W 69TH ST, LITTLE ROCK, AR 72209, US
190. CARLTON-BATES COMPANY, 4313 SW 21ST ST, OKLAHOMA CITY, OK 73108, US
191. CARLTON-BATES COMPANY, 4413 N THOMPSON ST, SPRINGDALE, AR 72764, US
192. CARLTON-BATES COMPANY, 501-C UWHARRIE CT, RALEIGH, NC 27606, US
193. CARLTON-BATES COMPANY, 505 BERGMAN AVE, LOUISVILLE, KY 40203, US
194. CARLTON-BATES COMPANY, 520 WEDDELL DR STE 8, SUNNYVALE, CA 94089, US
195. CARLTON-BATES COMPANY, 524 SUNCREST DR, GRAY, TN 37615, US
196. CARLTON-BATES COMPANY, 5405 S 125TH EAST AVE, TULSA, OK 74146, US
197. CARLTON-BATES COMPANY, 600 CORDWAINER DR, NORWELL, MA 02061, US
198. CARLTON-BATES COMPANY, 601 E CEDAR AVE UNIT F, MCALLEN, TX 78501, US
199. CARLTON-BATES COMPANY, 6510-A GATEWAY EAST, BLDG A, EL PASO, TX 79905, US
200. CARLTON-BATES COMPANY, 717 N ASHLEY RIDGE LOOP, SHREVEPORT, LA 71106, US
201. CARLTON-BATES COMPANY, 7425 S HARL AVE STE 1, TEMPE, AZ 85283, US
202. CARLTON-BATES COMPANY, 8696 COTTER ST, LEWIS CENTER, OH 43035, US
203. CARLTON-BATES COMPANY, 8900 CAMERON RD STE 100, AUSTIN, TX 78754, US
204. CARLTON-BATES COMPANY, 9214 BOND ST, OVERLAND PARK, KS 66214, US
205. CARLTON-BATES COMPANY, BLDG C STE 14, 4477 WINCHESTER RD, MEMPHIS, TN 38118, US
206. CHEMWELD INCORPORATED, 4530 BERKELEY LAKE RD, NORCROSS, GA 30071, US
207. CHEROKEE NATION, DISTRIBUTORS INC., HIGHWAY 51 W., STILWELL, OK 74960, US
208. Cleeve Technology Incorporated, 716 Colonel Sam Drive, Oshawa, ON L1H 7, US
209. CML INNOVATIVE TECHNOLOGIES,, ZONA FRANCA SARET, EDIF B6 1KM, ESTE AEROPUERTO CRI ALAJUELA, COSTA RICA, PR
210. COAST AIR INC, 11134 SEPULVEDA BLVD, MISSION HILLS, CA 91345, US
211. Communications Products &, Services Inc150 Blades Ln, Glen Burnie, MD 21060, US
212. Component Technology US, Ste 33503000 Valley Forge Cir, King of Prussia, PA 19406, US
213. COMPONENTS CENTER, 11208 YOUNG RIVER AVE, FOUNTAIN VALLEY, CA 92708, US
214. COMPONENTS CENTER, 3351 EDWARD AVE, SANTA CLARA, CA 95054, US
215. COMPREHENSIVE VIDEO GROUP, 55 Ruta Court, South Hackensack, NJ 07606, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

216. CONECTER, S.A. DE C.V., VALLE DE LIERP EDIF.77-A N01, VALLE DE ARAGON 1 SECC., NEZAHUALCOYOTL,EDO. MEX., NEZAHUALCOYOTL,EDO, ME 57100, US
217. CONNECTOR MICROTOOLING, SYSTEMS INC., 331 AARON AVE. STE. 129, ARLINGTON, TX 76012, US
218. COSTA ORIENTAL SA, RUTA 8 KM. 17.500, ZONAMERICA, MONTEVIDEO, UY
219. CUMBERLAND ELECTRONICS IN, 2501 SYCAMORE ST, HARRISBURG, PA 17111, US
220. Cutlass Associates, 3933 E Wateka, Gilbert, AZ 85297, US
221. CV LOGISTICS INC., 8270 WILLOW PL N STE 100, HOUSTON, TX 77070, US
222. D F SALES CO, DON'T ACTIVATE, SEE STD &, ADD'L INSTR FOR REFERRAL, 690 QUINN AVE, SAN JOSE, CA 95112, US
223. DALIS ELECTRONIC SUPPLY, STE 2, 3645 E ATLANTA AVE, PHOENIX, AZ 85040, US
224. Dallas Warehouse, 7350 HERMAN WAY, MIAMI, FL 33122, US
225. DATACOMM CABLES, 66 CENTRAL AVENUE, FARMINGDALE, NY 11735, US
226. DEE ELECTRONICS INC, 1400 WALNUT ST., DES MOINES, IA 50309, US
227. DEE ELECTRONICS INC, 2500 16TH AVE SW, CEDAR RAPIDS, IA 52404, US
228. Delta International Inc, Ste 1014970 SW 72 Ave, Miami, FL 33155, US
229. DICOPEL, S.A., FRANCISCO PIMENTEL No.98, COL. SAN RAFAEL, MEXICO, DF, MEXICO, DF, DF 06470, US
230. DIGI-KEY CORP, 701 BROOKS AVE S, THIEF RIVER FALLS, MN 56701, US
231. Digi-Key Corp, Thief River Falls, MN 56701, US
232. Digi-Key Corporation, Thief River Falls, MN 56701, US
233. DIRCKSEN & ASSOCIATES, ATTN: RECEIVING, 3452 E. LIVINSTON AVE., COLUMBUS, OH 43213, US
234. DRS FERMONT, C/O ALABAMA AEROSPACE, 80 SHELTON ST, BRIDGEPORT, CT 06608, US
235. Dunn Technologies, 2501 26TH AVE SO., MINNEAPOLIS, MN 55406, US
236. EDMO DISTRIBUTORS INC, 12830 E MIRABEAU PKWY., SPOKANE, WA 99216, US
237. EIS INC, Ste 5002018 Powers Ferry Rd, ATLANTA, GA 30339, US
238. ELECTRO AIR CORP., 400 FRANKLIN RD STE 260, MARIETTA, GA 30067, US
239. ELECTRO INSULATION CORPORATION, 3921 VENTURA DR, ARLINGTON HEIGHTS, IL 60004, US
240. Electro Sonic Inc, 1100 Gordon Baker Rd, Willowdale, ON M2H 3, US
241. ELECTRONIC INDUSTRIES, 19 E. IRVING ST., OSHKOSH, WI 54901, US
242. ELECTROSPEC, 24 E CLINTON ST, DOVER, NJ 07801, US
243. Emsco, 1230 W Central Blvd, Orlando, FL 32802, US
244. EMTEL ELECTRONICS, 375 VANDERBILT AVE., NORWOOD, MA 02062, US
245. EQUIPTEx INDUSTRIAL PRDCT, 14 N BLEEKER ST, MOUNT VERNON, NY 10550, US
246. Esco LLC, 2 S. Pointe Dr. #220, Lake Forest, CA 92630, US
247. ETA Global Inc., Attn: Thea Renard, Palestine, TX 75802, US
248. F E C Technology Corp, 1 Dupont St Ste 100, Plainview, NY 11803, US
249. FEDERAL DEFENSE, INDUSTRIES INC, 11952 DISCOVERY CT, MOORPARK, CA 93021, US
250. FLAME ENTERPRISES INC, 21500 GLEDHILL ST., CHATSWORTH, CA 91311, US
251. Flame Enterprises Inc., 21500 Gledhill St., Chatsworth, CA 91311, US
252. FORCE ELECTRONICS, 1440 S. PRIEST 101, TEMPE, AZ 85281, US
253. FORCE ELECTRONICS, 477 GIANNI ST., SANTA CLARA, CA 95054, US
254. Force Electronics, 5300 AVION PARK DRIVE, HIGHLAND HEIGHTS, OH 44143, US
255. Force Electronics, 58 Jonspin Rd, Wilmington, MA 01887, US
256. FORCE ELECTRONICS, 700 N PLAZA DR, VISALIA, CA 93291, US
257. FORCE ELECTRONICS, BRANCH #57, 1826 KRAMER LN. STE. A, AUSTIN, TX 78758, US
258. FORCE ELECTRONICS, STE 200, 3100 SUMMIT AVE, PLANO, TX 75074, US
259. FORCE ELECTRONICS, STE 230, 10801 WALKER ST., CYPRESS, CA 90630, US
260. FORCE ELECTRONICS, STE 230, 9101 HARLAN ST, WESTMINISTER, CO 80031, US
261. FORCE ELECTRONICS, STE 260, 10200 RICHMOND AVE, HOUSTON, TX 77042, US
262. FORCE ELECTRONICS, STE 702, 17270 WOODINVILLE-REDMOND, RD. NE, WOODINVILLE, WA 98072, US
263. FORCE ELECTRONICS, STE. 100, 2267 LAVA RIDGE CT., ROSEVILLE, CA 95661, US
264. FORCE ELECTRONICS, STE. A&B, 7985 DUNBROOK ST., SAN DIEGO, CA 92126, US
265. FORCE ELECTRONICS, STE. C, 742 HAMPSHIRE RD., WESTLAKE VILLAGE, CA 91361, US
266. FUTURE ELECTRONICS INC., 1192 E. NEWPORT CTR. DR., DEERFIELD BEACH, FL 33442, US
267. FUTURE ELECTRONICS INC., 300 LINDEN OAKS, ROCHESTER, NY 14625, US
268. FUTURE ELECTRONICS INC., 3033 EXPRESS DR. N., HAUPPAUGE, NY 11788, US
269. FUTURE ELECTRONICS INC., 41 MAIN ST., BOLTON, MA 01740, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

270. FUTURE ELECTRONICS INC., 4150 OLD AIRWAYS BLVD, SOUTHAVEN, MS 38671, US
271. FUTURE ELECTRONICS INC., 5720 SMETANA DR, STE 325, MINNETONKA, MN 55343, US
272. FUTURE ELECTRONICS INC., 6060 ROCKSIDE RD, INDEPENDENCE, OH 44131, US
273. FUTURE ELECTRONICS INC., GREYSTONE PLAZA, STE. 310, 7200 N. MOPAC EXPY., AUSTIN, TX 78731, US
274. FUTURE ELECTRONICS INC., PARKER BUSINESS CENTER, STE. 154, 2800 SUMNER BLVD., RALEIGH, NC 27616, US
275. FUTURE ELECTRONICS INC., STE 100, 38800 COUNTRY CLUB DR, FARMINGTON HILLS, MI 48331, US
276. FUTURE ELECTRONICS INC., STE 1000, 59 SKYLINE DR, LAKE MARY, FL 32746, US
277. FUTURE ELECTRONICS INC., STE 115, 30851 AGOURA RD, AGOURA HILLS, CA 91301, US
278. FUTURE ELECTRONICS INC., STE 160, 6650 SW REDWOOD LANE, PORTLAND, OR 97224, US
279. FUTURE ELECTRONICS INC., STE 205, 8520 ALLISON POINTE BLVD., INDIANAPOLIS, IN 46250, US
280. FUTURE ELECTRONICS INC., STE 210, 3350 MONTEVILLA PKWY, BOTHELL, WA 98021, US
281. FUTURE ELECTRONICS INC., STE 220, 690 N MCCARTHY BLVD, MILPITAS, CA 95035, US
282. FUTURE ELECTRONICS INC., STE 340, 15950 BAY VISTA DR, CLEARWATER, FL 33760, US
283. FUTURE ELECTRONICS INC., STE 400, 2101 CLINTON AVE, HUNTSVILLE, AL 35805, US
284. FUTURE ELECTRONICS INC., STE. 100, 120 LITTLETON RD., PARSIPPANY, NJ 07054, US
285. FUTURE ELECTRONICS INC., STE. 150, 175 N. CORPORATE DR., BROOKFIELD, WI 53045, US
286. FUTURE ELECTRONICS INC., STE. 150, 2201 W. PLANO PARKWAY, PLANO, TX 75075, US
287. FUTURE ELECTRONICS INC., STE. 180, 1190 WINTERSON RD., LINTHICUM, MD 21090, US
288. FUTURE ELECTRONICS INC., STE. 200, 1640 LEAD HILL BLVD., ROSEVILLE, CA 95661, US
289. FUTURE ELECTRONICS INC., STE. 200, 25B TECHNOLOGY, IRVINE, CA 92618, US
290. FUTURE ELECTRONICS INC., STE. 200, 5000 STONEWOOD DR., WEXFORD, PA 15090, US
291. FUTURE ELECTRONICS INC., STE. 200, 5550 PRAIRIE STONE PKWY., HOFFMAN ESTATES, IL 60192, US
292. FUTURE ELECTRONICS INC., STE. 200, 6256 GREENWICH DR., SAN DIEGO, CA 92122, US
293. FUTURE ELECTRONICS INC., STE. 203, 1430 OAK COURT, BEAVERCREEK, OH 45430, US
294. FUTURE ELECTRONICS INC., STE. 210, 10977 GRANADA LN., OVERLAND PARK, KS 66211, US
295. FUTURE ELECTRONICS INC., STE. 210, 251 SALINA MEADOWS PKWY., SYRACUSE, NY 13212, US
296. FUTURE ELECTRONICS INC., STE. 220, 4400 RIVER GREEN PKWY., DULUTH, GA 30096, US
297. FUTURE ELECTRONICS INC., STE. 225, 4801 E. WASHINGTON ST., PHOENIX, AZ 85034, US
298. FUTURE ELECTRONICS INC., STE. 240, 655 CRAIG RD., CREVE COEUR, MO 63141, US
299. FUTURE ELECTRONICS INC., STE. 280, 4595 BROADMOOR SE, GRAND RAPIDS, MI 49512, US
300. FUTURE ELECTRONICS INC., STE. 301, 3450 S. HIGHLAND DR., SALT LAKE CITY, UT 84106, US
301. FUTURE ELECTRONICS INC., STE. 330, 10737 GATEWAY WEST, EL PASO, TX 79935, US
302. FUTURE ELECTRONICS INC., STE. 350 BLDG. 26, 1819 DENVER WEST DR., GOLDEN, CO 80401, US
303. FUTURE ELECTRONICS INC., STE. 900, 2000 CRAWFORD PL., MT LAUREL, NJ 08054, US
304. FUTURE ELECTRONICS INC., STE. 970, 10333 RICHMOND AVE., HOUSTON, TX 77042, US
305. FUTURE ELECTRONICS INC., WESTGATE OFFICE CENTER, 700 WEST JOHNSON AVE., CHESHIRE, CT 06410, US
306. FUTURE ELECTRONICS, 41 Main St, Bolton, MA 01740, US
307. FUTURE ELECTRONICS, Distribution Center LPMS4150 old airways blvd, Southaven, MS 38671, US
308. Gallant & Wein NJ Corp, 11-20 43rd Rd, Long Island City, NY 11101, US
309. GATEWAY MEGATECH, 58 Jonspin Rd, Wilmington, MA 01887, US
310. GEMCAP INC., 623 BICYCLE PATHPORT, JEFFERSON STATION, NY 11776, US
311. GENIE GROUP INC, STE 100, 300 BEASLEY DR, FRANKLIN, TN 37064, US
312. GENUINE AIRCRAFT HARDWARE, 4250 AEROTECH CENTER WAY, PASO ROBLES, CA 93446, US
313. GLOBAL CABLE & ELECTRONIC, Ste B745 W Winder Industrial Pkwy, Winder, GA 30680, US
314. GO ELECTRONICS, 360 HICKMAN DR., SANFORD, FL 32771, US
315. GO ELECTRONICS, 5218 N SHOBE RD, ALEXANDER, AR 72022, US
316. GO ELECTRONICS, 6451 INDUSTRIAL LOOP, GREENDALE, WI 53129, US
317. GO ELECTRONICS, STE. 1, 301 ROYA LN., BRYANT, AR 72022, US
318. GO ELECTRONICS, STE. 109, 105 SOUTHEAST PKWY., FRANKLIN, TN 37064, US
319. GO ELECTRONICS, STE. 960, 27501 SW 95TH AVE., WILSONVILLE, OR 97070, US
320. GO ELECTRONICS, UNIT 223, 203 CONCORD ST., PAWTUCKET, RI 02860, US
321. GO ELECTRONICS-MN, 3433 E. 25TH ST., MINNEAPOLIS, MN 55406, US
322. GOPHER ELECTRONICS CO INC, 222 LITTLE CANADA RD E, SAINT PAUL, MN 55117, US
323. Gopher Electronics Co Inc, 222 Little Canada Rd E, St Paul, MN 55117, US
324. GREAT LAKES WIRE & CABLE, 31845 DENTON DR, WARREN, MI 48092, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

- 325. Guillevin International, 229 Adelaide St. North, London, ON N6B 3, US
- 326. HAIDAR INC., 2906 SPRINGBROOK ROAD, CRYSTAL LAKE, IL 60012, US
- 327. HAMMOND ELECTRONICS INC, 22-C OAK BRANCH DR, GREENSBORO, NC 27407, US
- 328. HAMMOND ELECTRONICS INC., 1230 W. CENTRAL BLVD., ORLANDO, FL 32805, US
- 329. HAMMOND ELECTRONICS INC., 6600 NW 21ST AVE., BAY D, FORT LAUDERDALE, FL 33309, US
- 330. HAMMOND ELECTRONICS INC., STE. 150, 1360 PRESIDENTIAL DR., RICHARDSON, TX 75081, US
- 331. Hawk Electronics, Equipment Co., Louisville, KY 40201, US
- 332. HAWK ELECTRONICS, NORTH DOCK, 511 GLENN AVE, WHEELING, IL 60090, US
- 333. HEARTLAND ELECTRONICS INC, 4150C INDUSTRIAL DR, SAINT PETERS, MO 63376, US
- 334. HEILIND ELECTRONICS INC, BRANCH CODE 18, 7030 WOODBINE AVE STE 500, MARKHAM ONTARIO, CA
- 335. HEILIND ELECTRONICS INC, STE 146, 150 S SUNNY SLOPE RD, BROOKFIELD, WI 53005, US
- 336. HEILIND ELECTRONICS, 100 S TURNPIKE RD, WALLINGFORD, CT 06492, US
- 337. HEILIND ELECTRONICS, 18 INDUSTRIAL DR, HUDSON, NH 03051, US
- 338. HEILIND ELECTRONICS, 317 S. NORTHLAKE BLVD., BRANCH CODE 15, ALTAMONTE SPRINGS, FL 32701, US
- 339. HEILIND ELECTRONICS, 5300 AVION PARK DR., HIGHLAND HEIGHTS, OH 44143, US
- 340. Heilind Electronics, 58 Jonspin Rd, Wilmington, MA 01887, US
- 341. HEILIND ELECTRONICS, STE 140, 450 E DEVON AVE, ITASCA, IL 60143, US
- 342. HEILIND ELECTRONICS, STE 202, 520 COLUMBIA DR, JOHNSON CITY, NY 13790, US
- 343. HEILIND ELECTRONICS, STE A, 435 DIVIDEND DR, PEACHTREE CITY, GA 30269, US
- 344. HEILIND ELECTRONICS, STE E, 6365 CARLSON DR., EDEN PRAIRIE, MN 55346, US
- 345. HEILIND ELECTRONICS, STE G50, 115 US HIGHWAY 46, MOUNTAIN LAKES, NJ 07046, US
- 346. HEILIND ELECTRONICS, STE. 105, 2300 WESTINGHOUSE BLVD., RALEIGH, NC 27604, US
- 347. HEILIND ELECTRONICS, STE. 203A, 2550 EISENHOWER AVE., NORRISTOWN, PA 19403, US
- 348. Herman Electronics Atlanta, 7350 HERMAN WAY, MIAMI, FL 33122, US
- 349. HI-LINE ELECTRIC CO., 2121 VALLEY VIEW LN., DALLAS, TX 75234, US
- 350. HMC ELECTRONICS, 33 SPRINGDALE AVE., CANTON, MA 02021, US
- 351. Hughes-Peters Inc, 8000 Technology Blvd., Huber Heights, OH 45424, US
- 352. HUGHES-PETERS INC, STE 210, 10325 LANDBURY DR, HOUSTON, TX 77099, US
- 353. HUGHES-PETERS INC, UNIT B, 5333 COMMERCE SQUARE DR, INDIANAPOLIS, IN 46237, US
- 354. HUTCH & SON INC, 300 N. MAIN ST., EVANSVILLE, IN 47711, US
- 355. I V R I INC., 730 N. FRANKLIN ST., YORK, PA 17403, US
- 356. Impulse Technologies Ltd., 920 Gana Crt, MISSISSAUGA, ON L5S 1, US
- 357. INDUSTRIAL ELECTRIC WIRE & CABLE, 5001 S. Towne Dr., New Berlin, WI 53151, US
- 358. INDUSTRIAL SUPPLY, 1905 WESTWOOD AVE., RICHMOND, VA 23227, US
- 359. INDUSTRIAL TRADE SUPPLY, 6415 INDEPENDENCE AVE., WOODLAND HILLS, CA 91367, US
- 360. INSULATION SUPPLY COMPANY, 1901 HARPERS WAY, TORRANCE, CA 90501, US
- 361. INTEGRATED PROCUREMENT TECHNOLOGIES, 360S HOPE BLDG C-200, SANTA BARBARA, CA 93105, US
- 362. Interstate Connecting, Components Inc310A Commerce Dr, MOORESTOWN, NJ 08057, US
- 363. INTERSTATE WIRE COMPANY, PO BOX 38413, DALLAS, TX 75238, US
- 364. J P Simons Co, 1426 Brook Dr, Downers Grove, IL 60515, US
- 365. J P SIMONS CO., 1426 BROOK DR, DOWNERS GROVE, IL 60515, US
- 366. JENKINS SUPPLY, 943 WESTWOOD DR, MARRERO, LA 70072, US
- 367. Jentronics Ltd, 15 Weston Ct, Dartmouth, NS B3B 1, US
- 368. JET COMPONENTS, 62 BRIDGE ROAD, ISLANDIA, NY 11749, US
- 369. JO-KELL INC, 1716 LAMBERT CT., CHESAPEAKE, VA 23320, US
- 370. K C ELECTRONICS, 186 N BELLE MEAD RD, EAST SETAUKET, NY 11733, US
- 371. K C Electronics, 186 N. Belle Mead Rd., East Setauket, NY 11733, US
- 372. KAUFMAN CO. INC., 19 WALKHILL ROAD, NORWOOD, MA 02062, US
- 373. KENSINGTON ELECTRONICS, INC, STE 150, 11801 STONEHOLLOW DR, AUSTIN, TX 78758, US
- 374. Key Electronic Solutions LLC, 623 Distributors Row Ste. D, NEW ORLEANS, LA 70123, US
- 375. KIMBALL ELECTRONICS INC, 1400 W. 3RD AVE., DENVER, CO 80223, US
- 376. KIMBALL ELECTRONICS INC, 2233 S. 300 E., SALT LAKE CITY, UT 84115, US
- 377. KIMBALL ELECTRONICS INC, 652 N. FIVE MILE RD., BOISE, ID 83713, US
- 378. KIMBALL ELECTRONICS INC, 953 A S. MAIN ST., POCATELLO, ID 83204, US
- 379. KIMBALL ELECTRONICS INC., 652 N. FIVE MILE RD., BOISE, ID 83713, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

- 380. Kimco Distributing Corp., 6353 W. Rogers Cir. Ste. 3, Boca Raton, FL 33487, US
- 381. Koehlke Components Inc, 1201 Commerce Center Dr, Franklin, OH 45005, US
- 382. LADD INDUSTRIES, 4849 HEMPSTEAD STATION DR, KETTERING, OH 45429, US
- 383. LAKELAND ENG. EQUIP. CO., 4865 G ST., OMAHA, NE 68117, US
- 384. Lambo Kitting, 9 - 30 Capilano Way, British Columbia, New Westminster, BC, CA
- 385. Lapp Tannehill Inc, Ste 9008675 Eagle Creek Pkwy, Savage, MN 55378, US
- 386. LAUGHLIN SUPPLY CO, 12301 E MARGINAL WAYS NSTR, SEATTLE, WA 98168, US
- 387. LEEPORT ELECTRONICS LTD., 1/F BLODK 1 GOLDEN DRAGON, INDL CTR. 152-160 TAI LIN, PAI RD. KWAI CHUNG NT, HONG KONG, CN
- 388. MARCH ELECTRONICS, 25 FELDLAND ST, BOHEMIA, NY 11716, US
- 389. Marinette Marine, 727 S Washington St, Shawano, WI 54166, US
- 390. MARSH ELECTRONICS INC, MAIN WAREHOUSE, 1563 S. 101ST ST., MILWAUKEE, WI 53214, US
- 391. MARSH ELECTRONICS INC., CHICAGO MAIN WAREHOUSE, 203 SUNBURY DR., SAINT CHARLES, IL 60175, US
- 392. MARSH ELECTRONICS INC., CLEVELAND MAIN WAREHOUSE, 2202 E. ENTERPRISE PKWY., TWINSBURY, OH 44087, US
- 393. MARSH ELECTRONICS INC., COLUMBUS MAIN WAREHOUSE, 3040 RIVERSIDE DR. #114, COLUMBUS, OH 43221, US
- 394. MARSH ELECTRONICS INC., INDIANAPOLIS MAIN WHSE., STE. 101, 15529 STONY CREEK WAY, NOBLESVILLE, IN 46060, US
- 395. MARSH ELECTRONICS INC., N1042 TOWER VIEW DR, GREENVILLE, WI 54942, US
- 396. MARSH ELECTRONICS, STE 220, 2155 STONINGTON AVE, HOFFMANESTATES, IL 60192, US
- 397. MASLINE ELECTRONICS, 511 CLINTON AVE S, ROCHESTER, NY 14620, US
- 398. MASTER DISTRIBUTORS, 1220 OLYMPIC BLVD., SANTA MONICA, CA 90404, US
- 399. MASTER DISTRIBUTORS, 12506 130TH LN. NE, KIRKLAND, WA 98034, US
- 400. MASTER DISTRIBUTORS, 2328 WALSH AVE STE A, SANTA CLARA, CA 95051, US
- 401. MASTER DISTRIBUTORS, 2400 W SCHNEIDMAN DR, QUINCY, IL 62305, US
- 402. MASTER DISTRIBUTORS, 2425 S. 21ST ST., PHOENIX, AZ 85034, US
- 403. MASTER DISTRIBUTORS, 3100 NW 36TH ST., MIAMI, FL 33142, US
- 404. MASTER DISTRIBUTORS, 610 E. 10TH ST., OAKLAND, CA 94606, US
- 405. MASTER DISTRIBUTORS, 8359 N STEVEN RD, MILWAUKEE, WI 53223, US
- 406. MASTER DISTRIBUTORS, 8400 N ALLEN RD., PEORIA, IL 61615, US
- 407. MASTER DISTRIBUTORS, 842 S. 7TH ST., LOUISVILLE, KY 40203, US
- 408. MASTER DISTRIBUTORS, STE. 103, 9701 DESSAU RD., AUSTIN, TX 78754, US
- 409. MASTER INTERNATIONAL CORP, ONLINECOMPONENTS.COM, 2425 S. 21ST ST., PHOENIX, AZ 85034, US
- 410. MATERIAL MANAGEMENT GROUP INC, 2319 E. Pensar Dr., APPLETON, WI 54911, US
- 411. MATERIALES ELECTRICOS LORI,S.A, AV. NUECES NO 176-1, COL.NUEVA SANTA MARIA, MEXICO, D.F., MEXICO, D.F., DF 02800, US
- 412. MATRIX ENTERPRISES, 2864 NORTHRIDGE DR NW, GRAND RAPIDS, MI 49534, US
- 413. Matrix Technology, 161 Alden Road, Unit 9, Markham, ON L3R 3, US
- 414. Maverick Electronics, 58 Jonspin Rd, Wilmington, MA 01887, US
- 415. MCMaster-CARR SUPPLY CO, 200 AURORA INDL. PKWY., AURORA, OH 44202, US
- 416. MCMaster-CARR SUPPLY CO, 200 NEW CANTON WAY, ROBBINSVILLE, NJ 08691, US
- 417. MCMaster-CARR SUPPLY CO, 600 N COUNTY LINE RD, ELMHURST, IL 60126, US
- 418. MCMaster-CARR SUPPLY CO, 9630 NORWALK BLVD, SANTA FE SPRINGS, CA 90670, US
- 419. MCMaster-CARR SUPPLY, 200 NEW CANTON WAY, ROBBINSVILLE, NJ 08691, US
- 420. MCMaster-CARR SUPPLY, 6100 FULTON INDL BLVD SW., ATLANTA, GA 30336, US
- 421. MEIJI CORPORATION USA, STE 120, 1510 NEWTOWN PIKE, LEXINGTON, KY 40511, US
- 422. METRO RELIABLE RESOURCES, 64 AVON CIRCLE, NEEDHAM, MA 02494, US
- 423. Miamb Marriott Hotels & Resorts, Ste 5002018 Powers Ferry Rd, ATLANTA, GA 30339, US
- 424. MIAMI WAREHOUSE, 7350 HERMAN WAY, MIAMI, FL 33122, US
- 425. MICROWAVE COMPONENTS INC., UNIT 5, 3171 SE. DOMINICA TER., STUART, FL 34997, US
- 426. MIDSTATE ELECTRONICS CO., 71 S. TURNPIKE RD, WALLINGFORD, CT 06492, US
- 427. Milcor Industries, 70 Kinderkamack Rd., Emerson, NJ 07630, US
- 428. Milrail Incorporated, 111 Gun Street, Pointe Claire, QC H9R 3, US
- 429. MONTANA DATA COM, 35-15 11th Street, Long Island City, NY 11106, US
- 430. MOTION INDUSTRIES INC., 2680 CHURCH AVE., FRESNO, CA 93706, US
- 431. MOTION INDUSTRIES, 1880 S. FLORENCE CT., WICHITA, KS 67209, US
- 432. MOUSER ELECTRONICS, 1000 N. MAIN ST., MANSFIELD, TX 76063, US
- 433. Mouser Electronics, 1000 N. Main Street, Mansfield, TX 76063, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

- 434. MOUSER ELECTRONICS, STE 101, 1810 GILLESPIE WAY, EL CAJON, CA 92020, US
- 435. Murray A. Percival Co., 2014 Brown Road, Auburn Hills, MI 48326, US
- 436. NEDCO ELECTRONICS, 1169 KNOLLWOOD CIR., ANAHEIM, CA 92801, US
- 437. NEDCO ELECTRONICS, 12110 PRICHARD FARM RD., MARYLAND HEIGHTS, MO 63043, US
- 438. NEDCO ELECTRONICS, 505 CHADDICK DR, WHEELING, IL 60090, US
- 439. NEDCO ELECTRONICS, 5230 PARK EMERSON DR #A, INDIANAPOLIS, IN 46203, US
- 440. NEDCO ELECTRONICS, 594 AMERICAN WAY, PAYSON, UT 84651, US
- 441. NEDCO ELECTRONICS, 990 LONE OAK RD STE 136, EAGAN, MN 55121, US
- 442. NEDCO ELECTRONICS, STE. 200, 2500 E. RANDOL MILL RD., ARLINGTON, TX 76011, US
- 443. Nelson & Wright, Bar Mills, ME 04004, US
- 444. NEP ELECTRONICS, DO NOT ACTIVATE, SEE STD & ADDL INSTR, 805 MITTEL DR., WOOD DALE, IL 60191, US
- 445. NEW JERSEY WAREHOUSE, 7350 HERMAN WAY, MIAMI, FL 33122, US
- 446. NEWARK (A3), 1080 WOODCOCK RD, ORLANDO, FL 32803, US
- 447. NEWARK (H2), STE 300, 1200 PLACID AVE, PLANO, TX 75074, US
- 448. NEWARK ELECTRONICS PULASKI RDC, 4801 N Ravenswood Ave, Chicago, IL 60640, US
- 449. NEWARK ELECTRONICS, 4801 N Ravenswood Ave, Chicago, IL 60640, US
- 450. Newark Electronics, C/O UPS Logistics Group Canada 6375 Dixie Rd Ste 202, Mississauga, ON L5T 2, US
- 451. NEWARK, 217 WILCOX AVE, GAFFNEY, SC 29341, US
- 452. Newark, 331 Consortium Court, London, ON N6E 2, US
- 453. NEWARK, 405 PIONEER RD, SPRINGBORO, OH 45066, US
- 454. NEWARK, STE 462, 4801 N RAVENSWOOD AVE, CHICAGO, IL 60640, US
- 455. NEWCASTLE INDUSTRIES INC, 2664 S. LA CIENEGA BLVD., LOS ANGELES, CA 90034, US
- 456. NORSTAN ELECTRONICS INC, 1911 E CARNEGIE AVE, SANTA ANA, CA 92705, US
- 457. NORVELL ELECTRONICS, 1850 LITTLE ORCHARD ST., SAN JOSE, CA 95125, US
- 458. NORVELL ELECTRONICS, 2251 CHENNAULT DR., CARROLLTON, TX 75006, US
- 459. Park Distributors, 347 Railroad Ave., Bridgeport, CT 06604, US
- 460. PEERLESS ELECTRONIC, EQUIPMENT CO, 1815 S 7TH ST, LOUISVILLE, KY 40208, US
- 461. Peerless Electronics Inc, Ste 100300 Beasley Dr, Franklin, TN 37064, US
- 462. Peerless Electronics Inc, Bethpage, NY 11714, US
- 463. PEERLESS ELECTRONICS INC, GATE 3, 700 HICKSVILLE RD., BETHPAGE, NY 11714, US
- 464. PEERLESS ELECTRONICS INC, STE. 120, 6716 ALEXANDER BELL DR., COLUMBIA, MD 21046, US
- 465. Phoenix/EDT, 2299 Drew Road, Unit 26, Mississauga, ON L5S 1, US
- 466. Plastic Supply Inc., 2109 Candelaria NE, Albuquerque, NM 87107, US
- 467. POWELL ELECTRONICS INC, 200 COMMODORE DR, SWEDESBORO, NJ 08085, US
- 468. POWELL ELECTRONICS INC, STE 130, 4500 FULLER DR, IRVING, TX 75038, US
- 469. POWELL ELECTRONICS INC, STE 210, 4 MOUNT ROYAL AVE, MARLBOROUGH, MA 01752, US
- 470. PRECISION RADIO LIMITED, 1160 S KING ST, HONOLULU, HI 96814, US
- 471. Primo Instruments, 4407 Charleroi, Montreal Nord, QC H1H 1, US
- 472. Production Dynamics of, Chicago 9551 S Cottage Grove Ave, CHICAGO, IL 60628, US
- 473. QPL Electronic Distrib, NUTTING LAKE, MA 01865, US
- 474. R & K SUPPLY CO, 16 FINCH ST., HILTON HEAD ISLAND, SC 29926, US
- 475. Radar Electric, 22214 20th Ave. SE, Bothell, WA 98021, US
- 476. RADAR INC, 223 E PACIFIC AVE, SPOKANE, WA 99202, US
- 477. RADAR INC, DOOR 6, 22214 20TH AVE. SE, BOTHELL, WA 98021, US
- 478. RADAR INC, STE 18H, 8309 SW CIRRRUS DR, BEAVERTON, OR 97008, US
- 479. RADAR INC, STE I, 11770 W PRESIDENT DR, BOISE, ID 83713, US
- 480. REFRIGERADORES DE GUATEMALA SA, 3A AV 8-92 ZONA 3 LOTIFICACION, COL. EL ROSARIO MIXCO, GUATEMALA C.A., GUATEMALA C.A., GT 1007, US
- 481. RELAY SPECIALTIES, 17 RARITAN RD., OAKLAND, NJ 07436, US
- 482. Reptron Electronics Inc., 13700 Reptron Blvd., Tampa, FL 33626, US
- 483. RESCO ELECTRONICS, 4961 MERCANTILE RD., NOTTINGHAM, MD 21236, US
- 484. Reynolds And Son Inc., 47 Bridge St., South Barre, VT 05670, US
- 485. RICHARDSON ELECTRONICS, DK. 1, 40W267 KESLINGER RD., LAFOX, IL 60147, US
- 486. ROCKWELL AUTOMATION, INC., 5001 S. Towne Dr., New Berlin, WI 53151, US
- 487. Round the World Logistics USA Corp, 11719 Gunners Drive, Germantown, MD 20876, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

488. RS ELECTRONICS, 149 WELDON PKWY. STE. 109, MARYLAND HEIGHTS, MO 63043, US
489. RS ELECTRONICS, 150 EXECUTIVE CENTER DR., GREENVILLE, SC 29615, US
490. RS ELECTRONICS, 1885A BEAVER RIDGE CIR, NORCROSS, GA 30071, US
491. RS Electronics, 34443 Schoolcraft Rd, Livonia, MI 48150, US
492. RS ELECTRONICS, 34443 SCHOOLCRAFT RD., LIVONIA, MI 48150, US
493. RS ELECTRONICS, BLDG 3 STE 203, 3645 LINDEN AVE, GRAND RAPIDS, MI 49548, US
494. RS ELECTRONICS, STE. 330, 6701 W. 64 ST., OVERLAND PARK, KS 66202, US
495. RSI INC, CRI DIV, 1670 KOEHLER'S CROSSING, KYLE, TX 78640, US
496. SAGER CONSIGNMENT WHSE, C/O BAXTER HEALTH CARE, STE. 100, 7975 114TH AVE. N., LARGO, FL 33777, US
497. SAGER ELECTRONICS, 19 LEONA DR., MIDDLEBORO, MA 02346, US
498. Sager Electronics, 200 Matheson Blvd Ste 102, Mississauga, ON L5R 3, US
499. SAGER ELECTRONICS, 2001 E DYER RD STE 400, GROUP OF LOGISTICS, C/O TERRY BOWMAN, SANTA ANA, CA 92705, US
500. SAGER ELECTRONICS, 31225-H BAINBRIDGE RD., SOLON, OH 44139, US
501. SAGER ELECTRONICS, C/O BROKERS LOGISTICS, 1000 HAWKINS BLVD., EL PASO, TX 79915, US
502. SAGER ELECTRONICS, C/O BROKERS LOGISTICS, 8419 SAN GABRIEL, LAREDO, TX 78045, US
503. SAGER ELECTRONICS, C/O COOPER LGHING CONSGMT, 4115 S BROAD ST, ELLAVILLE, GA 31806, US
504. SAGER ELECTRONICS, C/O PLOUGH ELECTRIC SUPPL, 1155 BRYANT ST., SAN FRANCISCO, CA 94103, US
505. SAGER ELECTRONICS, C/O WOW LOGISTICS CO., 2690 BADGER AVNEUE, OSHKOSH, WI 54904, US
506. SAGER ELECTRONICS, GS001 WAREHOUSE, 119 HARRISON AVE, ROSELAND, NJ 07068, US
507. SAGER ELECTRONICS, STE 200, 17330 BROOKHURST ST, FOUNTAIN VALLEY, CA 92708, US
508. SAGER ELECTRONICS, STE 900, 1000 JUPITER RD, PLANO, TX 75074, US
509. SDI INC, C/O SANDEN INTERNATIONAL, 601 SANDEN BLVD., WYLIE, TX 75098, US
510. SELTEK, 5130 GATEWAY E, EL PASO, TX 79905, US
511. SHERBURN ELECTRONICS CORP, 175 COMMERCE DR, HAUPPAUGE, NY 11788, US
512. Sidco, 1043 DiGiulio Ave., Santa Clara, CA 95050, US
513. Silver State Wire & Cable Inc., Ste. P625 Spice Island Dr., Sparks, NV 89431, US
514. Simcona Electronics of Canada Inc., 3422 Wonderland Road S., London, ON N6L 1, US
515. SIMCONA ELECTRONICS, 275 Mount Read Blvd, Rochester, NY 14606, US
516. SIMCONA ELECTRONICS, BLDG 2, 335 MOUNT READ BLVD, ROCHESTER, NY 14611, US
517. SOUTHERN CALIFORNIA CONNECTOR, 930 Via Alondra, CAMARILLO, CA 93012, US
518. SOUTHERN CONTROLS INC., 3511 WETUMPKA HWY., MONTGOMERY, AL 36110, US
519. SOUTHERN CONTROLS INC., 401 PINE VALLEY CIR., BESSEMER, AL 35022, US
520. SOUTHERN CONTROLS INC., 826-B LAKESIDE DR., MOBILE, AL 36693, US
521. SOUTHERN CONTROLS INC., 924 4TH AVE. SE, DECATUR, AL 35601, US
522. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, 1885 HARLEM RD., CHEEKTOWAGA, NY 14212, US
523. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, 2020 ALEN ST EXTENSION, FALCONER, NY 14733, US
524. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, 24 WATER ST., BINGHAMTON, NY 13902, US
525. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, 727 AZON RD, JOHNSON CITY, NY 13790, US
526. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, 900 CHURCH ST E, ELMIRA, NY 14901, US
527. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, SOUTHWEST OHIO DIV, 6196 POE AVE, DAYTON, OH 45414, US
528. SOUTHERN ELECTRIC SUPPLY, DBA REXEL, STE. 5000, 1344 UNIVERSITY AVE., ROCHESTER, NY 14607, US
529. Southern Electric Supply, DBA Rexel1049 Prince Geroges Blvd, Upper Marlboro, MD 20774, US
530. SOUTHERN ELECTRONICS SUPPLY, 1909 Tulane #14, New Orleans, LA 70112, US
531. SPARTAN INDUSTRIAL SUPPLY, C/O ITRON ELECTRICITY, METERING, 313 N HWY 11 DOCK C, WEST UNION, SC 29696, US
532. SPECIALIZED PRODUCTS, 1100 S. KIMBALL AVE., SOUTHLAKE, TX 76092, US
533. SPECIALTY BOLT & SCREW, 235 BOWLES RD., AGAWAM, MA 01001, US
534. SPECTRONICS, 1206 MONTLIMAR DR, MOBILE, AL 36609, US
535. STAG ENTERPRISE INC., Ste A2010 Cobb Intl Blvd NW, KENNESAW, GA 30152, US
536. Stanley Supply & Services, 335 Willow St., North Andover, MA 01845, US
537. STANLEY SUPPLY & SERVICES, 7815 S 46TH ST, PHOENIX, AZ 85044, US
538. STANLEY SUPPLY & SERVICES, CENTRAL DISTRIBUTION CTR, 4444 W MONTROSE AVE, CHICAGO, IL 60641, US
539. STANLEY SUPPLY & SERVICES, RIVEREDGE BUSINESS PARK, 111 LAKE DR STE A, NEWARK, DE 19702, US
540. STARFLIGHT AEROSPACE INC, 503 N QUEEN ST, FONDA, IA 50540, US
541. STARK ELECTRONICS, 401 ROYALSTON AVE N, MINNEAPOLIS, MN 55405, US
542. Stark Electronics, Attn Accts Payable401 Royalston Ave N, Minneapolis, MN 55405, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

543. STATE ELECTRONICS, 36 ROUTE 10, EAST HANOVER, NJ 07936, US
544. STERLING WIRE & CABLE LLC, 1117 ALDRICH AVE. NORTH, MINNEAPOLIS, MN 55411, US
545. STEVEN ENGINEERING INC, 230 RYAN WAY, S SAN FRANCISCO, CA 94080, US
546. STRANCO PRODUCTS INCORPORATED, 650 S. Schmidt Rd., BOLINGBROOK, IL 60440, US
547. Sujo Systems, Ste 41498 N Saginaw St, Lapeer, MI 48446, US
548. SUMINISTROS TECNICOS, FRESNOS No 1820, COL. VILLA FLORIDA, MONTERREY, NUEVO LEON, MONTERREY, NUEVO L, NL 64810, US
549. Summit Aviation Supply, 1008 Teaneck Rd, Teaneck, NJ 07666, US
550. SUN INDUSTRIES, SUITE 101, 370 AMAPOLA AVE, TORRANCE, CA 90501, US
551. Supersonic Services, Inc., Ste 10312399 SW. 53 St., Cooper City, FL 33330, US
552. TAG INTERNATIONAL INC, 959 TERMINAL WAY, SAN CARLOS, CA 94070, US
553. Taylor Industrial, Los Angeles, CA 90025, US
554. TC Services, 9624 Girard Ave., Bloomington, MN 55431, US
555. TEAMMAX CORP, 470 WILDWOOD AVE, WOBURN, MA 01801, US
556. TECHNI TOOL INC, 1547 N. TROOPER RD., WORCESTER, PA 19490, US
557. TECRA TOOL INDUSTRIES, UNIT C, 2452 S. TRENTON WAY, DENVER, CO 80231, US
558. TELTEC INC, 7890 12TH AVE S, MINNEAPOLIS, MN 55425, US
559. The Bernd Group, Dunedin, FL 34697, US
560. The Bernd Group, INC, Dunedin, FL 34697, US
561. THOMPSON ELCTR N SUPPLIES, 2050 FAIRWOOD AVE, COLUMBUS, OH 43207, US
562. THOMPSON ELCTR N SUPPLIES, 9605 KEARNY VILLA RD, STE C, SAN DIEGO, CA 92126, US
563. THOMPSON ELCTR N SUPPLIES, C/O GOLD MEDAL PRODUCTS, 10700 MEDALLION DR., CINCINNATI, OH 45241, US
564. THOMPSON ELECTRONICS, EMERSON NETWORK PESNA INC, C/O TEXAS FORWARDING SERV, 8311 KILLIAM IND BLVD, LAREDO, TX 78045, US
565. THOMPSON ELECTRONICS, N AMERICAN INTERCONNECT, NOGALES DISTRIBUTION CTR, 3269 N GRAND AVE STE A, NOGALES, AZ 85621, US
566. TIME MOTION TOOLS, 12778 BROOKPRINTER PL., POWAY, CA 92064, US
567. TOOLS FOR INDUSTRY CORP., STE. 5, 856 JOHNSON AVE., RONKONKOMA, NY 11779, US
568. TRI-COM Inc, 359 E Madison Ave, CLIFTON HEIGHTS, PA 19018, US
569. TRIUMPH COMPONENTS INC., 175P NEW BOSTON ST., WOBURN, MA 01801, US
570. TTI (AL), STE 201, 150 W. PARK LOOP, HUNTSVILLE, AL 35806, US
571. TTI (AU), STE 235, 5910 COURTYARD DR, AUSTIN, TX 78731, US
572. TTI (FL), STE 801, 5810 HOFFNER AVE, ORLANDO, FL 32822, US
573. TTI (H), 2441 NORTHEAST PKWY, FORT WORTH, TX 76106, US
574. TTI (MA), 3 HIGHWOOD DR W, TEWKSBURY, MA 01876, US
575. TTI (NJ), 1 EXECUTIVE DR. STE. 9, MOORESTOWN, NJ 08057, US
576. TTI (OR), STE. 202, 7185 SW SANDBURG RD., TIGARD, OR 97223, US
577. TTI, 2441 Northeast Pkwy, Fort Worth, TX 76106, US
578. TTI, CONNECTOR DIV, 2601 SYLVANIA CROSS DR, FORT WORTH, TX 76137, US
579. TW CABLE LLC, 81 EXECUTIVE BLVD, FARMINGDALE, NY 11735, US
580. Unilux V.F.C. Corp., 140 Hanlan Rd., Unit B, Woodbridge, ON L4L 3, US
581. United Fasteners Co Inc, DO NOT ACTIVATE REFER, TO WALDOM 800 892 5366, 25 Drexel Dr, Bay Shore, NY 11706, US
582. UNITED GLOBAL SOURCING, 269 EXECUTIVE DR., TROY, MI 48083, US
583. VAN ASCHE INDUSTRIAL, SUPPLY INC., 204 US HWY. 412, SILOAM SPRINGS, AR 72761, US
584. VIRGINIA ELECTRONIC COMP., CHARLOTTESVILLE, VA 22901, US
585. Waco Electronics, 4900 Monaco Pky, Commerce City, CO 80022, US
586. WALDOM ELECTRONICS CORP, 1801 MORGAN ST., ROCKFORD, IL 61102, US
587. WALKER COMPONENT GROUP, 13400 NORTHRUP WAY STE 31, BELLEVUE, WA 98005, US
588. WALKER COMPONENT GROUP, 1795 E. 66TH AVE., DENVER, CO 80229, US
589. WALKER COMPONENT GROUP, 25691 ATL OCEAN DR B18, LAKE FOREST, CA 92630, US
590. WALKER COMPONENT GROUP, 3688 W 2100 S, WEST VALLEY CITY, UT 84120, US
591. WALKER COMPONENT GROUP, CSID/I.E.C., 3720 SW 141ST ST. #102, BEAVERTON, OR 97005, US
592. WALKER COMPONENT GROUP, STE 140, 9960 BUSINESS PARK DR, SACRAMENTO, CA 95827, US
593. Walker Components Group, (CSID/I.E.C.)420 E 58TH Ave, Denver, CO 80216, US
594. WALLACE ELECTRONICS, 10551 MILLER RD STE 300, DALLAS, TX 75238, US
595. WALLACE ELECTRONICS, 13720 W. POLO TRAIL DR., LAKE FOREST, IL 60045, US

Manufacturer and Supplier Location Information

Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)

Location: 1396 Charlotte Highway, Fairview, NC 28730-9798, US

Authorized Distributors:

- 596. WASSCO, 12778 Brookprinter Place, Poway, CA 92064, US
- 597. WAYTEK INC, 2440 GALPIN CT, CHANHASSEN, MN 55317, US
- 598. Wesco Distribution Canada LP, 640 Cataraqui Woods Dr, Kingston, ON K7P 2, US
- 599. WES-GARDE COMPONENTS GRP, 190 ELLIOTT ST., HARTFORD, CT 06114, US
- 600. WES-GARDE COMPONENTS GRP, 376 E. GUNDERSEN DR., CAROL STREAM, IL 60188, US
- 601. WES-GARDE COMPONENTS GRP, 5816 CORPORATE AVE., SUITE 150, ORANGE COUNTY, CA 90630, US
- 602. WES-GARDE COMPONENTS GRP, 75 LOCUST ST., HARTFORD, CT 06114, US
- 603. WES-GARDE COMPONENTS GRP, 8940 QUARTZ AVE., NORTHRIDGE, CA 91324, US
- 604. WES-GARDE COMPONENTS GRP., 300 ENTERPRISE DR., WESTERVILLE, OH 43081, US
- 605. WES-GARDE COMPONENTS GRP., 3815 INDUSTRY BLVD., LAKELAND, FL 33811, US
- 606. WES-GARDE COMPONENTS GRP., CORPORATE WAREHOUSE, STE. 300, 4301 RIDER TRL., EARTH CITY, MO 63045, US
- 607. WES-GARDE COMPONENTS GRP., STE. 103, 621 HUTTON ST., RALEIGH, NC 27606, US
- 608. WES-GARDE COMPONENTS GRP., STE. 320, 6230 N. BELTLINE RD., IRVING, TX 75063, US
- 609. WES-GARDE COMPONENTS GRP., STE. W, 9150 SW PIONEER CT., WILSONVILLE, OR 97070, US
- 610. WES-GARDE COMPONENTS, 194 ELLIOTT ST., HARTFORD, CT 06114, US
- 611. WIRENETICS, 27737 HOPKINS AVE, VALENCIA, CA 91355, US
- 612. WORLD MICRO COMPONENTS, 7730 ROSWELL RD - STE 400, ATLANTA, GA 30350, US
- 613. XP POWER INC, 990 BENECIA AVE, SUNNYVALE, CA 94085, US
- 614. ZIEGLER TOOLS INC., RHEEM MANUFACTURING, ATTN: ZIEGLER TOOLS, 138 ROBERSON MILL RD., MILLEDGEVILLE, GA 31061, US