

**DLA Land and Maritime - VQ**  
**Supplemental Information Sheet for Electronic QPL-83726**

Date: 12/14/2023

**Specification Details:**

Specification: MIL-PRF-83726  
 Title: Relays, Hybrid and Solid State, Time Delay  
 Federal Supply Class (FSC): 5945  
 Conventional: No  
 Specification contains quality assurance program: No  
 MIL-STD-790 Established Reliability & High Reliability: Yes  
 MIL-STD-690 Failure Rate Sampling Plans & Procedures: Yes  
 Weibull Graded: No  
 Specification contains space level reliability requirements: No  
 Specification allows test optimization: No

**Contact Information:**

Office of Primary Involvement: Hybrid Devices Branch, DLA Land and Maritime - VQH  
 Primary Qualifying Activity Contact: 614-692-6826, e-mail: vqh.cj@dla.mil  
 Secondary Qualifying Activity Contact: 614-692-1566, e-mail: vqh.js@dla.mil

**Notes:**

Contact the manufacturer or refer to the manufacturers website for a list of Authorized Distributors.

**Part Configuration:**

M83726/5-0001P

| Designator | Specif-<br>ication<br>Number | Specif-<br>ication<br>Sheet | Dash<br>Number | Mounting<br>Type |
|------------|------------------------------|-----------------------------|----------------|------------------|
| M          | 83726                        | /5                          | -0001          | P                |

| PART LISTINGS                                                                                    |                                                 |                                       |                                           |
|--------------------------------------------------------------------------------------------------|-------------------------------------------------|---------------------------------------|-------------------------------------------|
| GOVERNMENT<br>DESIGNATION                                                                        | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
| <b>MIL-R-83726/7 Inactive For New Design After 22 July 1992 (Use MIL-PRF-83726/28)</b>           |                                                 |                                       |                                           |
| M83726/7-0600<br>through<br>3003                                                                 | 93410-0600W<br>through<br>93410-3003W           | 83726-144-99                          | B.C. Systems                              |
| <b>MIL-R-83726/8 Inactive For New Design After 22 July 1992 (Use MIL-PRF-83726/29)</b>           |                                                 |                                       |                                           |
| M83726/8-1000<br>through<br>3003                                                                 | 93411-1000W<br>through<br>93411-3003W           | 83726-144-99                          | B.C. Systems                              |
| <b>MIL-R-83726/12 Inactive For New Design After 22 July 1992 (Use MIL-PRF-83726/29)</b>          |                                                 |                                       |                                           |
| M83726/12-1000<br>through<br>3003                                                                | TD-1369-1000W<br>through<br>TD-1369-3003W       | 83726-97-0111                         | Leach International                       |
| <b>MIL-R-83726/14 Inactive For New Design After 25 June 1993 (Use MIL-PRF-83726/28)</b>          |                                                 |                                       |                                           |
| M83726/14-1000<br>through<br>3003                                                                | TD-1370-1000W<br>through<br>TD-1370-3003W       | 83726-97-0112                         | Leach International                       |
| <b>MIL-R-83726/18 Inactive for New Design after 23 June 1995 (No Superseding Standard)</b>       |                                                 |                                       |                                           |
| M83726/18-1000W<br>through<br>3003W                                                              | MRTD210-1000W<br>through<br>MRTD210-3003W       | 83726-97-0151; 83726-97-0154          | DRI Relays, Inc.                          |
| <b>MIL-R-83726/19 Inactive for New Design after 23 June 1995 (No Superseding Standard)</b>       |                                                 |                                       |                                           |
| M83726/19-1000W<br>through<br>3003W                                                              | MOTD210-1000W<br>through<br>MOTD210-3003W       | 83726-97-0151; 83726-97-0154          | DRI Relays, Inc.                          |
| <b>MIL-PRF-83726/20 inactive for New Design after 15 November 2002 (No Superseding Standard)</b> |                                                 |                                       |                                           |
| M83726/20-0500W<br>through<br>5003W                                                              | TD-1435-0500W<br>through<br>TD-1435-5003W       | 83726-95-0062                         | Leach International                       |
| M83726/20-0500A<br>through<br>5003A                                                              | TD-1435-0500A<br>through<br>TD-1435-5003A       | 83726-95-0062                         | Leach International                       |

| PART LISTINGS                                                                                    |                                                 |                                       |                                           |
|--------------------------------------------------------------------------------------------------|-------------------------------------------------|---------------------------------------|-------------------------------------------|
| GOVERNMENT<br>DESIGNATION                                                                        | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
| <b>MIL-PRF-83726/21 inactive for New Design after 15 November 2002 (No Superseding Standard)</b> |                                                 |                                       |                                           |
| M83726/21-001                                                                                    | TD-1436-5000W                                   | 83726-95-0063                         | Leach International                       |
| M83726/21-002                                                                                    | TD-1436-5001W                                   | 83726-95-0063                         | Leach International                       |
| M83726/21-003                                                                                    | TD-1436-5002W                                   | 83726-95-0063                         | Leach International                       |
| M83726/21-004                                                                                    | TD-1436-5003W                                   | 83726-95-0063                         | Leach International                       |
| M83726/21-005                                                                                    | TD-1436-5000AW                                  | 83726-95-0063                         | Leach International                       |
| M83726/21-006                                                                                    | TD-1436-5001AW                                  | 83726-95-0063                         | Leach International                       |
| M83726/21-007                                                                                    | TD-1436-5002AW                                  | 83726-95-0063                         | Leach International                       |
| M83726/21-008                                                                                    | TD-1436-5003AW                                  | 83726-95-0063                         | Leach International                       |
| <b>MIL-R-83726/22 Inactive For New Design After 26 October 1993 (No Superseding Standard)</b>    |                                                 |                                       |                                           |
| M83726/22-1000W<br>through<br>6002W                                                              | TD-1412-1000W<br>through<br>TD-1412-6002W       | 83726-97-0073                         | Leach International                       |
| M83726/22-1000A<br>through<br>6002A                                                              | TD-1412-1000A<br>through<br>TD-1412-6002A       | 83726-97-0073                         | Leach International                       |
| <b>MIL-R-83726/23 Inactive For New Design After 10 November 1993 (Use MIL-PRF-83726/29)</b>      |                                                 |                                       |                                           |
| M83726/23-1000<br>through<br>7502                                                                | TD-1505-1000<br>through<br>TD-1505-7502         | 83726-97-0113                         | Leach International                       |
| <b>MIL-R-83726/24 Inactive For New Design After 23 June 1995 (No Superseding Standard)</b>       |                                                 |                                       |                                           |
| M83726/24-0500<br>through<br>5003                                                                | TDH-1609-0500<br>through<br>TDH-1609-5003       | 83726-97-0088                         | Leach International                       |
| <b>MIL-R-83726/25 Inactive For New Design After 23 June 1995 (NO Superseding Standard)</b>       |                                                 |                                       |                                           |
| M83726/25-0500<br>through<br>5003                                                                | TDH-1610-0500<br>through<br>TDH-1610-5003       | 83726-97-0089                         | Leach International                       |
| M83726/28-1000P<br>through<br>5003P                                                              | TDH-8050-1000P<br>through<br>TDH-8050-5003P     | 83726-3177-11                         | Leach International                       |
| M83726/28-1000S<br>through<br>5003S                                                              | TDH-8051-1000S<br>through<br>TDH-8051-5003S     | 83726-3177-11                         | Leach International                       |
| M83726/28-7500P                                                                                  | TDH-8050-7500P7500P                             | 83726-3177-11                         | Leach International North America         |
| M83726/28-7500S                                                                                  | TDH-8051-7500S7500S                             | 83726-3177-11                         | Leach International North America         |
| M83726/28-1000P<br>through<br>5003P                                                              | TD228-1000P<br>through<br>TD228-5003P           | 83726-2893-10; 83726-5328-19          | Tyco Electronics/CII Relays               |
| M83726/28-1000S<br>through<br>5003S                                                              | TD228-1000S<br>through<br>TD228-5003S           | 83726-2893-10; 83726-5328-19          | Tyco Electronics/CII Relays               |
| M83726/28-7500P                                                                                  | TD228-7500P7500P                                | 83726-2893-10; 83726-5328-19          | Tyco Electronics/CII Relays               |
| M83726/28-7500S                                                                                  | TD228-7500S7500S                                | 83726-2893-10; 83726-5328-19          | Tyco Electronics/CII Relays               |
| M83726/29-1000P<br>through<br>5003P                                                              | TDH-8070-1000P<br>through<br>TDH-8070-5003P     | 83726-3177-11                         | Leach International                       |
| M83726/29-1000S<br>through<br>5003S                                                              | TDH-8071-1000S<br>through<br>TDH-8071-5003S     | 83726-3177-11                         | Leach International                       |
| M83726/29-1000P<br>through<br>5003P                                                              | TD229-1000P<br>through<br>TD229-5003P           | 83726-5209-18                         | Tyco Electronics/CII Relays (India)       |
| M83726/29-1000S<br>through<br>5003S                                                              | TD229-1000S<br>through<br>TD229-5003S           | 83726-5209-18                         | Tyco Electronics/CII Relays (India)       |

| PART LISTINGS                       |                                                 |                                       |                                           |
|-------------------------------------|-------------------------------------------------|---------------------------------------|-------------------------------------------|
| GOVERNMENT<br>DESIGNATION           | MANUFACTURER'S<br>DESIGNATION OR<br>TYPE NUMBER | TEST OR<br>QUALIFICATION<br>REFERENCE | SUPPLIER'S NAME<br>(ADDRESS ON LAST PAGE) |
| M83726/30-1000P<br>through<br>5003P | TDH-8060-1000P<br>through<br>TDH-8060-5003P     | 83726-3177-11                         | Leach International                       |
| M83726/30-1000S<br>through<br>5003S | TDH-8061-1000S<br>through<br>TDH-8061-5003S     | 83726-3177-11                         | Leach International                       |
| M83726/30-1000P<br>through<br>5003P | TD230-1000P<br>through<br>TD230-5003P           | 83726-2896-10; 83726-5208-18          | Tyco Electronics/CII Relays               |
| M83726/30-1000S<br>through<br>5003S | TD230-1000S<br>through<br>TD230-5003S           | 83726-2896-10; 83726-5208-18          | Tyco Electronics/CII Relays               |
| M83726/31-1000P<br>through<br>5003P | TDH-8080-1000P<br>through<br>TDH-8080-5003P     | 83726-3177-11                         | Leach International                       |
| M83726/31-1000S<br>through<br>5003S | TDH-8081-1000S<br>through<br>TDH-8081-5003S     | 83726-3177-11                         | Leach International                       |
| M83726/31-1000P<br>through<br>5003P | TD231-1000P<br>through<br>TD231-5003P           | 83726-5207-18                         | Tyco Electronics/CII Relays (India)       |
| M83726/31-1000S<br>through<br>5003S | TD231-1000S<br>through<br>TD231-5003S           | 83726-5207-18                         | Tyco Electronics/CII Relays (India)       |

---

**Manufacturer and Supplier Location Information**

---

**Manufacturer: B.C. Systems (CAGE Code: 48313)**

Location: 200 N. Belle Meade Road, Setauket, NY 11733-3463, US

Plants:

1. Plant: Same Address as Manufacturer

**Manufacturer: DRI Relays, Inc. (CAGE Code: 99699)**

Location: 60 Commerce Drive, Hauppauge, NY 11788, US

Plants:

1. Plant: Same Address as Manufacturer

**Manufacturer: Leach International North America (CAGE Code: 58657)**

Location: North America Division, P.O. Box 5032, 6900 Orangethorpe Avenue, Buena Park, CA 90620-1351, US

Plants:

1. Plant: Same Address as Manufacturer

**Manufacturer: Tyco Electronics/CII Relays (CAGE Code: 58614)**

Location: High Performance Group-Relays, P.O. Box 520, 1396 Charlotte Highway, Fairview, NC 28730, US

Plants:

1. Plant: Same Address as Manufacturer
2. Tyco Electronics/CII Relays (India), CAGE: 1263Y, 16B Garment Complex, CSEZ, Kakkanad, Cochin, 682037, India